UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	ices and Reports on Wells	ì	
	157% N. 1784 AND ADDRESS OF THE PARTY OF THE	5.	Lease Number SF-077231
1. Type of Well GAS	PEGEIVED	6.	If Indian, All. or Tribe Name
2 7	MAR 1 5 1999 D	7.	Unit Agreement Nam
2. Name of Operator BURLINGTON RESOURCES OIL	a gas company DIST. 3		
3. Address & Phone No. of Opera		8.	Well Name & Number
PO Box 4289, Farmington, NM		9.	Shaw #1A API Well No. 30-045-21658
4. Location of Well, Footage, Sec., T, R, M 955'FNL 1190'FWL, Sec.13, T-30-N, R-9-W, NMPM		10.	Field and Pool Blanco MV/Blanco P
733 THE 1130 PME, Sec. 13, 1-3	JO N, N J W, MAPA	11.	County and State San Juan Co, NM
	DICATE NATURE OF NOTICE, REPORT,	OTHER	DATA
Type of Submission _X_ Notice of Intent	Type of Action Abandonment Change Recompletion New Co		
Subsequent Report			racturing
Sandagache Report		Shut of	_
Final Abandonment	Casing Repair Water		_
Final Abandonment	Casing Repair Water Altering Casing Conver X Other -		f
Final Abandonment 13. Describe Proposed or Comp	Casing Repair Water Altering Casing Conver X Other - leted Operations the tubing on the subject well a	sion to	o Injection
Final Abandonment 13. Describe Proposed or Comp It is intended to repair	Casing Repair Water Altering Casing Conver X Other - leted Operations the tubing on the subject well a	sion to	o Injection
Final Abandonment 13. Describe Proposed or Comp It is intended to repair	Casing Repair Water Altering Casing Conver X Other - leted Operations the tubing on the subject well a	sion to	o Injection
Final Abandonment 13. Describe Proposed or Comp It is intended to repair	Casing Repair Water Altering Casing Conver X Other - leted Operations the tubing on the subject well a	sion to	o Injection ng
Final Abandonment 13. Describe Proposed or Comp It is intended to repair	Casing Repair Water Altering Casing Conver X Other - leted Operations the tubing on the subject well a	sion to	o Injection
Final Abandonment 13. Describe Proposed or Comp It is intended to repair	Casing Repair Water Altering Casing Conver X Other - leted Operations the tubing on the subject well a	sion to	o Injection
Final Abandonment 13. Describe Proposed or Comp It is intended to repair to the attached pr	Casing Repair Water Altering Casing Conver X Other - leted Operations the tubing on the subject well a	sion to	o Injection
It is intended to repair to the attached proposed or Comp It is intended to repair to the attached proposed or Comp It is intended to repair to the attached proposed or Comp It is intended to repair to the attached proposed or Comp	Casing RepairWaterAltering CasingConverX_Other	ccording	Date 2/25/99
Final Abandonment 13. Describe Proposed or Comp It is intended to repair to the attached pr	Casing Repair Water Altering Casing Conver X Other - leted Operations the tubing on the subject well a rocedure. foregoing is true and correct. (MEL) Title Regulatory Adminis	ccording	o Injection Of the state of th

Shaw #1A

Mesaverde/Pictured Cliffs 955'FNL, 1190' FWL

Unit D, Section 13, T-30-N, R-9-W

Latitude / Longitude: 36° 48.9413' / 107° 44.1778' DPNO: 4821401 MV/4821402 PC **Tubing Repair Procedure**

- Hold safety meeting. Comply with all NMOCD, BLM and Burlington safety and environmental 1. regulations. Test rig anchors and build blow pit prior to moving in rig. Notify BROG Regulatory (Peggy Bradfield 326-9727) and the appropriate Regulatory Agency prior to pumping any cement job. If an unplanned cement job is required, approval is required before the job can be pumped. If verbal approval is obtained, document approval in DIMS/WIMS. Allow as much time as possible prior to pump time in case the Agency decides to witness the cement job.
- MOL and RU workover rig. Obtain and record all wellhead pressures. NU relief line. Blow well 2. down and kill with 2% KCL water if necessary. ND WH and NU BOP with stripping head. Test and record operation of BOP rams. Have wellhead and valves serviced as necessary. Test secondary seal and replace/install as necessary.

Mesaverde/Pictured Cliffs 2-3/8", 4.7# tubing is set at 5071'. Release donut, pick up additional joints of tubing and tag bottom. (Record depth.) PBTD should be at +/-5163'. TOOH with tubing. Visually inspect tubing for corrosion and replace any bad joints. Check tubing for scale build up and notify Operations Engineer.

- If fill is encountered, TIH with 3-7/8" bit, bit sub and watermelon mill on 2-3/8" tubing and round 4. trip to below perforations, cleaning out with air/mist. NOTE: When using air/mist, minimum mist rate is 12 bph. If scale is present, contact Operations Engineer to determine methodology for removing scale from casing and perforations.
- 5. TIH with one joint of 2-3/8" tubing with an expendable check on bottom and a seating nipple one joint off bottom then ½ of the 2-3/8" production tubing. Run a broach on sandline to insure that the tubing is clear. TIH with remaining 2-3/8" tubing and then broach this tubing. Replace any bad joints. CO to PBTD with air/mist. PU above the perforations and flow the well naturally, making short trips for clean up when necessary.
- 6. Land tubing at ±5080°. ND BOP and NU WH. Pump off expendable check. Connect to casing and circulate air to assure that expendable check has pumped off. Obtain pitot gauge up the tubing. If well will not flow up the tubing, make swab run to SN. RD and MOL. Return well to production.

Recommended: M.E. Hutter Operations Engineer

Approved:

Druce W. Doug 3.1.99
Drilling Superintendent

Operations Engineer:

Mary Ellen Lutev

Office - (599-4052) Home - (325-9387) Pager - (324-2671)

MEL/klg