UNITED STATES

DEPARTMENT		OF	TI	ΙE	INTERIOR
BUREAU (F	LA	MD.	M	NAGEMENT

Sundry No	tices and Reports on Wells		
	17 COT 21 PM 3: 39	5.	Lease Number SF-080244
Type of Well GAS	Sie Barniston L. Mill	6.	
		7.	Unit Agreement Na
. Name of Operator			
RESOURCES OF	L & GAS COMPANY		
. Address & Phone No. of Open	rator	8.	Well Name & Number Pierce #3A
PO Box 4289, Farmington, N		9.	
. Location of Well, Footage,		10.	Field and Pool
1140'FSL, 825'FEL, Sec.7, 7	C-30-N, R-9-W, NMPM	11	Blanco Mesaverde County and State
		11.	San Juan Co, NM
2. CHECK APPROPRIATE BOX TO I	INDICATE NATURE OF NOTICE.	REPORT, OTHER	DATA
Type of Submission	Type of Acti		
X Notice of Intent		Change of Pla	
	Recompletion		
Subsequent Report	Plugging Back		
Final Abandonment	Casing Repair Altering Casing		
	X Other - Tubing repa		
2 Parada Proposad on Con	1		
3. Describe Proposed or Com	mpleted Operations		
_	the tubing in the subject	DEG	
It is intended to repair	the tubing in the subject	NEC OCT	國心 (基) 3 0 1997
It is intended to repair	the tubing in the subject	DEC OIL CO	
It is intended to repair attached procedu	the tubing in the subject	() 100 110 110 110 110	3 0 1297 2 0 127 2 1 DIVA
It is intended to repair attached procedu	the tubing in the subject	DEC OIL GO	CALL OF EACH OF THE STATE OF TH

Pierce #3A

Mesaverde 1140 FSL, 825 FEL

Unit P, Section 7, T-30-N, R-09-W

Latitude / Longitude: 36° 49.32' / 107° 48.90'

DPNO: 58911 Tubing Repair Procedure

- Hold safety meeting. Comply with all NMOCD, BLM and Burlington safety and environmental regulations. Test rig anchors and build blow pit prior to moving in rig. Notify BROG Regulatory (Peggy Bradfield 326-9727) and the appropriate Regulatory Agency prior to pumping any cement job. If an unplanned cement job is required, approval is required before the job can be pumped. If verbal approval is obtained, document approval in DIMS/WIMS. Allow as much time as possible prior to pump time in case the Agency decides to witness the cement job.
- 2. MOL and RU workover rig. Obtain and record all wellhead pressures. NU relief line. Blow well down and kill with 2% KCL water if necessary. NU BOP with stripping head. Test and record operation of BOP rams. Have wellhead and valves serviced as necessary. Test secondary seal and replace/install as necessary.
- 3. Release donut, pick up additional joints of tubing and tag bottom. (Record depth.) TOOH with tubing. Visually inspect tubing for corrosion and replace any bad joints. Check tubing for scale build up and notify Operations Engineer.
- 4. PU casing scraper and bit. TIH and CO to PBTD. PU above perforations and flow the well naturally, making short trips for clean up when necessary. TOOH with bit and scraper.
- 5. TIH with 2-3/8" tubing with an expendable check on bottom and a seating nipple one joint off bottom. Rabbit all tubing. CO to PBTD.
- 6. Land tubing near bottom perforation. ND BOP and NU wellhead. Pump off expendable check. Obtain final pitot gauge up the tubing. If well will not flow on it's own, make swab run to seating nipple. If a swab run is not necessary, run a broach on slickline to ensure that the tubing is clear. RD and MOL. Return well to production.

Recommended: 1994 - Later	Approved:	
Operations Engineer		Drilling Superintendent
Mary Ellen Lutey		
Office - (599-4052)		
Home - (325-9387)		
Pager - (324-2671)		

Well Data Sheet

Footage: 1140' FSL & 825' FEL	Unit: P Sect: 07 Town:	030N Range: 009W		100 Formation: MY
Dual: NO Commingled: NO		D	County: San Juan	State: New Mexico
	· ·	Last Chg Date:	Plunger Lift: No	BH Priority: BH Test Date: 3/1.
CASING:				BH Test Date: 3/1.
	Suator			
Hole Size: 33/2	Surface Interm	Congain	<u>19 /-Liner</u>	Longstring Liner
	<u></u>	6/41		
Casing Set w : $\frac{11/8 - 5}{215}$	6#, (-55 7", ID=		#. K-55	
(3532'	<u>54</u> 35'P	KI. 2) 534-12KN	ote: Openial
	100 5x 05/ 00 5x 05/		150 PD= C.	com 5347'- 54
<u> </u>		250(12 · w/29 00	1.0.6326-0	
(= 1 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3	+ 1/2 c=7/se	per c. 6.25 PFS	zilsoni-e	
,	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	5x -1/ = 14 pc-	zilo flaka	
	70	T 12 6-15 (113)	د د)	
TOC: <00		376 (2)		
	E By: CIRC, TOC: 2050'B	מסבט : TOC: מסבט '	By: 7.5 TOC	: By:
ELL HISTORY:				
Orig. Owner: EPNG			Formation Top	<u> 18</u>
GLE: <u>645</u> 9'	Spud Date: 04:03:79	SJ	СН	4700
KB:	First Del. Date: 04 01.79	NA	MF	4920
TD: 545 = 1	MCFD:	OA 1365	PL	5 % <u>4</u>
PBD:	BOPD:	KT	GP	
Constant T	BWPD:	FT	GH	
51-HC 7030 CM	ME: Brighton 15	000:01. PC 5170	GRR	S
77 000 male Mich	HoDE 40 Kally Fac	d: LW 2230	DK	
N/C/ H-10 5 97 CO	HO STAC: 97,000	ON CK		
540 001 Alick F	I D SA UVA	h		
2L: -07N: 10 00) (4)	al act Condensate			
		1400.31		
	51.312 601.11	- 54.000 cg	Il all ma	onantos 94 s
	31.30 cal H20.	.frac: 84,000 q	el gel-ord	ensate 984,0
	SIOSO CAD HOO.	-fue: 84,000 q	ul que ord	engate = 84,0
RRENT DATA:	51.30 Cal H20.	Tubing:	al allema	engates £4,0
FRENT DATA: Perfs: Cris MF 14009	51, 4906, 14, 50, 50		2331 6 72	in the sign
RRENT DATA:	51,30 Cpl) H20.		23 12 72 MILTONE 50 10 10 10 10 10 10 10 10 10 10 10 10 10	in the sign
HPO (40, 20). JELLAND. PRENT DATA: Perfs: C F. F. MF 40, 29 23, 65, 75, 20 (15 PZ)	17, 4906, 14, 50, 50, 50, 50, 50, 50, 50, 50, 50, 50	Tubing:	73 3 2 7 = MAI + 0 - 51 A	in the sign
HPO (40, 20). JELLAND. PRENT DATA: Perfs: C F. F. MF 40, 29 23, 65, 75, 20 (15 PZ)	, 17, 4906, 14, 50, 50	Tubing:	2331 6 72	in the sign
# 80/40 pd. jelust. PRRENT DATA: Perfs: C fis. MF 40.09 23, 65 75 93, 506 66, 73, 60 (1587) 21: 5409 - 5429 (17, 4906, 14, 50, 50, 50, 50, 50, 50, 50, 50, 50, 50	Tubing:	73 3 2 7 = MAI + 0 - 51 A	in the sign
HPO (40, 20). JELLAND. PRENT DATA: Perfs: C F. F. MF 40, 29 23, 65, 75, 20 (15 PZ)	17, 4906, 14, 50, 50, 50, 50, 50, 50, 50, 50, 50, 50	Tubing:	73 3 2 7 = MAI + 0 - 51 A	in the sign
# 80/40 pd. jelust. PRRENT DATA: Perfs: C fis. MF 40.09 23, 65 75 93, 506 66, 73, 60 (1587) 21: 5409 - 5429 (: 51.30 Cpl) H20. , 17, 4906, 14, 55, 50 5. 5146 70, 5202, 6	Tubing:	73/3 / 7 = 10 M/1 - 0 - = 10 Par = 3 - 40 hold = 3/3 - 37/	or draw
# 10/40 pd. jelust. PRRENT DATA: Perfs: C for MF 4009 23, 65 75 93, EDIG 26, 78, 20 (15PZ) 21: 5409 - 5429 (LLING HISTORY/REMARKS:	17, 4906, 14, 50, 50, 50, 50, 50, 50, 50, 50, 50, 50	Tubing:	73/3 / 7 = 10 M/1 - 0 - = 10 Par = 3 - 40 hold = 3/3 - 37/	in the sign
# 10 40 20. 1 LING HISTORY/REMARKS: Last Rig Date:	: 51.30 Cpl) H20. , 17, 4906, 14, 55, 50 5. 5146 70, 5202, 6	Tubing:	73/3 / 7 = 10 M/1 - 0 - = 10 Par = 3 - 40 hold = 3/3 - 37/	or draw
# 10 40 20. 1 LING HISTORY/REMARKS: Last Rig Date:	: 51.30 Cpl) H20. , 17, 4906, 14, 55, 50 5. 5146 70, 5202, 6	Tubing:	73/3 / 7 = 10 M/1 - 0 - = 10 Par = 3 - 40 hold = 3/3 - 37/	or draw
# 10 40 20. 1 LING HISTORY/REMARKS: Last Rig Date:	: 51.30 Cpl) H20. , 17, 4906, 14, 55, 50 5. 5146 70, 5202, 6	Tubing:	73/3 / 7 = 10 M/1 - 0 - = 10 Par = 3 - 40 hold = 3/3 - 37/	or draw
# 10 40 20. 1 LING HISTORY/REMARKS: Last Rig Date:	: 51.30 Cpl) H20. , 17, 4906, 14, 55, 50 5. 5146 70, 5202, 6	Tubing:	73/3 / 7 = 10 M/1 - 0 - = 10 Par = 3 - 40 hold = 3/3 - 37/	or draw
Perfs: Cr. S. MF 4009 23. 662 75 93. 506 26. 72. 60 (15PZ) CLING HISTORY/REMARKS: Last Rig Date: cmarks: 4	17, 4906, 14, 50, 50, 50, 50, 50, 50, 50, 50, 50, 50	Tubing:	73/3 / 7 = 10 M/1 - 0 - = 10 Par = 3 - 40 hold = 3/3 - 37/	or draw
Prod Ops Project Type:	17, 4906, 14 52 50 5146 70, 5202 6 2 SPF) Last Rig AFE Type: (orkover Required: >6 Yes	Tubing: 3 24 42, 48 Packer: Function: Rad String:	23 a 2 a a a a a a a a a a a a a a a a a	Or and established and a second a second and
ERRENT DATA: Perfs: Cr. 5, MF 40 09 23, 105, 75, 20 (15PZ) 24, 209 - 5429 (LLING HISTORY/REMARKS: Last Rig Date: cmarks: 4 134 1	Last Rig AFE Type: Corkover Required: 20 Yes Luck Libra S Area Team Project 11 Light of Area Team Project	Tubing: 3 24 42, 48 Packer: Partic: Parti: Partic: Partic: Partic: Partic: Partic: Partic: Partic:	23 2 2 3 2 3 2 8 8 8 8 8 8 8 8 8 8 8 8 8	Or aim es la ita from AFE Type:
Prod Ops Project Type:	17, 4906, 14 52 50 5146 70, 5202 6 2 SPF) Last Rig AFE Type: (orkover Required: >6 Yes	Tubing: 3 24 42, 48 Packer: Partic: Parti: Partic: Partic: Partic: Partic: Partic: Partic: Partic:	23 a 2 a a a a a a a a a a a a a a a a a	DAFE Type:

AX 1996 plunder installed + removed,