## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-013
Expires; March 31, 1993

5. Lesse Designation and Serial No.

CHAIDDY	NOTICES	AND	REPORTS	ON	WELL	C
CHMINIA	$M \rightarrow M \rightarrow M$	$\Delta MIJ$	KEPURIS	V JIW	VVELL	

SUNDRY NOTICES AND RE		arvoir	SF-080132	
Do not use this form for proposals to drill or to dee Use "APPLICATION FOR PERMIT		6. If Indian, Allott	ee or Tribe Name	
		7. If Unit or CA,	Agreement Designation	
1. Type of Well		8, Well Name and	1 No.	
Oil Gas Other  2. Name of Operator	Attention:		e /S/ #7A	
Amoco Production Company	Kelly Stearns	9. API Well No.		
3. Address and Telephone No.		3004522122		
P.O. Box 800, Denver, Colorado 80201	(303) 830-44	TO. Fleid Sid Foo	10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		11. County or Pa	asin Fruitland Coal	
1750' FNL 1590'FWL Sec. 2	3 T 30N R 9W		Juan New Mexico	
12. CHECK APPROPRIATE BOX(s) TO	INDICATE NATURE OF	NOTICE, REPORT, OR	OTHER DATA	
TYPE OF SUBMISSION		E OF ACTION		
Notice of Intent  Subsequent Report  Final Abandonment Notice	Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other	Change of Plans New Construction Non-Routine Fract Water Shut-Off Conversion to Inje Dispose Water (Note: Report results of multiple Recompletion Report and Log for	curing action a completion on Well Completion or	
14. I hereby certify that the foregoing is true and correct		Business Analyst	12-01-1993	
Signed Killy Attarns	Title		Dete	
(This space for Federal or State of lice use)	<b>-</b>	AUGE!	PTED FOR RECORD	
Approved by Conditions of approval, if any:	Title		DEC 1 5 1993	
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and	willfully to make to any department or agen	cy of the United States any false, ARM	INCHORMAN HIGHOPITCE	

FLORANCE GAS COM /S/ #7A BASIN FRUITLAND COAL CONVERSION TO INJECTION WELL

MIRUSU 10/15/93. NDWH & NUBOPS. TOH AND LAY DWN 81 JNTS. CHG EQUIP TO PULL 2 3/8" TBG. UNSEAT SEAL ASSEMBLY & LET WELL BLW DWN. START OUT OF HOLE. WELL UNLOADING. PMP 15 BBLS DWN TBG. CONTINUE OUT OF HOLE. PMP ANOTHER 15 BBLS. LAY DWN 7 BLAST JNTS. PMP 15 BBLS. PULL TOTAL OF 160 JNTS 2 3/8" TBG, 3 SUBS & 1/2 MULESHOE. TIH 2 3/8" TBG & TAG FILL 5203'. RIG IN HES N2 UNITS. CLEAN OUT TO 5250' USING N2 & FOAM. COULD NOT WORK IT BELOW 5250'. BLW WELL CLEAN. RIG DWN N2. TIH & LAY DWN 2 3/8" TBG.TIH & SET PLUT AT 1230'. NDBOPS & CHG OUT WELLHEAD. RELEASE PLUG. TOH WITH RET PLUG. PICK UP & RUN 7" RET PLUG & SET AT 2800'. TOH. RDMOSU 10/19/93.

MIRUSU 11/08/93. BLOW DOWN. KILL WELL WITH 80 BBLS OF KCL WATER. UNSEAT PK AT 2530' & 2650'..TOH W 7" PK'S & 2.375" TBG TO 500'. TOH W PK'S FROM 500'. RACK 5100' OF TBG. TIH W/ 7"BP & 2.375" BP. PU & TALLY TBG. SET BP AT 2402'. TEST CSG TO 1750 PSI FOR 30 MIN. OK. NDBOP-NUWH. CHANGE OUT WH. INSTALL DUAL TBG WELLHEAD. TEST WH TO 1500 PSI. OK. NUBOP STACK ON DUAL TBG WH. TEST TO 1500 PSI. OK. REC BP SET AT 2402'. TOH. TIH W/ 2.376" TBG. REC BP SET AT 2800'. TOH W/ 7" BP. CHANGE OUT TBG COLLARS TO SLIM HOLE COLLARS. RACK 2400' OF TBG. TIH W/ MV TBG TO 2310'. FINISH TIH W/ MV TBG & LAND AT 5165'. SEAL ASSEMBLY AT 2878' W/ 13,000 ON PK. LAND BAKER PK AT 2361'. CHANGE OUT PIPE RAMS. TIH W/ FRUITLAND TBG & LAND IN PK AT 2361'. INFLATE PK W/ HOWCO PUMP TO 1800 PSI. NUBOP-NUWH. TEST WH PACKING TO 3000 PSI FOR 30 MINUTES. OK. TEST BACK SIDE TO 1500 PSI FOR 30 MINUTES. OK. RET FRUITLAND TBG PLUG SET AT 2361'. PUMP ON MV TBG PLUG SET AT 5165'. PRESSURE UP TO 3000 PSI COULDN'T PUMP OUT PLUG. RUN SAND LINE W/ SINKER BARS SPUD ON PLUG AT 5165'. COULDN'T REMOVE PLUG. TIH W/SD LINE. TAG AT 5164'. SPUD ON TBG PLUG SET AT 5165' FOR 3 HOURS. COULDN'T REMOVE PLUG. RU TIH W/ HOWCO WL JET CUTTER TAG AT 5164'. RDMOSU 11/15/93.