State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division

	Oil Conservation	DIVISION		
	Sundry Notices and Re	eports on Wells		
1. Type of Well		API 5.	# (assigned by OCD) 30-045-22375 Lease Number	
GAS		6.	State Oil&Gas Lease #	
2. Name of Operator		7.		
RESOURCES OIL &	GAS COMPANY	8.	Turner B Com A Well No.	
3. Address & Phone No. of Operato	or		2A	
PO Box 4289, Farmington, NM	87499 (505) 326-9700	9.	Pool Name or Wildcat Blanco Mesaverde	
4. Location of Well, Footage, Se 1000'FSL, 1820'FEL, Sec.2, T-			Elevation:	
Type of Submission	Type of Ac	tion		
X Notice of Intent	Recompletion	Change of Plane New Construct	tion	
Subsequent Report	Plugging Back Casing Repair	Non-Routine : Water Shut o		
Final Abandonment	Altering Casing _ _X_ Other - Tubing re		o Injection	
13. Describe Proposed or Compl	eted Operations			
It is intended to repair t attached procedure.		ct well according	ng to the	
		ലെ	GIVIED.	
			T 2 2 1997	
		<u> </u>	ON. DIV. Ist. 3	
		Barry California a architect.	•••	
SIGNATURE Seggy Drakhu	od (MEL5) Regulatory	Administrator_	_October 20, 1997	

(This space for State Use)

Approved by shring Robinson Title DEPUTY OIL & GAS INSPECTOR, DIST. #3 Date OCT 2 2 1997

Turner B Com A #2A

Mesaverde 1000 FSL, 1820 FEL

Unit O, Section 2, T-30-N, R-09-W

Latitude / Longitude: 36° 50.13' / 107° 44.80

DPNO: 76155
Tubing Repair Procedure

- 1. Hold safety meeting. Comply with all NMOCD, BLM and Burlington safety and environmental regulations. Test rig anchors and build blow pit prior to moving in rig. Notify BROG Regulatory (Peggy Bradfield 326-9727) and the appropriate Regulatory Agency prior to pumping any cement job. If an unplanned cement job is required, approval is required before the job can be pumped. If verbal approval is obtained, document approval in DIMS/WIMS. Allow as much time as possible prior to pump time in case the Agency decides to witness the cement job.
- 2. MOL and RU workover rig. Obtain and record all wellhead pressures. NU relief line. Blow well down and kill with 2% KCL water if necessary. NU BOP with stripping head. Test and record operation of BOP rams. Have wellhead and valves serviced as necessary. Test secondary seal and replace/install as necessary.
- 3. Release donut, pick up additional joints of tubing and tag bottom. (Record depth.) TOOH with tubing. Visually inspect tubing for corrosion and replace any bad joints. Check tubing for scale build up and notify Operations Engineer.
- 4. PU casing scraper and bit. TIH and CO to PBTD. PU above perforations and flow the well naturally, making short trips for clean up when necessary. TOOH with bit and scraper.
- 5. TIH with 2-3/8" tubing with an expendable check on bottom and a seating nipple one joint off bottom. Rabbit all tubing. CO to PBTD.
- 6. Land tubing near bottom perforation. ND BOP and NU wellhead. Pump off expendable check. Obtain final pitot gauge up the tubing. If well will not flow on it's own, make swab run to seating nipple. If a swab run is not necessary, run a broach on slickline to ensure that the tubing is clear. RD and MOL. Return well to production.

Recommended: M.E. Shutting	Approved:	
Operations Engineer		Drilling Superintendent

Mary Ellen Lutey Office - (599-4052) Home - (325-9387) Pager - (324-2671)

Burlington Resources Well Data Sheet

