Submit 3 Copies To Appropriate District Office	State of New Mexico				Form C-103			
District I	Energy, Minerals and Natural Resources			Revised March 25, 1999				
1625 N. rench Dr., Hobbs, NM 88240				WELL	API NO.	- = 7	1.11	
District II 811 South First, Artesia, NM 88210	OIL CONSER	VATION	DIVISION			45-2270F ZZ	046	
District III	1220 Sout	th St. Fall	ich Dro	1	icate Type of			
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa I	Fe, xin 8	7505		STATE	FEE 🔀		
1220 S. St. Francis Dr., Santa Fe, NM		50	.//	6. Sta	ate Oil & Ga	is Lease No.		
87505 SUNDRY NOT	ΓICES AND REPORTS (STAVEL B	CAN SCO	7 1 00	Name 1	TI-14 A DI		
(DO NOT USE THIS FORM FOR PROP	OSALS TO DRILL OR TO DE	EREN OR GE	UG BACK TO A	/. Lea	se Name or	Unit Agreement Na	me:	
DIFFERENT RESERVOIR. USE "APPL PROPOSALS.)	ICATION FOR PERMIT" (FO	RM (C-101) F	OR SUCH		Heath	Gas Com A		
1. Type of Well:								
Oil Well Gas Well	Other							
2. Name of Operator		7,	42.0	8. Wel	l No.		$\neg \neg$	
Amoco Production Company	Attn: Mo	ary Corley				1A		
3. Address of Operator					l name or W			
P.O. Box 3092 Houston, TX 4. Well Location	77253	-· <u>-</u> -	·	Blanco	Mesaverde	:		
4. Well Location								
Unit Letter O 1015 feet from the South line and 1850 feet from the East line								
Section 32	Township 30N	Range	09W 1	NMPM	San Juan	County	1	
	10. Elevation (Show				San Stan	County		
5707'								
11. Check	Appropriate Box to In	ndicate Na	ature of Notice, I	Report	or Other D	ata		
	NTENTION TO:				ENT REP	ORT OF:		
PERFORM REMEDIAL WORK	PLUG AND ABANDO	N \square	REMEDIAL WORI	K		ALTERING CASING	3 🗆	
TEMPORARILY ABANDON	COMMENC			LLING O		PLUG AND		
PULL OR ALTER CASING	MULTIPLE CASING TEST AN COMPLETION CEMENT JOB			1D		ABANDONMENT		
		L J						
OTHER: Pay Add		×	OTHER:				<u></u>	
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.								
Amoco Production Company request permission to add the Lewis Shale pay in the subject well as per the attached procedure.								
	•		, ,			, , , , , , , , , , , , , , , , , , ,	•	
I haveby contifue that the information	an about to true and assure	1.4. 4. 4 1		11	11 C			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.								
SIGNATURE ///avy	forley .	TITLE <u>S</u>	. Regulatory Anal	yst	DATE _	12/27/2001		
Type or print name Mary/cor	ley /		<u></u> .	Teleph	one No. 28	31-366-4491		
(This space for State use)	U		MALA UNG ALUM	PRIME	NAT 100	1441 0 -		
APPPROVED BY	y steven n _. Hayde	e Titic	TOTY ONL & SAS INS	SECION,	-	JAN -2 20	102	
Conditions of approval, if any:		_TITLE		-		_DATE		


Heath GC A 1A Well Work Procedure

API #: 30-045-22646 Sec 32, T30N, R9W

- 1. Check anchors. MIRU workover rig.
- 2. Kill with 2% KCL water if necessary. Nipple down WH. NU BOPs and diversion spool with 3" outlets and 3" pipe to the blow tank. Pressure test BOPs to 500 psi.
- 3. Tag for fill and tally OH with 2-3/8" production tubing. Visually inspect tbg while POOH.
- 4. TIH with bit and scraper for 4-1/2" casing to 3850'.
- 5. TIH with tubing-set CIBP. Set CIBP at 3800'. Load hole with 2% KCL.
- 6. Pressure test casing to 2500 psi
- 7. Swab 2000' of fluid column in casing with the sandline.
- 8. RIH with 3-1/8" casing guns 1 SPF 180 deg phasing with Schlumberger's Prospector, select-fire charge. Perforate the Lewis formation (correlate to GR log).
- 9. Breakdown the perforations with acetic acid.
- 10. RU frac equipment and install wellhead isolation tool. Use 2% KCL-N2 foam in fracture stimulation.
- 11. Frac the Lewis according to pump schedule.
- 12. Flowback frac fluid.
- 13. TIH with tubing and bit. Cleanout fill to top of drill bridge plug set at 3800'.
- 14. RU WL and lubricator. RIH with RA tracer log.
- 15. TIH with tubing and bit and drill out bridge plug at 3800'.
- 16. Land 2-3/8" production tubing at 4642'.
- 17. Swab water from the tubing with the sandline.
- 18. ND BOP's. NU WH. Test well for air. Move rig out location.

HEATH GAS COM 'A' #1A

Sec 32, T30N, R9W API #: 30-045-22646



updated: 10/22/01 az