UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED

| | BLM / |
|---|--|
| Sundry Not | ces and Reports on Wells PM 12: 53 |
| 1. Type of Well GAS | 5. Lease Number 070 FARMINGION, NM SF-077282 6. If Indian, All. or Tribe Name |
| 2. Name of Operator | 7. Unit Agreement Nam |
| BURLINGTON RESOURCES | GAS COMPANY |
| 3. Address & Phone No. of Operator PO Box 4289, Farmington, NM | The state of the s |
| 4. Location of Well, Footage, Se 1170'FNL 1770'FWL, Sec.26, T- | ., T, R, M 10. Field and Pool |
| | CATE NATURE OF NOTICE, REPORT, OTHER DATA |
| Type of Submission _X_ Notice of Intent | Type of Action Abandonment Change of Plans Recompletion New Great |
| Subsequent Report | Recompletion New Construction Plugging Back Non-Routine Fracturing Casing Repair Water Shut off |
| Final Abandonment | Cusing Kepair water shut off Altering Casing Conversion to Injection _X_ Other - tubing repair |
| 13. Describe Proposed or Compl | ted Operations |
| It is intended to repair t attached procedure | e tubing on the subject well according to the |
| signed Lagry Shalheed | oregoing is true and correct. KLM5) Title Regulatory Administrator_Date 11/12/98 TLW |
| (This space for Federal or State APPROVED BY /S/ Duane W. Spence CONDITION OF APPROVAL, if any: | Title Date DEC - 1998 |

Grenier A #1A

Pictured Cliffs/Mesa Verde Dual Well 1170' FNL & 1170' FWL

Unit C, Section 26, T30N, R10W Latitude / Longitude: 36° 47.2265'/ 107° 51.3766'

DPNO: 25649 (PC) Tubing Repair Procedure

Project Summary: The Grenier A #1A was drilled in 1979 as a Pictured Cliffs/Mesa Verde dual well. Neither string of tubing has been pulled since originally installed. In 1979 the PC initially produced at 5 11 MCFD for about 4 menths and then dropped to under 20 MCFD. Sand fill is strongly suspected as the culprit. In October 1998, we ran slickline tools on the PC side to determine if we had sand fill. We stuck the tools (1" jars and sinker bars) approximately at the SN and had to pull out of the rope socket. These tools are still in the PC tubing. We propose to pull the Pictured Cliffs tubing, check for fill and clean out if necessary. We will replace any worn or scaled tubing, and add a new flow controller. We will attempt to pull the MV tubing and clean out to bottom while we are rigged up on this well, but we will not fish the seal assembly if it is stuck in the PBR (the MV does not suffer from any obvious problems).

- Hold safety meeting. Comply with all NMOCD, BLM and Burlington safety and environmental regulations. Test rig anchors and build blow pit prior to moving in rig. Notify BROG Regulatory (Peggy Bradfield 326-9727) and the appropriate Regulatory Agency prior to pumping any cement job. If an unplanned cement job is required, approval is required before the job can be pumped. If verbal approval is obtained, document approval in DIMS/WIMS. Allow as much time as possible prior to pump time in case the Agency decides to witness the cement job.
- 2. The Mesa Verde tubing is 2-3/8" 4.7# EUE set at 5187' with no SN. There is a plunger and a tubing stop/spring currently in the 2-3/8" tubing. Remove this equipment and set a CW plug in the 2-3/8" tubing before the workover. After the workover, pull CW plug and re-install the plunger equipment.
- MOL and RU workover rig. Obtain and record all wellhead pressures. NU relief line. Blow well down and kill with 2% KCL water if necessary. NU BOP with stripping head. Test and record operation of BOP rams. Have wellhead and valves serviced as necessary. Test secondary seal and replace/install as necessary. Note: There are slickline tools in the well (1" jars, four 1" sinker bars, and a rope socket) near the bottom of the PicturedCliffs tubing.
- 4. The Pictured Cliff tubing is 1-1/4", 2.33, V-55, IJ set at 2763' with a "gas anchor" at the bottom of tubing. It is unknown whether this "gas anchor" is orange peeled, bull plugged, or open ended. Release donut and TOH. Visually inspect tubing for corrosion and replace any bad joints. Check tubing for scale build up and notify Operations Engineer. Sand fill is suspected. If the 1-1/4" tubing is stuck in sand, then contact Operations Engineer and Drilling Superintendent for a fishing plan.
- Attempt to pull the 2-3/8" tubing out of the PBR (straight pick-up). If the 2-3/8" tubing will come free, then POOH with 2-3/8" tubing and proceed with step #6 (MV clean-out). If the 2-3/8" tubing will not come free, then TIH with open ended 1-1/4" IJ tubing and clean out to the top of the TIW liner hanger at +/- 2874' with air/mist. Pull up above PC perfs and flow well naturally making clean-up runs until sand production stops. POOH with 1-1/4" tubing and again try to pull the 2-3/8" tubing. If the 2-3/8" tubing is still stuck in the PBR, then proceed to step #7 (do not cut and fish the 2-3/8" tubing). NOTE: When using air/mist, minimum mist rate is 12 bph.

- 6. If the 2-3/8" tubing was successfully pulled: RIH with 3-728" bit on 2-3/8" tubing and clean out to below Mesa Verde perforations (bottom perf at 5196') with air/mist. POOH with 2-3/8" tubing. Re-dress seal assembly and run 2-3/8" tubing back in the hole with the original configuration (include expendable check). Broach 2-3/8" tubing going in hole.
- 7. RIH with 1 joint 1-1/4" IJ tubing, SN, and 1-1/4" IJ production tubing. Run a broach on sandline to insure that the tubing is clear. Kill well if necessary and land tubing at approximately 2790. ND BOP and NU WH. Connect to casing and circulate air to assure that well is unloaded. RD and MOL. Return well to production.

Recommended:

TImalaff 10/29/18 Approved:

Drilling Superintendent

Kevin Midkiff Office - 599-9807 Pager - 564-1653

KLM/jms