Form 3160-5 (December 1989)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED Budget Bureau No. 1004-0135

Expir	es:	Septer	mber 30	J, 199	U
 					_

RUREAU OF LAN	ID MANAGEMENT	2 Parties of the second of the		
	VANA COM	Lease Designation and Serial No.		
SUNDRY NOTICES AN	D REPORTS ON WELLS r to deepen or reentry to a different reservoir.	M 013686 6 If Indian, Allottee or Tribe Name		
Use "APPLICATION FOR I	PERMIT— 700 such proposals OIL OON DIV			
SUBMIT IN	TRIPLICATE	7. If Unit or CA, Agreement Designation		
1. Type of Well	0829	8. Well Name and No.		
OIL GAS WELL OTHE	R	Pritchard A 10		
2. Name of Operator		9. API Well No.		
Amoco Production Company	Mary Corley	30-045-27016		
3. Address and Telephone No.		10. Field and Pool, or Exploratory Area		
P.O. Box 3092 Houston, TX 772533	(281) 366-4491	Basin Fruitland Coal Gas		
4. Location of Well (Footage, Sec., T., R., M., or Survey I	Description)	11. County or Parish, State		
1730' FNL & 1800' FEL Sec. 1 T	30N R09W Unit G	San Juan New Mexico		
12. CHECK APPROPRIATE BOX(s)	TO INDICATE NATURE OF NOTICE, REPO	ORT, OR OTHER DATA		
TYPE OF SUBMISSION	TYPE OF ACT			
Notice of Intent	Abandonment	Change of Plans		
Subsequent Report	Recompletion	New Construction Non-Routine Fracturing		
-	☐ Plugging Back ☐ Casing Repair	Water Shut-Off		
Final Abandonment Notice	Altering Casing	Conversion to Injection		
	Other Recover Fish, C/O, R			
	(Note: Report results of multiple Recompletion Report and Log for the Recompletion Report results are the Recompletion Report results of the Report results	e completion on Well Completion or		
13. Describe Proposed or Completed Operations. (Clear	ly state all pertinent details, and give pertinent dates, include e locations and measured and true vertical depths for all man	ing estimated date of starting any proposed		
work. If wen is uncertonally diffice, give outstand				
Amaga Braduction Company request	permission to Recover Fish, C/O and Run &	Perforate Liner in the subject well		
as per the attached procedure:	permission to receive their, ever and the	·		
•				
÷				
•				
4				
14. I hereby certiff that the foregoing is true and correct	•			
14. Thereby certify that the foregoing is that and correct	Title Sr. Business Analyst	Date 05/10/00		
Signed friang week	Title Of Dusiness Analyst	Date		
(This space for Federal of State office use)		Date 5/17/00		
Approved by	Title	Date _ 3/ / 98		
Conditions of approval, if any:				

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

SJOET Well Work Procedure

Pritchard A 10

Version:

#1

Date:

May 10, 2000

Budget:

Well Repair

Work Type:

Recover fish, C/O, run and perf liner

Objectives:

- 1. Recover fish
- 2. Clean out fill, stabilize hole, run and perf liner
- 3. Return well to production
- 1. MIRUSU--AWS 395; equipped for day cavitation operations
- 2. ND tree, rig up BOP's; complete with venturies on blooie lines w/man. valves.
- 3. TOH w/2 3/8" tubing
- 4. Pick up washover shoe, overshot, bumper sub, accelerator, drill collars, and drill pipe, attempt to recover fish at 2840'; fish consists of 1 1/2 jts 2 7/8 CS Hydrill TBG, bit sub/float, and 4 3/4" bit. Note: no more than three days will be utilized at recovering fish. RIH w/ 4 3/4" bit and clean out fill from 2,865' to total depth (3129') using air and foam-use produced water w/a shale stabilizer or 2% KCl if needed, stabilize hole as quickly as possible to allow running liner (after reaching TD, trip out to casing shoe and wait for 4-6 hours and check to determine amount of fill and how difficult it is to clean up.
- 5. Run a blank 4.00" (11.34#) flush joint liner from TD back to approx. 2,800'. Install a washover or Texas shoe with "cut-right" on bottom with a retrievable float immediately above the shoe and a Baker Model SLR-P Liner Hanger Packer. Strip in hole and drill to bottom with power swivel (and treated water) if necessary. Hang liner, lay down drill pipe
- 6. RU HES, run GR-CCL to identify correct coal seam depths; TIH and perforate liner as follows:

COAL ZONES	•	PERFORATIO	<u>NS</u>	
Ignacio	2,946 to 2,952'	2,946 to 2,969'	4 jspf	92 holes
· ·	2,959 to 2,969'			
Cottonwood	3,012 to 3,017'	3,012 to 3,059'	4 jspf	188 holes
	3,021 to 3,026'			
Cahn	3,032 to 3,059'	3,107 to 3,126'	4 jspf	76 holes
	3,107 to 3,126'			
		Total		356 holes

RD HES.

- 5. RIH w/2 3/8"TBG as follows:
 - 1) mule shoe
 - 2) STD SN (1.460" ID)
 - 3) Approximately 12 Jts 2 1/16" IJ TBG (372' to get above liner top)
 - 4) 2 1/16" IJ TBG x 2 3/8" EUE TBG x-over
 - 4) Balance of 2 3/8" TBG (All TBG: 6.4# J55 FBN)

Land bottom of TBG at approximately 3105-10'. RDMOSU. Turn well over to production. Note: bring well on slowly, well may need swabbing in order to RTP.

Dependent on speed of hole stabilization, I estimate this procedure to require approximately 7-9 days and to cost approximately \$150,000 (see attached AFE form).

If problems are encountered, please contact:

Mike Kutas

(W) (303) 830-5159 (H) (303)840-3700 (P) (303)553-6334