Submit 3 Copies to Appropriate District Office

1. Type of Well: WELL

2. Name of Operator

3. Address of Operator

PERFORM REMEDIAL WORK

TEMPORARILY ABANDON

PULL OR ALTER CASING

4. Well Location

11.

OTHER:

State of New Mexico Energy, Minerals and Natural Resources Department

Farm C 103

OIL CONSERVATION DIVISION

Submit 3 Copies to Appropriate District Office		Energy, Minerals and Natural Resources Department				Revised 1-1-89		
DISTRICT I P.O. Box 1980, Hobbs, NM 88240		OIL CONSERVATION DIVISION P.O. Box 2088			N	WELL API NO. 30-045-27223		
DISTRICT II P.O. Drawer DD , A r	tesis, NM 88210	Santa Fe, New Mexico 87504-2088				5. Indicate Type of Lease STATE XX FEE		
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410						6. State Oil & Gas Lease No. E-178-1		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)						7. Lease Name or Unit Agreement Name Northeast Blanco Unit		
. Type of Well:	GAS WELL X	отн	腔					
Name of Operator Blackwood & Nichols Co., Ltd.						8. Well No. 448		
		o, CO 81302-12	237			9. Pool name or Wildcat Basin Fruitland Coal		
. Well Location Unit Letter	G : 15	15' Feet From The No	rth	Line and	1340	Feet From The East Line		
Section	32 ////////////////////////////////////	Township 31N		nge ^{7W} DF, RKB, RT, GR, e	tc.)	NMPM San Juan County		
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data								
NOTICE OF INTENTION TO: SUB					SEQUENT REPORT OF:			
ERFORM REMED	IAL WORK	EGENAL		REMEDIAL WOR	RK	ALTERING CASING		
EMPORARILY AB	ANDON E)	DECZ 0 1989		COMMENCE DE	RILLING	OPNS. PLUG AND ABANDONMENT		
ULL OR ALTER C	ASING	L CON. DIV.		CASING TEST AND CEMENT JOB				
THER:		DIST. 3		OTHER: Cor	mplet	ion X		
12. Describe Propose work) SEE RUL		ntions (Clearly state all per	tinent details, ar	nd give pertinent date	es, includ	ling estimated date of starting any proposed		
11-03-89	Rigging up	equipment for c	completion	n operations	s.			
11-04-89	Test blind rams and 7" casing to $2000\#$ - test OK. Pick up $6-1/4$ " bit. Drill cement and insert float. Drill out shoe at 2961'. Drill $6-1/4$ " hole from 2961' ti 3126' with water.							
11-05-89	Drill from 3126' to TD 3266'. Circulate with water. Small amounts of fine coal. Shut in well for pressure build up: 2 hrs 1150 psig.							
11-06-89	Circulated with water and air; lost air and stuck pipe, shut off water and air, built casing pressure to 1000 psi, bled off casing pressure through choke, pulled 6 jts drill pipe and circulated clean, had large amount of coal. Circulated clean at TD, Eastimated 15 Bbls water per hour. (Continued)							
I hereby certify that the	ne information above is tru	e and complete to the best of t	my knowledge and	i belief.				

at of my knowledge and belief. I hereby certify that the information DATE 19 We 89 Operations Manager TELEPHONE NO. (303) 247-0728 William F. Clark TYPE OR PRINT NAME

(This space for State Use)

APPROVED BY

Original Signed by FRANK T. CHAVEZ

SUPERVISOR DISTRICT & .

DEC 2 0 1989

CONDITIONS OF APPROVAL, IF ANY:

C-103 NEBU #448 Continued - Page 2 of 2

- 11-07-89 Clean out from 3075' to TD, returns heavy coal. Lost returns three times during the day, stopped pumping, pulled pipe up hole until free. Circulating with all water. Hole sloughs and packs off; very sticky. Water estimated at 15 BPH.
- 11-08-89 Circulated hole at TD with water; well making strong gas and moderate coal.
- 11-09-89 Blow well at TD with air, 5 bbl. Sweeps every 30 minutes. Circulate 6 hours with 2 air compressors, 5 bbl. sweeps wvery 30 minutes, light returns, 1/4" coal sometimes and coal fines. Short trip into casing. Clean out to TD.
- 11-10-89 Rigging up to run liner.
- 11-11-89 5-1/2" liner, 2894' to 3265'.
 Ran 11 jts (370.67') 5-1/2" 23# P-110 casing, shoe at 3265' (1' off bottom), top of hanger at 2894' (67' overlap). Perfs at 2944-2986'; 3028-3070'; 3109-3168'; and 3245-3263'. Lay down 2 jts drill pipe and hang drill pipe on donut, rig down snubbing unit. POOH, laying down drill pipe. Change rams to 2-7/8". Rig up to run tubing.
- Pick up 4-1/2" mill and 2-7/8" tubing. Tag top plug at 2944'.

 Drilling plugs at 2944-2986', 3028-3070', 3109-3168', and 3245-3259'.

 TOOH, lay down mill an float. RIH with expendable plug, 1 jt tubing, F nipple (2.25" ID), and 102 jts 2-7/8" 6.4# J-55 tubing. RIH, land and tubing, nipple down BOP, nipple up master valve, drop ball. Pump off check, flowed back gas to surface.

Ran 103 jts (3152.01') 2-7/8" 6.4# J-55 EUE FBNAU tubing with expendable check set at 3166' and F nipple (2.25" ID) at 3136'

Wet Gauge: 4# on 2" line-1236 MCFD.

Rig released.