Form 3 : 60-5 (June 1990)

representations as to any matter within its jurisdiction.

UNITED STATES DEPARTMENT OF THE INTERIOR RURFALL OF LAND MANAGEMENT

RECEIVED

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

BUREA	O OF LAND MANA	GLIVILIVI	RECEIVED		
OUNDDY NO	TIOTO AND DEDOI	TC ON WELLS	BLM	6. Lease Designation and Serial No).
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different proposals.				SF-078387-A	
			(10) 100 100	·6 Mindian, Allottee or Tribe Nam	•
Use "APPLIC	ATION FOR PERMIT - " for	such proposation			
		070		7. Vi Unit or CA, Agreement Desi	gnetion
		777	NEIII	18	
			3 ~ (A)		
1. Type of Well Oil Gas Well Other		DEGE	400h	8. Well Name and No.	
2. Name of Operator			- CO	Kernaghan B #6	
Amoco Production Company		Kithtion: PQ Kell Steams	ow.	9. API Well No.	
3. Address and Telephone No.		20	No	3004527	339
P.O. Box 800, Denver, Colorado 80201		KANStelling	36.3	10. Field and Pool, or Exploratory	
4, Location of Well (Footage, Sec., T., R., M., or		COUR DO	J.F.	Basin Fruitla	nd Coal
4, Location of year (Footage, Sec., 1., 11, 11, 11, 11,				11. County or Parish, State	
1280' FNL 1800' FEI	_ Sec. 29 T	31N R 8W		Can luan	New Mexico
				San Juan	
12. CHECK APPROPRI	IATE BOX(s) TO IND	ICATE NATURE O	F NOTICE, RE	PORT, OR OTHER D	ATA
TYPE OF SUBMISSION		TY	PE OF ACTION		
	<u> </u>	Abandonment	H	Change of Plane	
Notice of Intent	<u> </u>	Recompletion	H	New Construction	
Subsequent Report	 	Plugging Back	H	Non-Routine Fracturing	
Subsequent Report		Casing Repair	H	Water Shut-Off Conversion to Injection	
Final Abandonment Notice		Altering Casing Other Recavitation	H	Dispose Water	
Fills Appropriate Notice	i	Otto		t results of multiple completion on \	Well Completion or
				n Report and Log form.)	
13. Describe Proposed or Completed Operations subsurface locations and measured and true	Clearly state all pertinent details, and	give pertinent dates, including es	timated date of starting	any proposed work . If well is dire	ctionally drilled, give
subsurface locations and measured and true		/N 2 875" TRG MILL	OFF TOP OF LI	NER AT 3133'. RIG UP	HLS AND SET
MIRUSU 3/6/94. NDWH NUBOP. TOH AND LAY DOWN 2.875" TBG. MILL OFF TOP OF LINER AT 3133'. RIG UP HLS AND SET BRIDGE PLUG AT 3200'. TEST BOP STACK, MANIFOLD AND CSG TO 1500 PSI HIGH AND 250 PSI LOW. DRILL OUT BRIDGE					
PLUG AT 3200'M W/1300 CFM AIR. BLOW WELL DRY. CLEAN OUT HOLE TO 3446'. CIRC WITH 1300 CFM AIR AND SOAP					
MIST.ROTATE & RECIPICATE AT 3446'. CIRC WITH 1300 CRM AIR AND 8 GPM SOAP. ROTATE & RECIPICATE AT 3446',					
CIRC WITH 650 CFM AIR AND 4 GPM SOAP. SHORT TRIP AND CHECK FOR FILL. 4' FILL. TRIP IN HOLE WITH UNDER REAMER					
TO 3250'. UNDER REAM FROM 3257' TO 3400'. CIRC WITH 1300 CFM AIR AND 8 GPM SOAP. UNDER REAM TO 3446'.					
10 3250". UNDER REAM FR	CURCE 7 TIMES DESS	TO SOO# IN 1 HR TI	H TAG BRIDGE	PLUG AT 3067' CLEA	N OUT HOLE
CAVITATE/SURGE WELL #1, SURGE 7 TIMES PRESS TO 690# IN 1 HR. TIH TAG BRIDGE PLUG AT 3067'. CLEAN OUT HOLE					
TO 3090', CIRC WITH 1300 CFM AIR AND 7 GPM H20 MIST. CLEAN OUT HOLE TO 3446', CIRC WITH 1300 CFM AIR AND					
7 GPM H20 MIST. ROTATE & RECIPICATE AT 3446', CIRC WITH 1300 CFM AIR AND 7 GPM H20 MIST, 10 BBL H20 SWEEPS EVERY 30 MINUTES. CAVITATE/SURGE WELL #2, SURGE 8 TIMES PRESS TO 690 PSI IN 1 HR. TIH TAG FILL AT					
SWEEPS EVERY 30 MINUTE	S. CAVITATE/SURGE WE	LL #2, SURGE 8 11M	ES PRESS TO 63	O PSI IN I HK. TIH TA	U FILL AT
3400'.CLEAN OUT HOLE TO) 3446' CIRC WITH 1300	CFM AIR AND 7GPM	M H2O MIST. CA	AVII A I E/SURGE WELL	#3, SUNGE /
TIMES PRESS TO 650 PSI IN	I 1 HR. TIH CLEAN OUT	30'OF FILL, CIRC WIT	H 1300 CFM A	IH AND 10 BBLS H20/	HR. RUIAIE &
RECIPICATE AT 3446', CIRC	; WITH 1300 CFM AIR A	ND 10 BBLS H2O/HR	. ROTATE AND	RECIPICATE AT 3446	CIRC WITH
650 CFM AIR AND 10 BBLS	H2O/HR. CAVITATE/SU	RGE WELL #4, SURGI	E 7 TIMES PRES	S TO 620 PSI IN 1 HR.	KILL WELL
AND TRIP IN HOLE, TAG FIL	L AT 3414'. CLEAN OUT	HOLE TO 3446', CIF	RC WITH 1300 (CFM AIR AND 10 BBLS	H2O/HR.
ROTATE & RECIPICATE AT	3446', CIRC WITH 650 C	FM AIR AND 10 BBL	S H2O/HR. TOH	TO SHOE AT 3250'. (AVITATE-
SURGE WELL #5, SURGE 6	TIMES PRESS TO 640 PS	I IN 1 HR. TIH CLEAN	OUT 30' FILL.	ROTATE & RECIPICATI	E AT 3446',
CIRC, WITH 1300 CFM AIR	AND 10BBLS H2O/HR.	continued (on attachment		
					·
14. I hereby certify that the foregoing is true and	correct				
Vally A+	Truns	Title	Business Ana	alyst Date	03-24-1994
Signed		1100		CEPTED FOR RE	CONV
(This space for Federal or State office use)			A	,	
		Tiela		400 A M. 408	4
Approved by Conditions of approvel, if any:	w	Title		APR 0 %-199	
Солашена от арргоча, и элу:		MMOCE		FARMINGTON DISTRICT	UrFICE
Title 18 U.S.C. Section 1001, makes it a crime for	or any person knowingly and willfully	o make to any department or ag	ency of the United State	any false, ficticious, or fraudulent	statements or

ROTATE & RECIPICATE AT 3446', CIRC WITH 650 CFM AIR AND 10 BBLS H2O/HR. CAVITATE/SURGE WELL #5, SURGE 2 TIMES PRESS UP TO 650 PSI IN 1 HR. CAVITATE WELL 8 TIMES AT ONE HR SHUT INS TO 650 PSI. TIH AND TAG 8FT FILL AND CLEAN OUT. CIRCULATING W/1300 CFM AIR AND 7GPM MIST. CIRCULATING AT TD W/650 CFM AIR AND 5 BBL WATER SWEEPS PER HALF HOUR. PICK UP AND TIH W/DP AND TAG FILL AT 3436'. LDDP AND PULL TO SHOE. PICK UP AND TIH AND TAG BOTTOM AT 3436'. NO ADDITIONAL FILL. LD DP OUT OF OPEN HOLE. HANG DP OFF IN TBG HEAD AND REMOVE STRIPPER HEAD. NU SNUBBING STACK AND SNUBBING UNIT ABOVE RIG FLOOR. PRESSURE TEST ALL BOPS AND RAMS TO 660 PSI THE SI WELL BORE PRESSURE AND TEST DONE W/CASING HEAD GAS. TOH AND LD DP THRU STACK. TEST ALL DRILL STACK AND SNUBBING STACK RAMS TO 680 PSI WELL BORE GAS. SNUB IN 75 JOINTS OF 4.5 INCH LT&C CASING AS PROD TBG. LAND HANGER IN TBG IN TBG HEAD AND LOCK DOWN. BLEED DOWN AND HELD GOOD. MULE SHOE END SET AT 3227' AND BAKER 2.75 IN PROFILE NIPPLE SA 3181'. ND SNUBBING UNIT AND BOP STACK. NUWH AND TEST SECONDARY TBG BONNET SEAL TO 1500 PSI. TST OK. RDMOSU 3/21/94.