Form 3160-5 (June 1990)

representations as to any matter within its jurisdiction.

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FOUNT MEETING AFT				
Budget Bur	eau No.	1004-013	35	
Expires:	March	31, 1993		

SUNDRY NOTICES AND I Do not use this form for proposals to drill or to o Use "APPLICATION FOR PERM	deepen or reentry to a different reservoir.	SF-080917 6. If Indian, Allottee or Tribe Name 7. If Unit or CA, Agreement Designation	
1. Type of Well		7. If Unit of CA, Agreement Designation	
☐ Other Well		8. Well Name and No.	
2. Name of Operator	Attention:	Atlantic 1-34	
Amoco Production Company	Patty Haefele	9. API Well No.	
3. Address and Telephone No.	(303) 830-4988	3004510180	
P.O. Box 800, Denver, Colorado 80201	W	Basin Dakota	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 990' FNL 990' FEL Sec.	34 T 31N R 10W Unit A	11. County or Parish, State San Juan New Mexico	
	TO INDICATE NATURE OF NOTICE		
TYPE OF SUBMISSION	TYPE OF ACTION		
Notice of Intent Subsequent Report Final Abandonment Notice		Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water Let: Report results of multiple completion on Well Completion or ompletion Report and Log form.	
Amoco Production Company intends to plug a lf you have any questions, please contact Pat		rocedure.	
	同国C国I		
	105 110 1210	10. BUV0 10. 3	
14. I hereby certify that the foregoing is true and correct Signed Patty Haefele	Title Busines	s Associate Date 01-05-1994	
(This space for Federal or State office use)	Title	ACCROVED AS AMENDED	
Approved by Conditions of approval, if any:	1106	2 10N 1 0 1995	

PXA Procedures Atlantic 1-34

- 1. Check location for anchors. Install if necessary. Test anchors.
- 2. MIRUSU. Blow down well. Kill if necessary with fresh water. NDWH. NUBOP.
- 3. POOH with 2 3/8" tbg. RIH with tbg and cement retainer. Set retainer at 7325'. Test casing integrity to 500#. Squeeze perfs at 7376' to 7498' with 59.856 cuft cement. Pull out of retainer and spot cement plug to 6450' with 80.66 cuft cement.
- 4. RIH with perf gun and shoot squeeze holes at 4625'. RIH with retainer and set 50' above the squeeze holes and attempt to circulate to surface. If unable to circulate to surface be sure the following are covered 100' inside and outside of casing:

Pictured Cliffs at 3031'
Fruitland Coal at 2659'
Ojo Alamo at 1796'
and 381' to surface
Estimate 188.092 outside of casing and 63.482 inside casing.

- 5. NDBOP. Cut off casing and wellhead. Install PXA marker according to BLM or State requirements.
- 6. Turn over to John Schwartz for reclamation.
- 7. Rehabilitate location according to BLM or State requirements.

