Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135 Expires: November 30, 2000

5. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					NMNM - 0606 6. If Indian, Allottee or Tribe Name	
l. Type of Well					8. Well Name and No.	
☐ Oil Well ☐ Gas Well ☐ Other 2. Name of Operator Contact: MARY CORTEYA					ATLANTIC A LS 9	•
2. Name of Operator BP AMERICA PRODUCTION	bp.com	À	9. API Well No. 30-045-10262			
3n. Address P.O. BOX 3092 HOUSTON, TX 77253	PM 281.36 Fx 281.366	Flude area code 3 449102 8700	9 \\ = \\ = \\	10. Field and Pool, or Exploratory BLANCO MESAVERDE		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				(F.1)	11. County or Parish,	und State
Sec 27 T31N R10W SWSW 1090FSL 1650FWL					SAN JUAN COUNTY, NM	
12. CHECK APPI	ROPRIATE BOX(ES) TO	O INDICATE	NATURE OF	NOTICE, RI	EPORT, OR OTHE	RDATA
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent ■	☐ Acidize	□ Deepen □ Pr		☐ Product	ion (Start/Resume)	☐ Water Shut-Off
	☐ Alter Casing	☐ Frac	ure Treat	reat Reclamation		■ Well Integrity
☐ Subsequent Report	☐ Casing Repair	☐ Casing Repair ☐ New Construction		☐ Recomp	- ·	
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug and Abandon ☐ Ten		☐ Tempor	arily Abandon	
	☐ Convert to Injection	□ Plug Back □ Water			Disposal	
following completion of the involved testing has been completed. Final At determined that the site is ready for f BP America respectfully reque Menefee and Lewis Shale for	inal inspection.)	by nerforating	and fracture s	timulating the	n, have been completed, a)-4 shall be filed once and the operator has
					1.0	
					(<u>1.</u> 9	
14. I hereby certify that the foregoing is	true and correct. Electronic Submission # For BP AMERICA PR	10822 verified ODUCTION C	by the BLM We DMPANY, sent t	II Information to the Farming	System (5)	
Name (Printed/Typed) MARY CORLEY			Title AUTHORIZED REPRESENTATIVE			
Signature (Electronic S	Submission)	Date 03/19/2002				
	THIS SPACE FO	OR FEDERA			 SE	
						11
Approved By /s/ Jim Lovato			Title Per		7. Date	4/02
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office	BLM-1	FFO	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Atlantic A LS 9 Payadd Procedure


Sec 27, T31N, R10W API #: 30-04510262

- 1. Check anchors. MIRU workover rig.
- 2. Kill with 2% KCL water if necessary. Nipple down WH. NU BOPs and diversion spool with 3" outlets and 3" pipe to the blow tank. Pressure test BOPs to 500 psi.
- 3. Tag for fill and tally OH with 2-3/8" production tubing. Visually inspect tubing while POOH.
- 4. TIH with bit and scraper for 4 1/2" liner to 5200'.
- 5. TIH with tubing-set RBP. Set RBP at 4500'. Load hole with 2% KCL.
- 6. Pressure test casing to 2500 psi. Unset RBP and POH.
- 7. RIH with CIBP and 3-1/8" casing guns 1 SPF 120 deg phasing with Schlumberger's Prospector, select-fire charge. Set CIBP at 5180'. Perforate Menefee and Lewis shale (correlate to GR log).
- 8. RIH with 2-3/8" frac string with retrievable packer. Set packer at 4850'
- 9. RU frac equipment and install wellhead isolation tool. Use 2% KCL-N2 foam in fracture stimulation.
- 10. Frac Menefee according to pump schedule.
- 11. Flowback frac fluid immediately.
- 12. POH with frac string.
- 13. RIH and set CIBP at 4500'
- 14. Breakdown each Lewis perforation interval with hydrochloric acid.
- 15. RU frac equipment and install wellhead isolation tool. Use 2% KCL-N2 foam in fracture stimulation.
- 16. Frac the Lewis shale according pump schedule.
- 17. Flowback frac fluid immediately.
- 18. TIH with tubing and bit. Cleanout fill and drill bridge plugs set at 4500' and 4850'. Clean out fill to PBTD at 5370'. Blow well dry at PBTD.
- 19. RIH with 2-3/8" production tubing and land at 5330'.

- 20. Swab water from the tubing with the sandline.
- 21. ND BOP's. NU WH. Test well for air. Return well to production.

Atlantic A LS 9

Sec 27, T31N, R10W API#: 30-04510262



TD: 5425'

updated: 02/05/02 az