



18-7-7-G (3-92)

Date:

Time Sent:

7/18/94 9:30

This transmission
consists of:

pages

T
O

Charles Gholson

NMOC

Aztec

FAX Number

505-334-6170

FAX Operator's Number for Confirmation

F
R
O
M

Khanh Vu

Amoco

Denver

FAX Telephone Number

Voice Telephone Number

303-830-4920

Notes:

BRADENHEAD PROCEDURES
FOR
SULLIVAN GAS COM 1 A
July 18, 1994
30-045-2473900 : MV

RECEIVED
JUL 18 1994
OIL CON. DIV.
DATE 3

1. Record tubing, shut-in casing and shut-in bradenhead pressures.
2. MIRUSU.
3. NUBOP and test BOP.
4. TOH with tubing and check tubing.
5. TIH with RBP and set at 4250'.
6. Pressure test 7" casing to 2000 psi. If any leak is found, locate them and call Khanh Vu in Denver before proceeding.
7. Run a GR/CBL from 2400' to determine cement top for 7" casing.
8. Perforate 2 squeeze holes within 100' of TOC.
9. Use dye to calculate cement volume, pump 200% of cement volume, and circulate cement to surface.
10. WOC at least 24 hours.
11. TIH with bit and scraper and drill out cement.
12. Pressure test squeeze perfs to 1000 psig. If pressure test does not hold, resqueeze.
13. Clean out with nitrogen to PBTD at 5210', retrieve all RBPs.
14. Install 2 3/8" tubing at 5180' with a 1/2 mule shoe on bottom and seating nipple one joint off bottom.
15. NUBOP. NU well head.
16. Tie well back into surface equipment and put on production.