UNITED STATES RTMENT OF THE INTERI

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundr	Notices and Reports on Wells		
	\ 5.	Lease Number	
		SF-078483	
1. Type of Well GAS	6.	If Indian, Al	ll. or
		Unit Agreemer	nt Name
2. Name of Operator	TE CE IN TO IT	Allison Unit	
BURLINGTON	OIL & GAS COMPANY Departor 1, NM 87499 (505) 326-90404 DISTO 9. 10. 26, T-32-N, R-7-W, NMPM		
RESOURCES	OIL & GAS COMPANY W		
	11 day 20 12 8.	Well Name & 1	
3. Address & Phone No. of	perator	Allison Unit API Well No.	Com #6
PO BOX 4289, FAIMINGCO.	1, MM 87433 (303) 328-80 AME (DIES 3.	30-045-25425	
4. Location of Well, Foota	ge, Sec., T, R, M 10.	Field and Poo	ol
1520'FNL, 1530'FEL, Sec	26, T-32-N, R-7-W, NMPM	Blanco Mesave	erde
	C 11.	County and S	
	\mathcal{G}	San Juan Co,	NM
12. CHECK APPROPRIATE BOX	TO INDICATE NATURE OF NOTICE, REPORT, OTHER	DATA	
Type of Submission	Type of Action		
X Notice of Inten	# = =	ans	
	Recompletion New Construct	cion	
Subsequent Repo	rt Plugging Back Non-Routine I	racturing	
	Casing Repair Water Shut of		
Final Abandonme		o Injection	
	X Other - Tubing Repair		
13. Describe Proposed or	Completed Operations		
13. Describe rioposed of	Completed operations		
It is intended to re	pair the tubing in the subject well according	ng to the atta	ached
Procedure.		- 10	
		07(
		9 JUL -	77)
		33 T	迁
		-2 AM 8:59 MINGTON, NM	윤유
		ත් 🗫	72
		5 3	L.
		<u>Z</u> 0.	الوب
		2 5	
		≥ 9	
14. A hereby certify that	t the foregoing is true and correct.		
(/sc K1.			
Signed May Mall	Title Regulatory Administrator Dat	e 7/1/99	
(This space for Federal or	State Office use)		
APPROVED BY S/Duane W. S		JUL 2 n 1200	
CONDITION OF APPROVAL, if			
	<u>-</u>		

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Allison Unit Com #60 Blanco Mesaverde, DPNO: 193701

1520'FNL, 1530' FEL Unit G, Section 26, T-32-N, R-07-W

Latitude: 36° 57.26076', Longitude: 107° 31.90794'

Tubing Repair Procedure

- Comply with all NMOCD, BLM and Burlington safety and environmental 1. Hold safety meeting. regulations. Test rig anchors and build blow pit prior to moving in rig. Notify BROG Regulatory (Peggy Bradfield 326-9727) and the appropriate Regulatory Agency prior to pumping any cement job. If an unplanned cement job is required, approval is required before the job can be pumped. If verbal approval is obtained, document approval in DIMS. Allow as much time as possible prior to pump time in case the Agency decides to witness the cement job.
- MOL and RU workover rig. Hold daily safety meetings. Obtain and record all wellhead pressures. NU 2. relief line. Blow well down and kill with 2% KCL water if necessary. ND WH and NU BOP with stripping head. Test and record operation of BOP rams. Have wellhead and valves serviced as necessary. Test secondary seal and replace/install as necessary.
- 2-3/8" tubing is set at 6123'. Release donut, pick up additional joints of tubing and tag bottom. (Record 3. depth.) PBTD should be at +/-6189'. TOOH with tubing. Visually inspect tubing for corrosion and replace any bad joints. Check tubing for scale build-up and notify Operations Engineer.
- If fill is encountered, TIH with 3-7/8" bit, bit sub and watermelon mill on 2-3/8" tubing and round trip 4. below perforations, cleaning out with air/mist. NOTE: When using air/mist, minimum mist rate is 12 bph. If scale is present, contact Operations Engineer to determine methodology for removing scale from casing and perforations.
- TIH with one joint of 2-3/8" tubing with an expendable check on bottom and a seating nipple one joint off 5. bottom then ½ of the 2-3/8" production tubing. Run a broach on sandline to insure that the tubing is clear. TIH with remaining 2-3/8" tubing and broach this tubing. Replace any bad joints. CO to PBTD with air/mist. PU above the perforations and flow the well naturally, making short trips for clean up when necessary.
- Land tubing at ±6123'. ND BOP and NU WH. Pump off expendable check. Connect to casing and 6. circulate air to assure that expendable check has pumped off. Obtain pitot gauge up the tubing. If well will not flow up the tubing, make swab run to SN. RD and MOL. Return well to production.

Recommended:

Approved: Bruce D. Bory 6. 16. 99
Drilling Superintendent

Operations Engineer:

Mike Haddenham BR Office - 326-9577

Pager - 327-8427 Home - 326-3102

MDH/amm 06/14/99