

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☐ Fee ☒ **XX**
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - I" (FORM C-101) FOR SUCH PROPOSALS.)


1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator E. C. Brawley Bloomfield Oilfield Service Co.	8. Farm or Lease Name E. C. Brawley Goodrum
3. Address of Operator P. O. Box 1641 --- Bloomfield, N.M. 87413	9. Well No. 1
4. Location of Well UNIT LETTER 0 FEET FROM THE _____ LINE AND _____ FEET FROM THE _____ LINE, SECTION 34 TOWNSHIP 30 N RANGE 11-W NMPM.	10. Field and Pool, or Wildcat Oswell Farmington
15. Elevation (Show whether DF, RT, GR, etc.)	12. County

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/> X
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-28-80 Install 20' of 7 5/8 surface pipe, rig up and mix mud, drill to 130' started cir. around surface pipe, run 4 jts, 4 1/2" J-55 csg to 105', cir. cement with 60 sks class "A" cement, w.o.c. drill to 356' broke cir. around surface pipe 5' from hole, squeeze 50 sks class "A" cement around surface pipe, w.o.c. drill wood and small gravel plugs out to 1387' drill 2" hard cement to 1389' cir. hole, clean, mix and spot 20 sks class "A" cement 1389' to 1200', pick tubing up to 700', mix and spot 15 sks class "A" cement 700' to 600' w.o.c. 4 hrs tag cement at 622', mix and spot 15 sks class "A" cement @ 180' x.o.c. overnight. Tag cement at 160' mix and spot 25 sks class "A" cement at 160' w.o.c. 4 hrs, tag cement at 137' mix and spot 15 sks class "A" cement at 115'. cement cir. up 4 1/2" csg., install dry hole marker, rig down, move rig out, fill all pits, level and clean location. Ready for inspection 8-3-80.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED D. E. Bayler TITLE partner DATE 8-6-80

Original Signed by CHARLES GHOLSON

APPROVED BY _____ TITLE DEPUTY OIL CONSERVATION DIVISION #3 DATE AUG 11 1980

CONDITIONS OF APPROVAL, IF ANY: