Office Office	State of Ne			Form C-103
<u>District 1</u> – (575) 393-6161	Energy, Minerals and	Natural Resources	S TYPLI LABOUR	October 13, 2009
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283			WELL API NO. 30-025-01485	
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type	of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St		STATE	FEE
District IV – (505) 476-3460	Santa Fe, N	IM 87505	6. State Oil & O	as Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505				
	CES AND REPORTS ON W	/ELLS	7. Lease Name	or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOS	SALS TO DRILL OR TO DEEPEN	OR PLUG BACK TO A		
DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.)	CATION FOR PERMIT" (FORM C	-101) FOR SUCH		LJAMAR UNIT
1. Type of Well: Oil Well	Gas Well  Other INJE	CTIONOBBS OCD	8. Well Number	: 38
2. Name of Operator	/		9. OGRID Num	ber 269324
LINN OPERATING, INC.	<u> </u>	JUL 17 2014		
3. Address of Operator	TON TENAN 77000	205 7 2 5014	10. Tool name c	1
600 TRAVIS, SUITE 5100, HOUS	110N, TEXAS //002	Character and the second	MALJAMAR;G ANDRES	RAYBURG-SAN
4. Well Location		RECEIVED	ANDRES	
	60 feet from the	line and	2047 feet from	m the W line
Section 19			33E NMPN	
Section 19	11. Elevation (Show wheth		·	7 LEA County
	4,120' GR	er Dr., KKB, KI, GK	, etc.)	And the second of the second o
· · · · · · · · · · · · · · · · · · ·	<u>aj 1,125 OAT</u>		i i	
12 Check A	Appropriate Box to Indic	ate Nature of Not	ice Report or Othe	r Data
12. Check 1	ippropriate box to mate	ate ivatare of ivot	ice, report of othe	Data
NOTICE OF IN	ITENTION TO:	5	SUBSEQUENT RI	EPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	-	ı —	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS		DRILLING OPNS .	P AND A
PULL OR ALTER CASING	MULTIPLE COMPL [	CASING/CE	MENT JOB	
DOWNHOLE COMMINGLE			!	
OTHER:	Г	OTHER:	PASSED MIT & RT	rı 🗵
13. Describe proposed or comp	leted operations. (Clearly sta			
	ork). SEE RULE 19.15.7.14	NMAC. For Multipl	e Completions: Attach	wellbore diagram of
proposed completion or rec	ompletion.		$\bigcirc$	HIMC
				setting
PASSED MIT & PETLIPN TO IN JECTION				
all continued				
			eycep	10/70/4
	•		· ·	
DI F	ASE SEE ATTACHE	D COMPLETED	ODERATIONS	1 1 0.10
PLEASE SEE ATTACHED COMPLETED OPERATIONS 148 above				
				=0
				T. Tell.
				· 0
				·
Spud Date:	Rig Rela	ease Date:		
Spud Date.	Rig Rei	Lase Date.		
I hereby certify that the information	above is true and complete to	o the hest of my know	wledge and helief	
1 ,	acove is true and complete t	· · · · · · · · · · · · · · · · · · ·	vieuge and belief.	
Mall	1100			
SIGNATURE CHICA		D 1 0 1	ance Specialist III D	ATE July 15, 2014
	TILE:	Regulatory Compl	ance Specialist III D	ATE July 13, 2014
Tuna or print name Town D. Coll 1.			- ,	
Type or print name Terry B. Callaha		dress: tcallahan@lin	- ,	ONE: <u>281-840-4272</u>
Type or print name Terry B. Callaha For State Use-Qnly			- ,	
• • •			- ,	
For State Use Quly			- ,	ONE: 281-840-4272 DATE 7/Z1/Z014

6/23/2014 – FLOW BACK TANK & WS ON LOCATION, BREAK FLOWLINE. NOT FLOWING. NDWH. RLSE PKR & NUBOP & PAN. TOOH. PKR OUT OF HOLE (PKR WAS SET @ 3385 – 133.43 ABOVE TOP PERF), TALLY WS. RIH W/ POLAR 5-1/2 CSG SCRAPER W/ 4-3/4" BIT. TAG UP @ 3960' PERFS. COVERED UP. POOH OUT W/ SCRAPER. LEAVE OPEN DOWN FLOW LINE & SHUT DOWN.

6/24/2014 - SPOT REV UNIT. RU TIH W/ 4-3/4" BEARCLAW CARBIDE TIP BIT, 4- 3-1/2" DC'S, 2-3/8" WS. LOAD PIT, TAG FILL @ 3877', LD 5 JTS, RU STRIPER HEAD & REV UNIT RU POWER SWIVEL CLEAN OUT TO 4290'. CIRC HOLE CLEAN. LD SWIVEL POOH TO 3973'. WELL FLOWING TO TANK.

6/25/2014 – TIH W/ TBG/ BIT, TAG UP @ 4270', START DRILL OUT TO 4350', CIRCULATE CLEAN, RIG DWN SWIVEL ND STRIPER HEAD LAY DWN 9-JTS TOH W/ TBG. IN DERRICK. (BIT WORN OUT TIPS GONE.) RU TIH W/ PKR, TO TEST TBG. @ 1090' CSG DID NOT TEST. TOH RU RBP AND PKR. TIH SET RBP @ 3963', AND PKR. @ 3931'. SI SWH SDFN.

6/26/2014 - RU CRAIN START TESTING CSG; RELEASE RBP. WILL NOT RE-SET POOH TOOLS FULL OF IRON SULFIDE LEAVE OPEN DOWN FLOW LINE & SHUT DOWN. (RBP @ 3931', PKR. 3963'. (TEST CSG BAD @ 1090'))

6/27/2014 - WATER COMING OUT OF SURFACE VALVE, RIH W/ D&L 5 1/2" 13-20# SL SHEAR TENSION PKR TO 3918' AND SET PKR. (OK) CRAIN MI & RU W/ 27 BBLS OF ACID IN PKR. CAME LOOSE. FLOW ACID OUT OF TBG. & CSG. POOH W/ PKR & TBG OUT W/ PKR. RIH W/ NEW D & L 5 1/2" 14-20 # AS1X TREATING PKR. PKR. SET @ 3918' AGAIN RU CRAIN & START ACID JOB. CSG BAD WELL COMMUNICATED TBG & CSG AGAIN PUMP 10 BBLS. TO FLUSH TO CLEAR OF ACID PULL PKR. TO 3825' PUMP 20 BBLS. 2% KCL AHEAD, GO TO ACID & FLUSH W/ 50 BBLS. 2% KCL. SWI

6/30/2014 - 700# TBG, 550# CSG. TRY TO BLOW WELL DOWN, UNABLE TO HOOK TO FLOW LINE.

7/01/2014 - RLSE PKR & POOH. OUT W/ PKR. RIH W/5 1/2 X 2 7/8 13-14#AS1X RBP W/ 2 7/8 E- VALVE & 5 1/2 14-20 AS1X PKR. RBP @ 3865'. DID NOT SHUT WATER OFF. MOVE RBP UP HOLE TO 3865' SHUT WATER OFF. SET PKR @ 3848'. WAIT ON PUMP TRUCK (CSG TEST GOOD FROM SURFACE TO 355' (BAD 355' TO 482') GOOD 485' TO 3931'). SDFN

7/02/2014 - BLEED WELL OFF, UNSET PKR, TOH W/ 2 - 2 3/8 JTS, SET PKR @ 355', WAIT ON PUMP TRUCK, HOOKED UP PUMP TRUCK, GOT INJECTION RATE, 2 BBLS A MIN @ 250#, TOH W/ 21- 2 3/8 JTS & PKR, PU TENSION PKR, SN, TIH W/ 10- 2 3/8 JTS SET PKR, PULLED 20 PTS OVER, READY FOR CMT, WAIT ON CMT UNIT, START CMT PUMP 2 BBLS FRESH & BROKE CIRC OUT OF SURF CSG, PUMP 150 SACKS CLASS C NEAT W/ 2% CALCIUM CHLORIDE & DISP W/ 2 1/2 BBLS FRESH, DID NOT GET CMT BACK TO SURFACE, LEFT WELL READY FOR CMT IN THE MORNING, PU LOC, SION,

7/03/2014 - REPAIRED PUMP RIG, PRESSURED UP WELL 500# CSG / CEMENT JOB (GOOD). TOH W/ 10 JTS & PKR. SWIFWE

7/07/2014 - RU TIH W 4-3/4" BEARCLAW BIT 4 – 3-1/2" COLLARS ON TBG. NU STRIPPER HEAD, BREAK CIRC & START DRLG, TAG UP @ 348', 393' AND 606', BUT NO FLOW OUT SURF VALVE. CIRC HOLE CLEAN.

7/08/2014 - DRLD, CMT FELL OUT @ 894'. RIH TO 957', CIRC CLEAN. CSG TEST TO 550# (HELD FOR 15 MINS), (GOOD). SWI

7/09/2014 - POOH W/ TBG, COLLARS & BIT. RIH W/ RET HEAD TO GET RBP, LATCH ONTO RBP. LAY FLOWLINE TO TANK OPEN H-VALVE & BLEED WELL DOWN. RLSE RBP & LD WS, OUT W/ RBP (OK). MI & RU TESTERS, ALL 2-3/8" IPC TBG TESTED GOOD. SET PKR @ 3865' (OK). RD TESTERS.

7/10/2014 - RU TIH W/ 5 1/2X2 3/8 14-20# AS1X W/ 51/2X2 3/8 X1.50F ON -OFF TOOL. ALL NICKEL PLATTED LOBO HERE, LOAD & TEST PKR. TO 500# OK PUMP 10 BBLS. DOWN TBG. GET OFF ON/OFF TOOL; CIRC 75 BBLS. PKR. FLUID & BIOCIDE; FINISH LATCH ONTO PKR. NDBOP & PAN & NUWH. HOOK ONTO TBG. BLOW OUT PLUG @ 2400# PUMP IN @ 2 BPM @ 1000#.

7/11/2014 - PERFORMED MIT FOR 36 MINS, START 520# AND FINISH 470#. PASSED, WITNESSED BY BILL SONNAMAKER (HOBBS, NMOCD), RETURN TO INJECTION.

ATTACHMENT - ORIGINAL MIT CHART

