Submit 1 Copy To Appropriate District Office	State of New M			m C-103
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Nat	ural Resources	Revised Aug WELL API NO.	gust 1, 2011
District II - (575) 748-1283	OIL CONSERVATION	NOIZIVIGION	30-025-38386	
811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178	1220 South St. Fra		5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	Santa Fe, NM 8		STATE X FEE [6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM	S 4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		o. State Off & Gas Lease No.	
87505 SUNDRY NOT	ICES AND REPORTS ON WELL	S	7. Lease Name or Unit Agreemen	nt Name
(DO NOT USE THIS FORM FOR PROPO	SALS TO DRILL OR TO DEEPEN OR PI	LUG BACK TO A	Vacuum Glorieta East Unit Tract 38	in i tuille
DIFFERENT RESERVOIR. USE "APPLI PROPOSALS.)			/	
1. Type of Well: Oil Well X	Gas Well Other	4-2-0	8. Well Number 029	
2. Name of Operator ConocoPhilli	ips Company FEE	3 0 8 2016	9. OGRID Number 217817	
3. Address of Operator P. O. Box	51810 R	ECEIVED	10. Pool name or Wildcat	
Midland, T	X /9/10		Vacuum; Glorieta	
4. Well Location Unit Letter N:	969 feet from the South	line and 247	7 feet from the West	line
Section 29		lange 35E	NMPM County Lea	
Section 29	11. Elevation (Show whether DI			DO FINE
12. Check A	Appropriate Box to Indicate N	Nature of Notice,	Report or Other Data	
NOTICE OF IN	ITENTION TO:	SUB	SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON □	REMEDIAL WOR		SING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI		
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL	CASING/CEMEN	「JOB □	
DOWNHOLE COMMININGLE				
OTHER:		OTHER:		
	ork). SEE RULE 19.15.7.14 NMA		d give pertinent dates, including esti appletions: Attach wellbore diagram	
ConocoPhillips Company would	like to TA this wellbores due to ha	ving a high water cut	and facility water handling capacity	у.
Procedures are Attached	111			
Attached is a current/proposed we	elibore schematic			
Spud Date:	Rig Release D	late:		
Spud Date.	Kig Kelease D	atc.		
I hereby certify that the information	above is true and complete to the b	est of my knowledg	e and belief.	
. / / / / /		-		
SIGNATURE November 1	TITLE Staff	Regulatory Technicia	DATE 02/03/2016	= =
Type or print name Rhonda Rogers	F-mail addres	ss: rogerrs@conoco	phillips.com PHONE: (432)688	8-9174
For State Use Only	2-man addres	10goristi conoco	1110111. (432)000	
YVI AL)	MK10111 - Ni	At 5. 000	11001 - 2/01	2016
APPROVED BY:	USIQUAL TITLE DI	and Superior	DATE A/O/	wit
Conditions of Approval (if any):		•	TED A D DAIG	1
		W. S. C. 1	FEB 0 8 2016	14

VGEU 38-29 API 30-025-38386 TA WELLBORE

Project Scope

Justification and Background: TA wellbore

This well has been down since 10/19/2015 due to having a high water cut and facility water handling capacity. This well has a fluid level (765' FAP) and needs to be converted to an ESP. However, due to the uncertainty of how much fluid the 2015 VGEU New Drill Program will provide to the battery, which started in September, the increased water production that would occur from the conversion the facility would be operating at or beyond its capacity. Therefore, the 2015 VGEU New Drills will be put on production and the facility upgrade will be re-evaluated before this ESP conversion.

Well Control Information				
Estimated H2S (ppm)	15,000	Max anticipated MCFPD	10	
100 ppm H2S ROE (ft)	7	Well Category	1	
500 ppm H2S ROE (ft)	3	BOP Class	1 (Hydraulic)	

Perforations					
Type	Formation	Top	Bottom		
Perforations	Glorieta	6,109'	6,144'		
PBTD	6,275'				
TD	6,335'				

Well Service Procedure:

- 1) MIRU pulling unit. Kill well.
- 2) TOOH w/ rods & pump. LD rods and pump. Send pump and shear tool to Don Nan to be inspected.
 - a. Notify Henry Guillen (575-390-8311) to have TRC pick up rods.
 - b. Send pump to Don Nan to be inspected, repaired, and put back as spare. If pump is junk or uneconomical to repair, will not repair or build new.
 - c. Inspect shear tool, repair, and put back as spare. If uneconomic to repair, will not repair or build new.
- 3) NDWH, NUBOP. Test BOP.
- 4) Release TAC & TOOH w/ Tbg. LD TAC. Stand Tbg back in Derrick.
 - a. Visually inspect all Tbg out of hole for scale and paraffin.

If scale or paraffin is present

- 5) PU & TIH w/ bit and scraper sized for 15.5# 5 ½" casing to PBTD @ 6,275'. TOOH & LD bit and scraper. Stand back Tbg in Derrick.
 - a. Record tag depth in WV

If scale or paraffin is not present

- 6) PU & TIH w/ CBP. Set CBP @ 6,059' (50' from top perf).
- RU pump truck. Load well bore w/ brine and test CBP to 500 psi surface pressure. If CBP holds then proceed to circulate packer fluid and chart pressure.
- 8) RU pump truck. Circulate packer fluid to surface (6,059' x 0.0238 bbl/ft = 144 bbls).

VGEU 38-29 API 30-025-38386 TA WELLBORE

- 9) MI lay down machine. TOOH & lay down Tbg. Release lay down machine.
 - a. Send Tbg into EL Farmer to be inspected
 - b. Top off casing w/ packer fluid
- 10) RU chart recorder w/1,000 psi chart to casing. Pressure test CBP to 560 psi for 35 mins.
 - a. Notify the NMOCD of impending test.
 - b. If test fails, notify Production Eng. for possible job scope change.
 - c. Do not look for casing leak without approval.
- 11) NDBOP. NUWH.
- 12) RDMO and release all equipment.

