

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2038
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-77

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REPERM OR PLUG, SALA TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT WITH FORM C-1011 FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		4. Location of well UNIT LETTER <u>H</u> <u>1650</u> FEET FROM THE <u>North</u> LINE AND <u>990</u> FEET FROM THE <u>East</u> LINE, SECTION <u>8</u> TOWNSHIP <u>19-S</u> RANGE <u>38-E</u> N.M.P.M.	5. Indicate Type of Lease State <input type="checkbox"/> Fed <input checked="" type="checkbox"/>
2. Name of Operator <u>Amoco Production Company</u>		6. State Oil & Gas Lease No.	7. Unit Agreement Name
3. Address of Operator <u>P. O. Box 68, Hobbs, New Mexico 88240</u>		8. Farm or Lease Name <u>South Hobbs (GSA) Uni</u>	9. Well No. <u>70</u>
15. Elevation (Show whether DF, RT, CR, etc.) <u>3620' KB</u>		10. Field and Pool, or Locat <u>Hobbs (GSA)</u>	
12. County <u>Lea</u>			

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to eliminate excessive water production as follows:
Rig up service unit with rods, pump and tubing. Run in hole with cast iron bridge plug for 5-1/2" -15.5# casing and workstring. Set cast iron bridge plug at 4110'. Pull out of hole with workstring. Run in hole with mother hubbard and 2-3/8" tubing. Set seating nipple at 4040±. Run in hole with pump and rods. Return well to production and evaluate by pump test.

O+4-NMOCD, H 1-HOU R. E. Ogden RM 21.150 1-F. J. Nash, HOU RM 4.206 1-SUSP 1-PJS
1-Petro Lewis

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Peter J. Serna TITLE Assist. Admin. Analyst DATE 6-14-83

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT SUPERVISOR

JUN 16 1983

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
JUN 15 1983
O.C.D.
HOBBS OFFICE