

COPY TO O.G.U.

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.
NM 04465

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Federal "WL"

9. WELL NO.
D 1

10. FIELD AND POOL, OR WILDCAT
Triste Draw Delaware

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA
Sec. 35, T-23-S, R-32-E

12. COUNTY OR PARISH 13. STATE
Lea New Mexico

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLET.

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. MI RU Casing PU. Warehouse rods & pull tbg. Call U.S.G.S. in Hobbs, New Mexico
2. Set CIBP on tbg. at - 4,980'.
3. Spot 35' cement plug on top of CIBP. PU to 4,900'.
4. Circ. casing w/9.5#/gal. ~~brine w/2500# salt gel/100 barrels brine.~~
mud
5. POOH with tbg.
6. Freepoint 4-1/2" casing and cut off.
7. Lay down 4-1/2" casing.
 - a) If 4-1/2" casing is stuck above 1,300'. perforate 4-1/2" at 1,300' (top of salt ± 1,360') & squeeze cement to surface casing shoe (approx. 200 sx. using 25% loss), leaving a 200' (14 sx.) plug in the 4-1/2" casing. Then go to step No. 11.
8. RIH w/2-3/8" tbg. & spot a Class "C" cement plug 100' in & 100' out of 4-1/2" casing stub (approx. 50 sx.).
9. Pull tbg. to 1,200' (top of salt at 1,350') & spot 50 sx. Class "C" cement plug. Tag plug after 12 hours.
10. Pull tbg. to ± 430' & spot a Class "C" cement plug across 8-5/8" casing shoe from 430' to 330' (approx. 35 sx.).
11. Pull tbg. to 30' & spot 10 sx. Class "C" cement plug to surface.
12. Cut off casing below SB & weld 1/2" steel plate on 8-5/8" casing.
13. Rig down casing pillars.
14. Install dry hole marker, minimum of 4' above ground level.
Clean and level location.
15. Obtain final inspection.

18. I hereby certify that the foregoing is true and correct

SIGNED *J.R. Hughes* J.R. Hughes

TITLE District Drilling Supt. DATE May 5, 1981

(This space for Federal Public Data use)

APPROVED

TITLE DATE

* APPROVED BY *Roger A. Chapman*
CONDITIONS OF APPROVAL, IF ANY:
MAY 12 1981

for JAMES A. GILGHAM
DISTRICT SUPERVISOR

* SUBJECT TO ATTACHED CONDITIONS

* See Instructions on Reverse Side