



## C6+ Gas Analysis Report

11019G	South Hobbs Unit CTB Inlet		South Hobbs Unit CTB Inlet
Sample Point Code	Sample Point Name		Sample Point Location
Laboratory Services	2020036993	1719	D Armstrong - Spot
Source Laboratory	Lab File No	Container Identity	Sampler
USA	USA	USA	New Mexico
District	Area Name	Field Name	Facility Name
Nov 24, 2020 09:58	Nov 24, 2020 09:58	Nov 24, 2020 11:59	Nov 24, 2020
Date Sampled	Date Effective	Date Received	Date Reported
60.00	Torrance	38 @ 70	
Ambient Temp (°F)	Flow Rate (Mcf)	Analyst	Press PSI @ Temp °F Source Conditions
Oxy	NG		
Operator	Lab Source Description		

Component	Normalized Mol %	Un-Normalized Mol %	GPM
H2S (H2S)	0.0000	0	
Nitrogen (N2)	0.1080	0.10806	
CO2 (CO2)	85.2310	85.23111	
Methane (C1)	0.6730	0.67276	
Ethane (C2)	0.6140	0.61395	0.1640
Propane (C3)	3.9190	3.91938	1.0790
I-Butane (IC4)	1.7080	1.70793	0.5590
N-Butane (NC4)	4.2350	4.23453	1.3350
I-Pentane (IC5)	1.4540	1.45438	0.5320
N-Pentane (NC5)	0.9800	0.98005	0.3550
Hexanes Plus (C6+)	1.0780	1.07784	0.4680
TOTAL	100.0000	100.0000	4.4920

Method(s): Gas C6+ - GPA 2261, Extended Gas - GPA 2286, Calculations - GPA 2172

## Analyzer Information

Device Type: Gas Chromatograph      Device Make: Shimadzu  
 Device Model: GC-2014      Last Cal Date: Nov 24, 2020

## Gross Heating Values (Real, BTU/ft³)

14.696 PSI @ 60.00 °F		14.73 PSI @ 60.00 °F	
Dry	Saturated	Dry	Saturated
464.3	457.3	465.4	458.4

## Calculated Total Sample Properties

GPA2145-16 \*Calculated at Contract Conditions

Relative Density Real	Relative Density Ideal
1.5926	1.5805
Molecular Weight	
45.7756	

## C6+ Group Properties

Assumed Composition

C6 - 60.000%	C7 - 30.000%	C8 - 10.000%
--------------	--------------	--------------

Field H2S  
0 PPM

## PROTREND STATUS:

Passed By Validator on Nov 24, 2020

## DATA SOURCE:

Imported

## PASSED BY VALIDATOR REASON:

First sample taken @ this point, composition looks reasonable

## VALIDATOR:

Torrance Galvan

## VALIDATOR COMMENTS:

OK

**EVENT SPECIFIC JUSTIFICATIONS FORM****Facility:** South Hobbs Unit CTB**Start Date:** 05/29/2021 @ 07:25 PM**End Date:** 05/29/2021 @ 07:45 PM**Cause:** Sudden and unexpected compressor malfunction due to high temp alarm**Duration of event:** 20 minutes**Method of Flared Gas Measurement:** Flare Meter

---

**1. Reason why this event was beyond Operator's control:**

The emissions event was caused by the unforeseen, unexpected, sudden, and unavoidable breakdown of equipment or process that was beyond the owner/operator's control, and did not stem from activity that could have been foreseen and avoided, and could not have been avoided by good design, operation, and preventative maintenance practices. It is OXY's policy to route all stranded sales gas to a flare during an unforeseen and unavoidable emergency or malfunction, in order to minimize emissions as much as possible. The flare is regularly monitored to ensure flame is lit and meeting opacity requirements. Internal OXY compression equipment failure procedures ensure that upon a compressor unit shutdown, a production tech is promptly notified and is instructed to assess the issue as soon as possible in order to take prompt corrective action and minimize emissions. Upon arrival, production tech must assess whether compressor shutdown is due to damage and repair is needed, or whether there are other reasons. In this case, this emissions event was caused by compressor unit LP4700 malfunctioning due to overheating from extremely high ambient temperatures. This compressor malfunction was caused by the combination of extremely high ambient temperatures and normal engine operating conditions (despite proper design and operation) caused the compressors to overheat, which in turn triggered the engine's sensor to abruptly shut down the unit to avoid catastrophic damage to the internal engine components. This event was completely out of OXY's control to prevent from occurring but OXY made every effort to control and minimize excess emissions while OXY productions resolved the issues. Notwithstanding compressor design and operation, compressors are inherently dynamic and high external ambient temperatures can cause compressors to malfunction and shutdown with warning or advance notice. High external ambient temperatures can decrease the efficiency of the compressor unit coolers to maintain operability temperatures as well as increase the temperatures of the equipment itself from radiant heat. In addition, external high ambient temperatures can also raise the temperature of the incoming gas to the compressors as the radiant heat hits the flowlines the gas is flowing through; which in turn, this metal flowline shall increase the gas temperature, which causes the internal compressor temperature to rise as well. These gas compressors are engineered to shut down at certain maximum external/internal temperatures in order to avoid catastrophic damage to the compressors.

**2. Steps Taken to limit duration and magnitude of venting or flaring:**

The emissions event was caused by the unforeseen, unexpected, sudden, and unavoidable breakdown of equipment or process that was beyond the owner/operator's control, and did not stem from activity that could have been foreseen and avoided, and could not have been avoided by good design, operation, and preventative maintenance practices. It is OXY's policy to route all stranded sales gas to a flare during an unforeseen and unavoidable emergency or malfunction, in order to minimize emissions as much as possible. The flare is regularly monitored to ensure flame is lit and meeting opacity requirements. In this case, the steps taken to limit duration and magnitude of flaring was for Oxy production techs to quickly respond to the compressor alarm, diagnose the issue, and make the necessary adjustments to restart the unit back to normal working service. This event and the steps taken to limit the duration of the flaring lasted no more than twenty (20) minutes.

**3. Corrective Actions taken to eliminate the cause and reoccurrence of venting or flaring:**

The emissions event was caused by the unforeseen, unexpected, sudden, and unavoidable breakdown of equipment or process that was beyond the owner/operator's control, and did not stem from activity that could have been foreseen and avoided, and could not have been avoided by good design, operation, and preventative maintenance practices. It is OXY's policy to route all stranded sales gas to a flare during an unforeseen and unavoidable emergency or malfunction, in order to minimize emissions as much as possible. The flare is regularly monitored to ensure flame is lit and meeting opacity requirements. Oxy cannot take any corrective actions to eliminate the cause and potential reoccurrence of this flaring event as this event was caused by compressor unit LP4700 malfunctioning due to overheating from extremely high ambient temperatures. High ambient temperatures can have a drastic effect on compression equipment, and therefore malfunctions resulting from such are not foreseeable. Oxy makes every effort to perform weather preparations to its facility and its equipment to ensure safe and efficient working operations.

**District I**

1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720

**District II**

811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720

**District III**

1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170

**District IV**

1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

QUESTIONS

Action 32441

**QUESTIONS**

Operator: OCCIDENTAL PERMIAN LTD P.O. Box 4294 Houston, TX 772104294	OGRID: 157984
	Action Number: 32441
	Action Type: [C-129] Venting and/or Flaring (C-129)

**QUESTIONS****Determination of Reporting Requirements**

Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide additional guidance.

Was or is this venting or flaring caused by an emergency or malfunction	Yes
Did or will this venting or flaring last eight hours or more cumulatively within any 24-hour period from a single event	No
Is this considered a submission for a notification of a major venting or flaring	Yes, minor venting or flaring of natural gas.
<b>The operator shall file a form C-141 instead of a form C-129 for a release that includes liquid during venting or flaring that is or may be a major or minor release under 19.13.297 NMAC.</b>	
Was there or will there be at least 50 MCF of natural gas vented or flared during this event	Yes
Did this venting or flaring result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No

**Unregistered Facility Site**

Please provide the facility details, if the venting or flaring occurred or is occurring at a facility that does not have an Facility ID (##) yet.

Facility or Site Name	Not answered.
Facility Type	Not answered.

**Equipment Involved**

Primary Equipment Involved	Other (Specify)
Additional details for Equipment Involved. Please specify	Emergency Flare due to sudden and unexpected compressor malfunction due to high temp alarm

**Representative Compositional Analysis of Vented or Flared Natural Gas**

Please provide the mole percent for the percentage questions in this group.

Methane (CH4) percentage	1
Nitrogen (N2) percentage, if greater than one percent	0
Hydrogen Sulfide (H2S) PPM, rounded up	0
Carbon Dioxide (CO2) percentage, if greater than one percent	85
Oxygen (O2) percentage, if greater than one percent	0
<b>If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.</b>	
Methane (CH4) percentage quality requirement	Not answered.
Nitrogen (N2) percentage quality requirement	Not answered.
Hydrogen Sulfide (H2S) PPM quality requirement	Not answered.
Carbon Dioxide (CO2) percentage quality requirement	Not answered.
Oxygen (O2) percentage quality requirement	Not answered.

**Date(s) and Time(s)**

Date venting or flaring was discovered or commenced	05/29/2021
Time venting or flaring was discovered or commenced	07:25 PM
Is the venting or flaring event complete	Yes
Date venting or flaring was terminated	05/29/2021
Time venting or flaring was terminated	07:45 PM
Total duration of venting or flaring in hours, if venting or flaring has terminated	0
Longest duration of cumulative hours within any 24-hour period during this event	0

**Measured or Estimated Volume of Vented or Flared Natural Gas**

Natural Gas Vented (Mcf) Details	Not answered.
Natural Gas Flared (Mcf) Details	Cause: Equipment Failure   Other (Specify)   Natural Gas Flared   Spilled: 117 Mcf   Recovered: 0 Mcf   Lost: 117 Mcf ]
Other Released Details	Not answered.
Additional details for Measured or Estimated Volume(s). Please specify	Not answered.
Is this a gas only submission (i.e. only Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.

**Venting or Flaring Resulting from Downstream Activity**

Was or is this venting or flaring a result of downstream activity	No
Date notified of downstream activity requiring this venting or flaring	Not answered.
Time notified of downstream activity requiring this venting or flaring	Not answered.

**Steps and Actions to Prevent Waste**

--

For this event, the operator could not have reasonably anticipated the current event and it was beyond the operator's control.	True
Please explain reason for why this event was beyond your operator's control	In this case, this emissions event was caused by compressor unit LP4700 malfunctioning due to overheating from extremely high ambient temperatures. This compressor malfunction was caused by the combination of extremely high ambient temperatures and normal engine operating conditions (despite proper design and operation) caused the compressors to overheat, which in turn triggered the engine's sensor to abruptly shut down the unit to avoid catastrophic damage to the internal engine components. This event was completely out of OXY's control to prevent from occurring but OXY made every effort to control and minimize excess emissions while OXY productions resolved the issues.
Steps taken to limit the duration and magnitude of venting or flaring	The emissions event was caused by the unforeseen, unexpected, sudden, and unavoidable breakdown of equipment or process that was beyond the owner/operator's control, and did not stem from activity that could have been foreseen and avoided, and could not have been avoided by good design, operation, and preventative maintenance practices. It is OXY's policy to route all stranded sales gas to a flare during an unforeseen and unavoidable emergency or malfunction, in order to minimize emissions as much as possible. The flare is regularly monitored to the ensure flame is lit and meeting opacity requirements. In this case, the steps taken to limit duration and magnitude of flaring was for Oxy production techs to quickly respond to the compressor alarm, diagnose the issue, and make the necessary adjustments to restart the unit back to normal working service. This event and the steps taken to limit the duration of the flaring lasted no more than twenty (20) minutes.
Corrective actions taken to eliminate the cause and reoccurrence of venting or flaring	The emissions event was caused by the unforeseen, unexpected, sudden, and unavoidable breakdown of equipment or process that was beyond the owner/operator's control, and did not stem from activity that could have been foreseen and avoided, and could not have been avoided by good design, operation, and preventative maintenance practices. It is OXY's policy to route all stranded sales gas to a flare during an unforeseen and unavoidable emergency or malfunction, in order to minimize emissions as much as possible. The flare is regularly monitored to the ensure flame is lit and meeting opacity requirements. Oxy cannot take any corrective actions to eliminate the cause and potential reoccurrence of this flaring event as this event was caused by compressor unit LP4700 malfunctioning due to overheating from extremely high ambient temperatures. High ambient temperatures can have a drastic effect on compression equipment, and therefore malfunctions resulting from such are not foreseeable. Oxy makes every effort to perform weather preparations to its facility and its equipment to ensure safe and efficient working operations.

**District I**  
1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720  
**District II**  
811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720  
**District III**  
1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170  
**District IV**  
1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS  
  
Action 32441

CONDITIONS

Operator: OCCIDENTAL PERMIAN LTD P.O. Box 4294 Houston, TX 772104294	OGRID: 157984
	Action Number: 32441
	Action Type: [C-129] Venting and/or Flaring (C-129)

CONDITIONS

Created By	Condition	Condition Date
system	If the information provided in this report requires an amendment, submit a [C-129] Request to Amend Venting and/or Flaring Incident, utilizing your incident number from this event.	6/17/2021