



Certificate of Analysis

Number: 6030-21050216-004A

Artesia Laboratory

200 E Main St.

Artesia, NM 88210

Phone 575-746-3481

Chandler Montgomery
Occidental Petroleum
1502 W Commerce Dr.
Carlsbad, NM 88220

May 25, 2021

Field: Turkey
Station Name: Turkey Track CTB Check B
Station Number: 14670B
Station Location: CTB
Sample Point: Meter
Formation: Spot
County: Eddy
Type of Sample: : Spot-Cylinder
Heat Trace Used: N/A
Sampling Method: : Fill and Purge
Sampling Company: : SPL

Sampled By: Michael Mirabal
Sample Of: Gas Spot
Sample Date: 05/20/2021 10:47
Sample Conditions: 79 psia, @ 82 °F Ambient: 75 °F
Effective Date: 05/20/2021 10:47
Method: GPA-2261M
Cylinder No: 5030-00537
Instrument: 6030_GC6 (Inficon GC-3000 Micro)
Last Inst. Cal.: 05/03/2021 0:00 AM
Analyzed: 05/25/2021 07:28:39 by KNF

Analytical Data

Components	Un-normalized Mol %	Mol. %	Wt. %	GPM at 14.65 psia		
Hydrogen Sulfide	0.000	0.000	0.000		GPM TOTAL C2+	5.984
Nitrogen	2.015	2.042	2.652		GPM TOTAL C3+	2.878
Methane	75.693	76.715	57.062		GPM TOTAL iC5+	0.649
Carbon Dioxide	0.232	0.235	0.480			
Ethane	11.483	11.638	16.226	3.106		
Propane	5.288	5.359	10.957	1.473		
Iso-butane	0.679	0.688	1.854	0.225		
n-Butane	1.667	1.689	4.552	0.531		
Iso-pentane	0.421	0.427	1.428	0.156		
n-Pentane	0.431	0.437	1.462	0.158		
Hexanes Plus	0.760	0.770	3.327	0.335		
	98.669	100.000	100.000	5.984		

Calculated Physical Properties

Relative Density Real Gas	Total	C6+
	0.7472	3.2176
Calculated Molecular Weight	21.57	93.19
Compressibility Factor	0.9963	

GPA 2172 Calculation:

Calculated Gross BTU per ft³ @ 14.65 psia & 60°F

Real Gas Dry BTU	1268	5113
Water Sat. Gas Base BTU	1246	5024
Ideal, Gross HV - Dry at 14.65 psia	1263.2	5113.2
Ideal, Gross HV - Wet	1241.1	5023.7
Net BTU Dry Gas - real gas	1151	
Net BTU Wet Gas - real gas	1131	

Comments: H2S Field Content 0 ppm
Mcf/day 19263

Report generated by:

Quality Assurance: The above analyses are performed in accordance with ASTM, UOP, GPA guidelines for quality assurance, unless otherwise stated.

UPSET EVENT SPECIFIC JUSTIFICATIONS FORM**Facility:** Turkey Track CTB**Date:** 08/23/2021**Duration of event:** 15 Minutes**MCF Flared:** 114**Start Time:** 12:49 PM**End Time:** 01:04 PM**Cause:** Compressor Malfunctions > Gas Lift Compressor Unit # 3 & # 4**Method of Flared Gas Measurement:** Gas Flare Meter**Well API Associated with Facility:** 30-015-44143 Turkey Track 8 7 State 023 H

Comments: This upset event was not caused by any wells associated with the facility. This emissions event was caused by the unforeseen, unexpected, sudden, and unavoidable issue that was beyond the owner/operator's control, and did not stem from activity that could have been foreseen and avoided, and could not have been avoided by good design, operation, and preventative maintenance practices.

1. Reason why this event was beyond Operator's control:

The emissions event was caused by the unforeseen, unexpected, sudden, and unavoidable breakdown of equipment or process that was beyond the owner/operator's control, and did not stem from activity that could have been foreseen and avoided, and could not have been avoided by good design, operation, and preventative maintenance practices. It is OXY's policy to route all stranded sales gas to a flare during an unforeseen and unavoidable emergency or malfunction, in order to minimize emissions as much as possible. The flare is regularly monitored to ensure flame is lit and meeting opacity requirements.

In this case, several Oxy production techs and maintenance techs worked together to install gauges on the low and high liquid dump lines of gas lift compressor units #3 and # 4. While this work was being performed all other compression equipment at the facility was maximized. Oxy production techs and maintenance techs started this work by shutting down gas lift compressor #3 and quickly installing the gauges to the low and high liquid dump lines of the unit. Once the gauges were installed, Oxy production techs attempted to restart gas compressor unit #3 while the maintenance techs began procedures to shut down gas lift compressor unit # 4 to perform the same gauge installation work. The techs assumed that gas compressor unit # 3 would restart, but after several attempts, a call was made to the compressor owner to send out a compressor mechanic. With both gas lift compressor units down, the volume of gas overwhelmed the compression equipment and stranded gas was routed to flare. Oxy techs worked very quickly to finish installing the gauges on gas lift compressor unit # 4, and then restarted the unit, which caused flaring to cease a few minutes later, once gas lift compressor unit was working at normal working service. Flaring did not occur until both units were down, which cause excess gas to overwhelm the remaining compression equipment, yet Oxy techs worked diligently and efficiently to complete their work, and restart compressor unit # 4. USA compressor mechanic arrived soon, and was able to troubleshoot the unit, and get gas lift compressor unit # 3 started and back to working service, yet flaring had ceased once gas lift compressor unit #4 was restarted.

This event could not have been foreseen, avoided or planned for as notwithstanding compressor engine design and operation, compressors are inherently dynamic and even the smallest alarms, false or true, can be sudden, reasonably unforeseeable and unexpected which can cause compression malfunctions to occur. This event is

out of OXY's control yet, OXY made every effort to control and minimize emissions as much as possible. Oxy engages in respectable and good facility operation practices while also maintaining its continuous facility equipment preventative maintenance program.

2. Steps Taken to limit duration and magnitude of venting or flaring:

The steps take to limit the duration of this flaring was for Oxy techs to quickly finish installing the gauges on gas lift compressor unit # 4, and then restart the unit in order to have flaring cease. As stated above, Oxy production techs attempted to restart gas compressor unit #3 while the maintenance techs began procedures to shut down gas lift compressor unit # 4 to perform the same gauge installation work. The techs assumed that gas compressor unit # 3 would restart, but after several attempts, a call was made to the compressor owner to send out a compressor mechanic. With both gas lift compressor units down, the volume of gas overwhelmed the compression equipment and stranded gas was routed to flare. Oxy techs worked very quickly to finish installing the gauges on gas lift compressor unit # 4, and then restarted the unit, which caused flaring to cease a few minutes later, once gas lift compressor unit was working at normal working service. Flaring did not occur until both units were down, which cause excess gas to overwhelm the remaining compression equipment, yet Oxy techs worked diligently and efficiently to complete their work, and restart compressor unit # 4. USA compressor mechanic arrived soon, and was able to troubleshoot the unit, and get gas lift compressor unit # 3 started and back to working service, yet flaring had ceased once gas lift compressor unit #4 was restarted.

This event could not have been foreseen, avoided or planned for as notwithstanding compressor engine design and operation, compressors are inherently dynamic and even the smallest alarms, false or true, can be sudden, reasonably unforeseeable and unexpected which can cause compression malfunctions to occur. This event is out of OXY's control yet, OXY made every effort to control and minimize emissions as much as possible. Oxy engages in respectable and good facility operation practices while also maintaining its continuous facility equipment preventative maintenance program.

3. Corrective Actions taken to eliminate the cause and reoccurrence of venting or flaring:

Oxy cannot take any corrective actions to eliminate the cause and potential reoccurrence of compressor malfunctions as notwithstanding proper gas compressor design and operation, various forms of mechanical or technical issues can be sudden, reasonably unforeseeable and unexpected which can cause compressor unit malfunctions to occur without warning or advance notice. Oxy continually strives to maintain and operate its facility equipment in a manner consistent with good practices for minimizing emissions and reducing the number of emission events. Oxy has a strong and positive compression equipment preventative maintenance program in place. This incident was completely out of OXY's control to foresee, avoid or prevent from happening. OXY made every effort to control and minimize emissions as much as possible during this event. The only actions that Oxy can take and handle that is within its control, is to keep continue with its compression equipment preventative maintenance program for this facility.

District I1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720**District II**811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720**District III**1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170**District IV**1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 46465

QUESTIONS

Operator: OXY USA WTP LIMITED PARTNERSHIP P.O. Box 4294 Houston, TX 772104294	OGRID: 192463
	Action Number: 46465
	Action Type: [C-129] Venting and/or Flaring (C-129)

QUESTIONS

Prerequisites	
<i>Any messages presented in this section, will prevent submission of this application. Please resolve these issues before continuing with the rest of the questions.</i>	
Incident Well	[30-015-44143] TURKEY TRACK 8 7 STATE #023H
Incident Facility	Not answered.

Determination of Reporting Requirements	
<i>Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide additional guidance.</i>	
Was or is this venting and/or flaring caused by an emergency or malfunction	Yes
Did or will this venting and/or flaring last eight hours or more cumulatively within any 24-hour period from a single event	No
Is this considered a submission for a notification of a major venting and/or flaring	Yes, minor venting and/or flaring of natural gas.
<i>An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during venting and/or flaring that is or may be a major or minor release under 19.15.29.7 NMAC.</i>	
Was there or will there be at least 50 MCF of natural gas vented and/or flared during this event	Yes
Did this venting and/or flaring result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No
Was the venting and/or flaring within an incorporated municipal boundary or withing 300 feet from an occupied permanent residence, school, hospital, institution or church in existence	No

Equipment Involved	
Primary Equipment Involved	Other (Specify)
Additional details for Equipment Involved. Please specify	Emergency Flare > Compressor Malfunctions > Gas Lift Compressor Unit # 3 & # 4

Representative Compositional Analysis of Vented or Flared Natural Gas	
<i>Please provide the mole percent for the percentage questions in this group.</i>	
Methane (CH4) percentage	77
Nitrogen (N2) percentage, if greater than one percent	2
Hydrogen Sulfide (H2S) PPM, rounded up	0
Carbon Dioxide (CO2) percentage, if greater than one percent	0
Oxygen (O2) percentage, if greater than one percent	0
<i>If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.</i>	
Methane (CH4) percentage quality requirement	Not answered.
Nitrogen (N2) percentage quality requirement	Not answered.
Hydrogen Sulfide (H2S) PPM quality requirement	Not answered.
Carbon Dioxide (CO2) percentage quality requirement	Not answered.
Oxygen (O2) percentage quality requirement	Not answered.

Date(s) and Time(s)	
Date venting and/or flaring was discovered or commenced	08/23/2021
Time venting and/or flaring was discovered or commenced	12:49 PM
Time venting and/or flaring was terminated	01:04 PM
Cumulative hours during this event	0

Measured or Estimated Volume of Vented or Flared Natural Gas	
Natural Gas Vented (Mcf) Details	Not answered.

Natural Gas Flared (Mcf) Details	Cause: Other Other (Specify) Natural Gas Flared Released: 114 Mcf Recovered: 0 Mcf Lost: 114 Mcf]
Other Released Details	Not answered.
Additional details for Measured or Estimated Volume(s). Please specify	Gas Flare Meter
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.

Venting or Flaring Resulting from Downstream Activity	
Was or is this venting and/or flaring a result of downstream activity	No
Date notified of downstream activity requiring this venting and/or flaring	Not answered.
Time notified of downstream activity requiring this venting and/or flaring	Not answered.

Steps and Actions to Prevent Waste	
For this event, the operator could not have reasonably anticipated the current event and it was beyond the operator's control.	True
Please explain reason for why this event was beyond your operator's control	See Justification Form >The emissions event was caused by the unforeseen, unexpected, sudden, and unavoidable breakdown of equipment or process that was beyond the owner/operator's control, and did not stem from activity that could have been foreseen and avoided, and could not have been avoided by good design, operation, and preventative maintenance practices. It is OXY's policy to route all stranded sales gas to a flare during an unforeseen and unavoidable emergency or malfunction, in order to minimize emissions as much as possible. The flare is regularly monitored to the ensure flame is lit and meeting opacity requirements.
Steps taken to limit the duration and magnitude of venting and/or flaring	See Justification Form > The steps take to limit the duration of this flaring was for Oxy techs to quickly finish installing the gauges on gas lift compressor unit # 4, and then restart the unit in order to have flaring cease. As stated above, Oxy production techs attempted to restart gas compressor unit #3 while the maintenance techs began procedures to shut down gas lift compressor unit # 4 to perform the same gauge installation work. The techs assumed that gas compressor unit # 3 would restart, but after several attempts, a call was made to the compressor owner to send out a compressor mechanic. With both gas lift compressor units down, the volume of gas overwhelmed the compression equipment and stranded gas was routed to flare. Oxy techs worked very quickly to finish installing the gauges on gas lift compressor unit # 4, and then restarted the unit, which caused flaring to cease a few minutes later, once gas lift compressor unit was working at normal working service. Flaring did not occur until both units were down, which cause excess gas to overwhelm the remaining compression equipment, yet Oxy techs worked diligently and efficiently to complete their work, and restart compressor unit # 4. USA compressor mechanic arrived soon, and was able to troubleshoot the unit, and get gas lift compressor unit # 3 started and back to working service, yet flaring had ceased once gas lift compressor unit #4 was restarted.
Corrective actions taken to eliminate the cause and reoccurrence of venting and/or flaring	See Justification Form > Oxy cannot take any corrective actions to eliminate the cause and potential reoccurrence of compressor malfunctions as notwithstanding proper gas compressor design and operation, various forms of mechanical or technical issues can be sudden, reasonably unforeseeable and unexpected which can cause compressor unit malfunctions to occur without warning or advance notice. Oxy continually strives to maintain and operate its facility equipment in a manner consistent with good practices for minimizing emissions and reducing the number of emission events. Oxy has a strong and positive compression equipment preventative maintenance program in place. This incident was completely out of OXY's control to foresee, avoid or prevent from happening. OXY made every effort to control and minimize emissions as much as possible during this event. The only actions that Oxy can take and handle that is within its control, is to keep continue with its compression equipment preventative maintenance program for this facility.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 46465

CONDITIONS

Operator: OXY USA WTP LIMITED PARTNERSHIP P.O. Box 4294 Houston, TX 772104294	OGRID: 192463
	Action Number: 46465
	Action Type: [C-129] Venting and/or Flaring (C-129)

CONDITIONS

Created By	Condition	Condition Date
marialuna	If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event.	9/6/2021