



Certificate of Analysis

Number: 6030-25010237-001A

Artesia Laboratory

200 E Main St.

Artesia, NM 88210

Phone 575-746-3481

Chandler Montgomery
Occidental Petroleum
1502 W Commerce Dr.
Carlsbad, NM 88220

Field:	PERMIAN_RESOURCES	Report Date:	01/19/2025
Station Name:	Sand Dunes CTB Check	Sampled By:	CG
Station Number:	17000C	Sample Of:	Gas
Station Location:	OP-L0901-BT002	Sample Type:	Spot
Sample Point:	Meter	Sample Conditions:	125 psig, @ 62 °F Ambient: 43 °F
Property ID:	FMP/LSE NM40659	Sample Date:	01/13/2025 01:45
Formation:	NEW_MEXICO	Received Date:	01/14/2025
County:		Login Date:	01/14/2025
Well Name:	CTB	Effective Date:	01/01/2025
Type of Sample :	Spot-Cylinder	Flow Rate:	34819 MSCFD
Sampling Company:	SPL - OXY	Sampling Method:	Purge/Fill Vacuum
Heat Trace Used:	N/A	Heating Method:	
Last Inst. Cal.:	01/13/2025 08:04:58	Method:	GPA-2261M
Analyzed:	01/15/2025 11:37:09 by CDW	Cylinder No:	9999-005126
		Instrument:	70142339 (Inficon GC-MicroFusion)

Analytical Data

Components	Un-normalized Mol %	Mol. %	Wt. %	GPM at 14.65 psia		
Hydrogen Sulfide	0.0000	0.0000	0.0000		GPM TOTAL C2+	6.669
Nitrogen	1.2226	1.2114	1.5246		GPM TOTAL C3+	3.389
Methane	75.4281	74.7368	53.8641		GPM TOTAL iC5+	0.655
Carbon Dioxide	0.6516	0.6456	1.2764			
Ethane	12.3989	12.2852	16.5957	3.280		
Propane	6.3610	6.3027	12.4858	1.733		
Iso-butane	0.9604	0.9516	2.4848	0.311		
n-Butane	2.2123	2.1920	5.7237	0.690		
Iso-pentane	0.5013	0.4967	1.6100	0.181		
n-Pentane	0.5305	0.5256	1.7036	0.190		
Hexanes Plus	0.6584	0.6524	2.7313	0.284		
	100.9251	100.0000	100.0000	6.669		

Calculated Physical Properties	Total	C6+
Relative Density Real Gas	0.7714	3.2176
Calculated Molecular Weight	22.26	93.19
Compressibility Factor	0.9960	
GPA 2172 Calculation:		
Calculated Gross BTU per ft³ @ 14.65 psia & 60°F		
Real Gas Dry BTU	1309	5113
Water Sat. Gas Base BTU	1287	5024
Ideal, Gross HV - Dry at 14.65 psia	1303.6	5113.2
Ideal, Gross HV - Wet	1280.8	5023.7
Net BTU Dry Gas - real gas	1189	
Net BTU Wet Gas - real gas	1169	

Comments: H2S Field Content: 0 %

Hydrocarbon Laboratory Manager

Quality Assurance: The above analyses are performed in accordance with ASTM, UOP, GPA guidelines for quality assurance, unless otherwise stated. The test results apply to the sample as received.

**UPSET FLARING EVENT SPECIFIC JUSTIFICATIONS FORM****Facility Id#** fAPP2127048458**Operator:** OXY USA, Inc.**Facility:** Sand Dunes South Corridor CTB**Flare Date:** 06/25/2025**Duration of Event:** 40 Minutes**MCF Flared:** 887**Start Time:** 12:41 AM**End Time:** 01:21 AM**Cause:** Emergency Flare > Third Party Downstream Activity > Enterprise > Central Station > Operational Issues**Method of Flared Gas Measurement:** Gas Flare Meter**1. Reason why this event was beyond Operator's control:**

The emissions event was caused by the unforeseen, unexpected, sudden, and unavoidable interruption, restriction or complete shut-in of a gas pipeline by a third-party pipeline compressor station operator, which impacted Oxy's ability to send gas to them. This interruption, restriction or complete shut-in of the gas pipeline by a third-party pipeline compression station operator is downstream of Oxy's custody transfer point and out of Oxy's control to foresee, avoid or prevent from happening and did not stem from any of Oxy's upstream facility activity that could have been foreseen and avoided, and could not have been avoided by good design, operation, and preventative maintenance practices. In this case, flaring occurred due to an unexpected emergency shutdown, which resulted in an unannounced stoppage of sales gas flow intake from OXY by Enterprise operations. This emergency shutdown originated from Enterprise, a third-party downstream offloading operator, who was experiencing operational difficulties at their Central Station. Although Oxy strived to keep communication channels open with Enterprise personnel, there was no dialogue regarding the sales gas intake stoppage and/or emergency shutdown that happened on their end, until after their emergency shutdown had occurred. This lack of communication significantly hindered Oxy's ability and capacity to prevent flaring from occurring. Oxy's field and operations teams diligently oversee the facility to swiftly identify any deviations from standard operational parameters. Nevertheless, Enterprise did not provide any advance warning to the personnel at Oxy regarding continual potential stoppages of sales gas flow intake. If Enterprise had provided prior notification to Oxy personnel, field and operation personnel would have adjusted and balanced the wells to reduce the amount of gas being sent to the facility and to sales, which in turn would have mitigated the chances of flaring events from occurring. Although flaring is not OXY's preferred method for handling excess gas, it is necessary to ensure the safety of our operations, equipment, and field personnel. The occurrence of this event was beyond OXY's control.

2. Steps Taken to limit duration and magnitude of venting or flaring:

It is OXY's policy to route its stranded gas to a flare during an unforeseen and unavoidable emergency or malfunction, that is beyond Oxy's control to avoid, prevent or foresee, to minimize emissions as much as possible as part of the overall steps taken to limit duration and magnitude of flaring. The flare at this facility has a 98% combustion efficiency to lessen emissions as much as possible. In this case, flaring occurred due to an unexpected emergency shutdown, which resulted in an unannounced stoppage of sales gas flow intake from OXY by Enterprise operations. This emergency shutdown originated from Enterprise, a third-party downstream offloading operator, who was experiencing operational difficulties at their Central Station. Although Oxy strived to keep communication channels open with Enterprise personnel, there was no dialogue regarding the sales gas intake stoppage and/or emergency shutdown that happened on their end, until after their emergency shutdown had occurred. This lack of communication significantly hindered Oxy's ability and capacity to prevent flaring from

occurring. Oxy's field and operations teams diligently oversee the facility to swiftly identify any deviations from standard operational parameters. Nevertheless, Enterprise did not provide any advance warning to the personnel at Oxy regarding continual potential stoppages of sales gas flow intake. If Enterprise had provided prior notification to Oxy personnel, field and operation personnel would have adjusted and balanced the wells to reduce the amount of gas being sent to the facility and to sales, which in turn would have mitigated the chances of flaring events from occurring. Although flaring is not OXY's preferred method for handling excess gas, it is necessary to ensure the safety of our operations, equipment, and field personnel. The occurrence of this event was beyond OXY's control. As soon as flaring was triggered, Oxy production techs choked back several wells and the field area's mitigation optimizers cut injection rates to wells in the field to reduce injection and sales gas across the area so that field pressure would stay below the flare trigger setpoints of the facility to cease flaring. The occurrence of this event was beyond OXY's control. OXY took all possible measures to manage and reduce emissions to the greatest extent.

3. Corrective Actions taken to eliminate the cause and reoccurrence of venting or flaring:

Oxy is not in a position to implement corrective measures to address the root cause and prevent future incidents of a gas flow restriction, shut-in or suspension in the Enterprise offload sales gas pipeline, since this matter is beyond Oxy's custody transfer point and outside of Oxy's capacity to correct or keep from happening again. When Enterprise and its operations encounter operational or equipment issues or have difficulty managing the sales gas transmission flow volume from Oxy inefficiently, Enterprise then restricts Oxy's ability to proceed with its sales gas transmission. Oxy is committed to minimizing emissions as much as possible and aims to maintain open communication with its downstream and midstream operators, when feasible, to handle such events effectively.

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

DEFINITIONS

Action 483952

DEFINITIONS

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 483952
	Action Type: [C-129] Amend Venting and/or Flaring (C-129A)

DEFINITIONS

<p>For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application:</p> <ul style="list-style-type: none">• this application's operator, hereinafter "this operator";• venting and/or flaring, hereinafter "vent or flare";• any notification or report(s) of the C-129 form family, hereinafter "any C-129 forms";• the statements in (and/or attached to) this, hereinafter "the statements in this";• and the past tense will be used in lieu of mixed past/present tense questions and statements.

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 483952

QUESTIONS

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 483952
	Action Type: [C-129] Amend Venting and/or Flaring (C-129A)

QUESTIONS

Prerequisites	
<i>Any messages presented in this section, will prevent submission of this application. Please resolve these issues before continuing with the rest of the questions.</i>	
Incident ID (n#)	Unavailable.
Incident Name	Unavailable.
Incident Type	Flare
Incident Status	Unavailable.
Incident Facility	[fAPP2127048458] Sand Dunes South Corridor CTB
<i>Only valid Vent, Flare or Vent with Flaring incidents (selected above in the Application Details section) that are assigned to your current operator can be amended with this C-129A application.</i>	

Determination of Reporting Requirements	
<i>Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide additional guidance.</i>	
Was this vent or flare caused by an emergency or malfunction	Yes
Did this vent or flare last eight hours or more cumulatively within any 24-hour period from a single event	No
Is this considered a submission for a vent or flare event	Yes, major venting and/or flaring of natural gas.
<i>An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during venting and/or flaring that is or may be a major or minor release under 19.15.29.7 NMAC.</i>	
Was there at least 50 MCF of natural gas vented and/or flared during this event	Yes
Did this vent or flare result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No
Was the vent or flare within an incorporated municipal boundary or within 300 feet from an occupied permanent residence, school, hospital, institution or church in existence	No

Equipment Involved	
Primary Equipment Involved	Other (Specify)
Additional details for Equipment Involved. Please specify	Emergency Flare > Third Party Downstream Activity > Enterprise > Central Station > Operational Issues

Representative Compositional Analysis of Vented or Flared Natural Gas	
<i>Please provide the mole percent for the percentage questions in this group.</i>	
Methane (CH4) percentage	75
Nitrogen (N2) percentage, if greater than one percent	1
Hydrogen Sulfide (H2S) PPM, rounded up	0
Carbon Dioxide (CO2) percentage, if greater than one percent	1
Oxygen (O2) percentage, if greater than one percent	0
<i>If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.</i>	
Methane (CH4) percentage quality requirement	Not answered.
Nitrogen (N2) percentage quality requirement	Not answered.
Hydrogen Sulfide (H2S) PPM quality requirement	Not answered.
Carbon Dioxide (CO2) percentage quality requirement	Not answered.
Oxygen (O2) percentage quality requirement	Not answered.

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS, Page 2

Action 483952

QUESTIONS (continued)

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 483952
	Action Type: [C-129] Amend Venting and/or Flaring (C-129A)

QUESTIONS

Date(s) and Time(s)	
Date vent or flare was discovered or commenced	06/25/2025
Time vent or flare was discovered or commenced	12:41 AM
Time vent or flare was terminated	01:21 AM
Cumulative hours during this event	1

Measured or Estimated Volume of Vented or Flared Natural Gas	
Natural Gas Vented (Mcf) Details	Not answered.
Natural Gas Flared (Mcf) Details	Cause: Other Other (Specify) Natural Gas Flared Released: 887 Mcf Recovered: 0 Mcf Lost: 887 Mcf.
Other Released Details	Not answered.
Additional details for Measured or Estimated Volume(s). Please specify	Gas Flare Meter
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.

Venting or Flaring Resulting from Downstream Activity	
Was this vent or flare a result of downstream activity	Yes
Was notification of downstream activity received by this operator	No
Downstream OGRID that should have notified this operator	[713731] Enterprise Crude Pipeline LLC
Date notified of downstream activity requiring this vent or flare	
Time notified of downstream activity requiring this vent or flare	Not answered.

Steps and Actions to Prevent Waste	
For this event, this operator could not have reasonably anticipated the current event and it was beyond this operator's control	True
Please explain reason for why this event was beyond this operator's control	The emissions event was caused by the unforeseen, unexpected, sudden, and unavoidable interruption, restriction or complete shut-in of a gas pipeline by a third-party pipeline compressor station operator, which impacted Oxy's ability to send gas to them. This interruption, restriction or complete shut-in of the gas pipeline by a third-party pipeline compression station operator is downstream of Oxy's custody transfer point and out of Oxy's control to foresee, avoid or prevent from happening and did not stem from any of Oxy's upstream facility activity that could have been foreseen and avoided, and could not have been avoided by good design, operation, and preventative maintenance practices. In this case, flaring occurred due to an unexpected emergency shutdown, which resulted in an unannounced stoppage of sales gas flow intake from OXY by Enterprise operations. This emergency shutdown originated from Enterprise, a third-party downstream offloading operator, who was experiencing operational difficulties at their Central Station. Although Oxy strived to keep communication channels open with Enterprise personnel, there was no dialogue regarding the sales gas intake stoppage and/or emergency shutdown that happened on their end, until after their emergency shutdown had occurred. This lack of communication significantly hindered Oxy's ability and capacity to prevent flaring from occurring. Oxy's field and operations teams diligently oversee the facility to swiftly identify any deviations from standard operational parameters. Nevertheless, Enterprise did not provide any advance warning to the personnel at Oxy regarding continual potential stoppages of sales gas flow intake. If Enterprise had provided prior notification to Oxy personnel, field and operation personnel would have adjusted and balanced the wells to reduce the amount of

	gas being sent to the facility and to sales, which in turn would have mitigated the chances of flaring events from occurring.
Steps taken to limit the duration and magnitude of vent or flare	<p>It is OXY's policy to route its stranded gas to a flare during an unforeseen and unavoidable emergency or malfunction, that is beyond Oxy's control to avoid, prevent or foresee, to minimize emissions as much as possible as part of the overall steps taken to limit duration and magnitude of flaring. The flare at this facility has a 98% combustion efficiency to lessen emissions as much as possible. In this case, flaring occurred due to an unexpected emergency shutdown, which resulted in an unannounced stoppage of sales gas flow intake from OXY by Enterprise operations. This emergency shutdown originated from Enterprise, a third-party downstream offloading operator, who was experiencing operational difficulties at their Central Station. Although Oxy strived to keep communication channels open with Enterprise personnel, there was no dialogue regarding the sales gas intake stoppage and/or emergency shutdown that happened on their end, until after their emergency shutdown had occurred. This lack of communication significantly hindered Oxy's ability and capacity to prevent flaring from occurring. Oxy's field and operations teams diligently oversee the facility to swiftly identify any deviations from standard operational parameters. Nevertheless, Enterprise did not provide any advance warning to the personnel at Oxy regarding continual potential stoppages of sales gas flow intake. If Enterprise had provided prior notification to Oxy personnel, field and operation personnel would have adjusted and balanced the wells to reduce the amount of gas being sent to the facility and to sales, which in turn would have mitigated the chances of flaring events from occurring. Although flaring is not OXY's preferred method for handling excess gas, it is necessary to ensure the safety of our operations, equipment, and field personnel. The occurrence of this event was beyond OXY's control. As soon as flaring was triggered,</p>
Corrective actions taken to eliminate the cause and reoccurrence of vent or flare	<p>Oxy is not in a position to implement corrective measures to address the root cause and prevent future incidents of a gas flow restriction, shut-in or suspension in the Enterprise offload sales gas pipeline, since this matter is beyond Oxy's custody transfer point and outside of Oxy's capacity to correct or keep from happening again. When Enterprise and its operations encounter operational or equipment issues or have difficulty managing the sales gas transmission flow volume from Oxy inefficiently, Enterprise then restricts Oxy's ability to proceed with its sales gas transmission. Oxy is committed to minimizing emissions as much as possible and aims to maintain open communication with its downstream and midstream operators, when feasible, to handle such events effectively.</p>

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

ACKNOWLEDGMENTS

Action 483952

ACKNOWLEDGMENTS

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 483952
	Action Type: [C-129] Amend Venting and/or Flaring (C-129A)

ACKNOWLEDGMENTS

<input checked="" type="checkbox"/>	I acknowledge that with this application I will be amending an existing incident file (assigned to this operator) for a vent or flare event, pursuant to 19.15.27 and 19.15.28 NMAC.
<input checked="" type="checkbox"/>	I acknowledge that amending an incident file does not replace original submitted application(s) or information and understand that any C-129 forms submitted to the OCD will be logged and stored as public record.
<input checked="" type="checkbox"/>	I hereby certify the statements in this amending report are true and correct to the best of my knowledge and acknowledge that any false statement may be subject to civil and criminal penalties under the Oil and Gas Act.
<input checked="" type="checkbox"/>	I acknowledge that the acceptance of any C-129 forms by the OCD does not relieve this operator of liability should their operations have failed to adequately investigate, report, and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment.
<input checked="" type="checkbox"/>	I acknowledge that OCD acceptance of any C-129 forms does not relieve this operator of responsibility for compliance with any other applicable federal, state, or local laws and/or regulations.

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 483952

CONDITIONS

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 483952
	Action Type: [C-129] Amend Venting and/or Flaring (C-129A)

CONDITIONS

Created By	Condition	Condition Date
marialuna2	If the information provided in this report requires further amendment(s), submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event.	7/10/2025