| Office State of New Mexico | Form C-103 ¹ |
|--|--|
| District I – (575) 393-6161 Energy, Minerals and Natural Resou | rces Revised August 1, 2011 WELL API NO. |
| 1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283 | 20.025.07523 |
| 811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION | ON 50 023 07325 5. Indicate Type of Lease |
| District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 | STATE FEE |
| <u>District IV</u> – (505) 476-3460 Santa Fe, NM 8/505 1220 S. St. Francis Dr., Santa Fe, NM | 6. State Oil & Gas Lease No. 19552 |
| 87505 SUNDRY NOTICES AND REPORTS ON WELLS | 7. Lease Name or Unit Agreement Name |
| (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK T DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) | |
| 1. Type of Well: Oil Well Gas Well Other: INJECTOR | 8. Well Number: 141 |
| 2. Name of Operator Occidental Permian Ltd. | 9. OGRID Number: 157984 |
| 3. Address of Operator | 10. Pool name or Wildcat |
| HCR 1 Box 90 Denver City, TX 79323 | Hobbs (G/SA) |
| 4. Well Location | 220 fort form the WEST Line |
| Unit Letter M : 330 feet from the South line and | |
| Section 32 Township 18-S Range 11. Elevation (Show whether DR, RKB, RT, | 38-E NMPM Lea County |
| 3633' (KB) | , GK, etc.) |
| | · |
| 12. Check Appropriate Box to Indicate Nature of | Notice, Report or Other Data |
| ALOTICE OF INTENTION TO | CURCEOUENT REPORT OF |
| NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☑ PLUG AND ABANDON ☐ REMEDI | SUBSEQUENT REPORT OF: ALTERING CASING |
| | NCE DRILLING OPNS. P AND A |
| | |
| | CEMENT JOB |
| DOWNHOLE COMMINGLE | CEMENT JOB |
| | |
| DOWNHOLE COMMINGLE OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent d | letails, and give pertinent dates, including estimated date |
| DOWNHOLE COMMINGLE OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent d of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Mu | letails, and give pertinent dates, including estimated date |
| DOWNHOLE COMMINGLE OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent d | letails, and give pertinent dates, including estimated date |
| DOWNHOLE COMMINGLE OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent d of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Mu proposed completion or recompletion. | letails, and give pertinent dates, including estimated date |
| DOWNHOLE COMMINGLE OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent d of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Mu proposed completion or recompletion. POOH with injection equipment Solution in the completion of the complet | letails, and give pertinent dates, including estimated date altiple Completions: Attach wellbore diagram of |
| DOWNHOLE COMMINGLE OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent d of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Mu proposed completion or recompletion. POOH with injection equipment Solution is set CIBP (a) ~ 4000' Solution is set CIBP (a) ~ 4050' cap it with 5' of cement to 4045' | letails, and give pertinent dates, including estimated date altiple Completions: Attach wellbore diagram of |
| DOWNHOLE COMMINGLE OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent d of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Mu proposed completion or recompletion. POOH with injection equipment Set CIBP @ ~4000' Set CIBP @ ~4050' cap it with 5' of cement to 4045' RIH and set CICR at +/- 3900', | letails, and give pertinent dates, including estimated date altiple Completions: Attach wellbore diagram of During this procedure we plan to use the closed-loop system with a steel |
| DOWNHOLE COMMINGLE OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent d of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Mu proposed completion or recompletion. 1. POOH with injection equipment 2. Isolate casing leak @ ~ 4000' 3. Set CIBP @ ~4050' cap it with 5' of cement to 4045' 4. RIH and set CICR at +/- 3900', | During this procedure we plan to use the closed-loop system with a steel tank and haul contents to the required |
| OTHER: Isolate and proposed or completed operations. (Clearly state all pertinent dof starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Murproposed completion or recompletion. POOH with injection equipment Isolate casing leak @ ~ 4000' Set CIBP @ ~4050' cap it with 5' of cement to 4045' RIH and set CICR at +/- 3900', Cement Sqz leak qith ~ 100 sx of thixotropic cement blend following with 30 sx of class C cement w / 2% calcium chlorite RIH with 4-3/4" bit and clean out to 4045, test sqz. | letails, and give pertinent dates, including estimated date altiple Completions: Attach wellbore diagram of During this procedure we plan to use the closed-loop system with a steel |
| DOWNHOLE COMMINGLE OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent d of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Mu proposed completion or recompletion. 1. POOH with injection equipment 1. Isolate casing leak @ ~ 4000' 13. Set CIBP @ ~4050' cap it with 5' of cement to 4045' 14. RIH and set CICR at +/- 3900', 15. Cement Sqz leak qith ~ 100 sx of thixotropic cement blend following with 30 sx of class C cement w / 2% calcium chlorite 15. RIH with 4-3/4" bit and clean out to 4045, test sqz. 16. Continue Co to PBTD @ 4270' POOH with bit | During this procedure we plan to use the closed-loop system with a steel tank and haul contents to the required |
| OTHER: Isolate all pertinent dof starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Mu proposed completion or recompletion. POOH with injection equipment Isolate casing leak @ ~ 4000' Set CIBP @ ~4050' cap it with 5' of cement to 4045' RIH and set CICR at +/- 3900', Cement Sqz leak qith ~ 100 sx of thixotropic cement blend following with 30 sx of class C cement w / 2% calcium chlorite RIH with 4-3/4" bit and clean out to 4045, test sqz. Continue Co to PBTD @ 4270' POOH with bit RIH with injection equipment | During this procedure we plan to use the closed-loop system with a steel tank and haul contents to the required disposal per ODC Rule 19.15.17 |
| OTHER: Isolate all pertinent dof starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Mu proposed completion or recompletion. POOH with injection equipment Isolate casing leak @ ~ 4000' Set CIBP @ ~4050' cap it with 5' of cement to 4045' RIH and set CICR at +/- 3900', Cement Sqz leak qith ~ 100 sx of thixotropic cement blend following with 30 sx of class C cement w / 2% calcium chlorite RIH with 4-3/4" bit and clean out to 4045, test sqz. Continue Co to PBTD @ 4270' POOH with bit RIH with injection equipment | During this procedure we plan to use the closed-loop system with a steel tank and haul contents to the required disposal per ODC Rule 19.15.17 |
| OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent d of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Mu proposed completion or recompletion. 1. POOH with injection equipment 2. Isolate casing leak @ ~ 4000' 3. Set CIBP @ ~4050' cap it with 5' of cement to 4045' 4. RIH and set CICR at +/- 3900', 5. Cement Sqz leak qith ~ 100 sx of thixotropic cement blend following with 30 sx of class C cement w / 2% calcium chlorite 6. RIH with 4-3/4" bit and clean out to 4045, test sqz. 7. Continue Co to PBTD @ 4270' POOH with bit 8. RIH with injection equipment 9. Run MIT and place well back to services | During this procedure we plan to use the closed-loop system with a steel tank and haul contents to the required disposal per ODC Rule 19.15.17 Condition of Approval: notify |
| OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent d of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Mu proposed completion or recompletion. POOH with injection equipment Isolate casing leak @ ~ 4000' Set CIBP @ ~4050' cap it with 5' of cement to 4045' RIH and set CICR at +/- 3900', Cement Sqz leak qith ~ 100 sx of thixotropic cement blend following with 30 sx of class C cement w / 2% calcium chlorite RIH with 4-3/4" bit and clean out to 4045, test sqz. Continue Co to PBTD @ 4270' POOH with bit RIH with injection equipment Run MIT and place well back to services | During this procedure we plan to use the closed-loop system with a steel tank and haul contents to the required disposal per ODC Rule 19.15.17 Condition of Approval: notify OCD Hobbs office 24 hours |
| OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent d of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Mu proposed completion or recompletion. POOH with injection equipment Isolate casing leak @ ~ 4000' Set CIBP @ ~4050' cap it with 5' of cement to 4045' RIH and set CICR at +/- 3900', Cement Sqz leak qith ~ 100 sx of thixotropic cement blend following with 30 sx of class C cement w / 2% calcium chlorite RIH with 4-3/4" bit and clean out to 4045, test sqz. Continue Co to PBTD @ 4270' POOH with bit RIH with injection equipment Run MIT and place well back to services | During this procedure we plan to use the closed-loop system with a steel tank and haul contents to the required disposal per ODC Rule 19.15.17 Condition of Approval: notify |
| OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent d of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Mu proposed completion or recompletion. 1. POOH with injection equipment 2. Isolate casing leak @ ~ 4000' 3. Set CIBP @ ~4050' cap it with 5' of cement to 4045' 4. RIH and set CICR at +/- 3900', 5. Cement Sqz leak qith ~ 100 sx of thixotropic cement blend following with 30 sx of class C cement w / 2% calcium chlorite 6. RIH with 4-3/4" bit and clean out to 4045, test sqz. 7. Continue Co to PBTD @ 4270' POOH with bit 8. RIH with injection equipment 9. Run MIT and place well back to services Spud Date: Rig Release Date: | During this procedure we plan to use the closed-loop system with a steel tank and haul contents to the required disposal per ODC Rule 19.15.17 Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart |
| OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent d of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Mu proposed completion or recompletion. 1. POOH with injection equipment 2. Isolate casing leak @ ~ 4000' 3. Set CIBP @ ~4050' cap it with 5' of cement to 4045' 4. RIH and set CICR at +/- 3900', 5. Cement Sqz leak qith ~ 100 sx of thixotropic cement blend following with 30 sx of class C cement w / 2% calcium chlorite 6. RIH with 4-3/4" bit and clean out to 4045, test sqz. 7. Continue Co to PBTD @ 4270' POOH with bit 8. RIH with injection equipment 9. Run MIT and place well back to services Spud Date: Rig Release Date: | During this procedure we plan to use the closed-loop system with a steel tank and haul contents to the required disposal per ODC Rule 19.15.17 Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart |
| OTHER: OTHER: | During this procedure we plan to use the closed-loop system with a steel tank and haul contents to the required disposal per ODC Rule 19.15.17 Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart knowledge and belief. |
| OTHER: OTHER: | During this procedure we plan to use the closed-loop system with a steel tank and haul contents to the required disposal per ODC Rule 19.15.17 Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart knowledge and belief. |
| OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent d of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Mu proposed completion or recompletion. 1. POOH with injection equipment 2. Isolate casing leak @ ~ 4000' 3. Set CIBP @ ~4050' cap it with 5' of cement to 4045' 4. RIH and set CICR at +/- 3900', 5. Cement Sqz leak qith ~ 100 sx of thixotropic cement blend following with 30 sx of class C cement w / 2% calcium chlorite 6. RIH with 4-3/4" bit and clean out to 4045, test sqz. 7. Continue Co to PBTD @ 4270' POOH with bit 8. RIH with injection equipment 9. Run MIT and place well back to services | During this procedure we plan to use the closed-loop system with a steel tank and haul contents to the required disposal per ODC Rule 19.15.17 Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart knowledge and belief. |
| OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent d of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Mu proposed completion or recompletion. 1. POOH with injection equipment 2. Isolate casing leak @ ~ 4000' 3. Set CIBP @ ~4050' cap it with 5' of cement to 4045' 4. RIH and set CICR at +/- 3900', 5. Cement Sqz leak qith ~ 100 sx of thixotropic cement blend following with 30 sx of class C cement w / 2% calcium chlorite 6. RIH with 4-3/4" bit and clean out to 4045, test sqz. 7. Continue Co to PBTD @ 4270' POOH with bit 8. RIH with injection equipment 9. Run MIT and place well back to services Spud Date: Rig Release Date: TITLE Production Engine | During this procedure we plan to use the closed-loop system with a steel tank and haul contents to the required disposal per ODC Rule 19.15.17 Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart Knowledge and belief. |
| DOWNHOLE COMMINGLE OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent d of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Mu proposed completion or recompletion. 1. POOH with injection equipment 2. Isolate casing leak @ ~ 4000' 3. Set CIBP @ ~4050' cap it with 5' of cement to 4045' 4. RIH and set CICR at +/- 3900', 5. Cement Sqz leak qith ~ 100 sx of thixotropic cement blend following with 30 sx of class C cement w / 2% calcium chlorite 6. RIH with 4-3/4" bit and clean out to 4045, test sqz. 7. Continue Co to PBTD @ 4270' POOH with bit 8. RIH with injection equipment 9. Run MIT and place well back to services Spud Date: Rig Release Date: Otherwise Production Engine Type or print name Carlos Restrepo E-mail address carlos restreption of the starting any proposed work). See the starting any proposed complete to the best of my known and the starting any proposed complete to the best of my known and the starting any proposed work). See the starting any proposed work of the starting any proposed work). See the starting and proposed work of the starting and prop | During this procedure we plan to use the closed-loop system with a steel tank and haul contents to the required disposal per ODC Rule 19.15.17 Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart Condition of Approval: notify OCD Hobbs office 24 hours PHONE: 12/10/2020 |

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III
1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 12907

CONDITIONS OF APPROVAL

| Operator: | | | OGRID: | Action Number: | Action Type: |
|------------------------|---------------|----------------------|--------|----------------|--------------|
| OCCIDENTAL PERMIAN LTD | P.O. Box 4294 | Houston, TX772104294 | 157984 | 12907 | C-103X |

| OCD Reviewer | Condition |
|--------------|----------------------------|
| kfortner | Run Post workover MIT test |