

Office <u>District I</u> – (575) 393-6161	State of New Mexico	Form C-103*
	Energy, Minerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	30-025-40954
<u>District III</u> – (505) 334-6178	1220 South St. Francis Dr.	5. Indicate Type of Lease STATE FEE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	,	o. State on & Gas Lease 140.
87505	a the benong on the a	
	S AND REPORTS ON WELLS S TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name Corazon State Unit
	TON FOR PERMIT" (FORM C-101) FOR SUCH	
PROPOSALS.)		8. Well Number #12H
	s Well Other	O OCRUP N. 1
2. Name of Operator COG Operating, LLC		9. OGRID Number 229137
3. Address of Operator		10. Pool name or Wildcat
2208 W. Main Street Artesia, NM 88	3210	Wildcat G-08 S213304D; Bone Spring
4. Well Location	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	, , nature of the series is, some spring
	fact from the N line and 250	0 feet from the E line
-	feet from the N line and 259	
	1	MPM County Lea
1	1. Elevation (Show whether DR, RKB, RT, GR, et 3801' GR	(c.)
	3801 GR	
12 Clarata A		Daniel of Other Date
12. Check App	propriate Box to Indicate Nature of Notice	e, Report or Other Data
NOTICE OF INTE	NTION TO:	BSEQUENT REPORT OF:
	PLUG AND ABANDON 🛛 REMEDIAL WO	
		RILLING OPNS. P AND A
PULL OR ALTER CASING N	MULTIPLE COMPL	NT JOB
DOWNHOLE COMMINGLE		
CLOSED-LOOP SYSTEM	_	_
OTHER:	OTHER:	
12 D		
of starting any proposed work)	. SEE RULE 19.15.7.14 NMAC. For Multiple C	
	. SEE RULE 19.15.7.14 NMAC. For Multiple C	
of starting any proposed work) proposed completion or recom	. SEE RULE 19.15.7.14 NMAC. For Multiple C pletion.	
of starting any proposed work) proposed completion or recom 1. Tag Top of Fish @ 8507	. SEE RULE 19.15.7.14 NMAC. For Multiple C pletion.	Completions: Attach wellbore diagram of
of starting any proposed work) proposed completion or recom 1. Tag Top of Fish @ 8507' 2. Set 5 ½" CIBP @ 8457'. 3. Perf & Sqz 50 sx cmt @	. SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. Circ hole w/ MLF. Pressure test csg. Spot 25 ss 5545-5345'. WOC & Tag (9 5/8" Shoe)	completions: Attach wellbore diagram of ccmt @ 8457-8257'.
of starting any proposed work) proposed completion or recom 1. Tag Top of Fish @ 8507' 2. Set 5 ½" CIBP @ 8457'. 3. Perf & Sqz 50 sx cmt @ 4. Spot 210 sx cmt @ 4029	. SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. Circ hole w/ MLF. Pressure test csg. Spot 25 ss 5545-5345'. WOC & Tag (9 5/8" Shoe) -1914'. WOC & Tag (DV Tool, B/Salt)	completions: Attach wellbore diagram of comt @ 8457-8257'. ***R-111-P POTASH AREA***
of starting any proposed work) proposed completion or recom 1. Tag Top of Fish @ 8507' 2. Set 5 ½" CIBP @ 8457'. 3. Perf & Sqz 50 sx cmt @ 4. Spot 210 sx cmt @ 4029 5. Perf & Sqz 50 sx cmt @	SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. Circ hole w/ MLF. Pressure test csg. Spot 25 st 5545-5345'. WOC & Tag (9 5/8" Shoe) -1914'. WOC & Tag (DV Tool, B/Salt) 1914-1714'. WOC & Tag (T/Salt & 13 3/8" Sho	completions: Attach wellbore diagram of comt @ 8457-8257'. ***R-111-P POTASH AREA***
of starting any proposed work) proposed completion or recom 1. Tag Top of Fish @ 8507' 2. Set 5 ½" CIBP @ 8457'. 3. Perf & Sqz 50 sx cmt @ 4. Spot 210 sx cmt @ 4029 5. Perf & Sqz 50 sx cmt @ 6. Spot 25 sx cmt @ 200' to	SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. Circ hole w/ MLF. Pressure test csg. Spot 25 st 5545-5345'. WOC & Tag (9 5/8" Shoe) -1914'. WOC & Tag (DV Tool, B/Salt) 1914-1714'. WOC & Tag (T/Salt & 13 3/8" Shoe surface.	completions: Attach wellbore diagram of comt @ 8457-8257'. ***R-111-P POTASH AREA***
of starting any proposed work) proposed completion or recom 1. Tag Top of Fish @ 8507' 2. Set 5 ½" CIBP @ 8457'. 3. Perf & Sqz 50 sx cmt @ 4. Spot 210 sx cmt @ 4029 5. Perf & Sqz 50 sx cmt @ 6. Spot 25 sx cmt @ 200' to	SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. Circ hole w/ MLF. Pressure test csg. Spot 25 st 5545-5345'. WOC & Tag (9 5/8" Shoe) -1914'. WOC & Tag (DV Tool, B/Salt) 1914-1714'. WOC & Tag (T/Salt & 13 3/8" Sho	completions: Attach wellbore diagram of comt @ 8457-8257'. ***R-111-P POTASH AREA***
of starting any proposed work) proposed completion or recom 1. Tag Top of Fish @ 8507' 2. Set 5 ½" CIBP @ 8457'. 3. Perf & Sqz 50 sx cmt @ 4. Spot 210 sx cmt @ 4029 5. Perf & Sqz 50 sx cmt @ 6. Spot 25 sx cmt @ 200' to 7. Cut off well head, verify	SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. Circ hole w/ MLF. Pressure test csg. Spot 25 st 5545-5345'. WOC & Tag (9 5/8" Shoe) -1914'. WOC & Tag (DV Tool, B/Salt) 1914-1714'. WOC & Tag (T/Salt & 13 3/8" Shoe surface. cmt @ surface, weld on Dry Hole Marker.	completions: Attach wellbore diagram of comple
of starting any proposed work) proposed completion or recom 1. Tag Top of Fish @ 8507' 2. Set 5 ½" CIBP @ 8457'. 3. Perf & Sqz 50 sx cmt @ 4. Spot 210 sx cmt @ 4029 5. Perf & Sqz 50 sx cmt @ 6. Spot 25 sx cmt @ 200' to 7. Cut off well head, verify	SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. Circ hole w/ MLF. Pressure test csg. Spot 25 st 5545-5345'. WOC & Tag (9 5/8" Shoe) -1914'. WOC & Tag (DV Tool, B/Salt) 1914-1714'. WOC & Tag (T/Salt & 13 3/8" Shoe surface.	completions: Attach wellbore diagram of comple
of starting any proposed work) proposed completion or recom 1. Tag Top of Fish @ 8507' 2. Set 5 ½" CIBP @ 8457'. 3. Perf & Sqz 50 sx cmt @ 4. Spot 210 sx cmt @ 4029 5. Perf & Sqz 50 sx cmt @ 6. Spot 25 sx cmt @ 200' to 7. Cut off well head, verify	SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. Circ hole w/ MLF. Pressure test csg. Spot 25 st 5545-5345'. WOC & Tag (9 5/8" Shoe) -1914'. WOC & Tag (DV Tool, B/Salt) 1914-1714'. WOC & Tag (T/Salt & 13 3/8" Shoe surface. cmt @ surface, weld on Dry Hole Marker.	completions: Attach wellbore diagram of comple
of starting any proposed work) proposed completion or recom 1. Tag Top of Fish @ 8507' 2. Set 5 ½" CIBP @ 8457'. 3. Perf & Sqz 50 sx cmt @ 4. Spot 210 sx cmt @ 4029 5. Perf & Sqz 50 sx cmt @ 6. Spot 25 sx cmt @ 200' to 7. Cut off well head, verify	SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. Circ hole w/ MLF. Pressure test csg. Spot 25 st 5545-5345'. WOC & Tag (9 5/8" Shoe) -1914'. WOC & Tag (DV Tool, B/Salt) 1914-1714'. WOC & Tag (T/Salt & 13 3/8" Shoe surface. cmt @ surface, weld on Dry Hole Marker.	completions: Attach wellbore diagram of comple
of starting any proposed work) proposed completion or recom 1. Tag Top of Fish @ 8507' 2. Set 5 ½" CIBP @ 8457'. 3. Perf & Sqz 50 sx cmt @ 4. Spot 210 sx cmt @ 4029 5. Perf & Sqz 50 sx cmt @ 6. Spot 25 sx cmt @ 200' to 7. Cut off well head, verify	SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. Circ hole w/ MLF. Pressure test csg. Spot 25 st 5545-5345'. WOC & Tag (9 5/8" Shoe) -1914'. WOC & Tag (DV Tool, B/Salt) 1914-1714'. WOC & Tag (T/Salt & 13 3/8" Shoe surface. cmt @ surface, weld on Dry Hole Marker.	x cmt @ 8457-8257'. ***R-111-P POTASH AREA*** be) SEE ATTACHED CONDITIONS
of starting any proposed work) proposed completion or recom 1. Tag Top of Fish @ 8507' 2. Set 5 ½" CIBP @ 8457'. 3. Perf & Sqz 50 sx cmt @ 4. Spot 210 sx cmt @ 4029 5. Perf & Sqz 50 sx cmt @ 6. Spot 25 sx cmt @ 200' to 7. Cut off well head, verify LPC Area Below ground ma	SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. Circ hole w/ MLF. Pressure test csg. Spot 25 ss 5545-5345'. WOC & Tag (9 5/8" Shoe)-1914'. WOC & Tag (DV Tool, B/Salt) 1914-1714'. WOC & Tag (T/Salt & 13 3/8" Shoe surface. cmt @ surface, weld on Dry Hole Marker. arker send pics before backfilling hole	completions: Attach wellbore diagram of comple
of starting any proposed work) proposed completion or recom 1. Tag Top of Fish @ 8507' 2. Set 5 ½" CIBP @ 8457'. 3. Perf & Sqz 50 sx cmt @ 4. Spot 210 sx cmt @ 4029 5. Perf & Sqz 50 sx cmt @ 6. Spot 25 sx cmt @ 200' to 7. Cut off well head, verify LPC Area Below ground ma	SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. Circ hole w/ MLF. Pressure test csg. Spot 25 ss 5545-5345'. WOC & Tag (9 5/8" Shoe)-1914'. WOC & Tag (DV Tool, B/Salt) 1914-1714'. WOC & Tag (T/Salt & 13 3/8" Shoe surface. cmt @ surface, weld on Dry Hole Marker. arker send pics before backfilling hole	completions: Attach wellbore diagram of comple
of starting any proposed work) proposed completion or recom 1. Tag Top of Fish @ 8507' 2. Set 5 ½" CIBP @ 8457'. 3. Perf & Sqz 50 sx cmt @ 4. Spot 210 sx cmt @ 4029 5. Perf & Sqz 50 sx cmt @ 6. Spot 25 sx cmt @ 200' to 7. Cut off well head, verify LPC Area Below ground masses	SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. Circ hole w/ MLF. Pressure test csg. Spot 25 ss 5545-5345'. WOC & Tag (9 5/8" Shoe)-1914'. WOC & Tag (DV Tool, B/Salt) 1914-1714'. WOC & Tag (T/Salt & 13 3/8" Shoe surface. cmt @ surface, weld on Dry Hole Marker. arker send pics before backfilling hole	completions: Attach wellbore diagram of a cmt @ 8457-8257'. ***R-111-P POTASH AREA*** be) SEE ATTACHED CONDITIONS OF APPROVAL
of starting any proposed work) proposed completion or recom 1. Tag Top of Fish @ 8507' 2. Set 5 ½" CIBP @ 8457'. 3. Perf & Sqz 50 sx cmt @ 4. Spot 210 sx cmt @ 4029 5. Perf & Sqz 50 sx cmt @ 6. Spot 25 sx cmt @ 200' to 7. Cut off well head, verify LPC Area Below ground masses	SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. Circ hole w/ MLF. Pressure test csg. Spot 25 ss 5545-5345'. WOC & Tag (9 5/8" Shoe)-1914'. WOC & Tag (DV Tool, B/Salt) 1914-1714'. WOC & Tag (T/Salt & 13 3/8" Shoe surface. cmt @ surface, weld on Dry Hole Marker. arker send pics before backfilling hole Rig Release Date:	completions: Attach wellbore diagram of a cmt @ 8457-8257'. ***R-111-P POTASH AREA*** be) SEE ATTACHED CONDITIONS OF APPROVAL
of starting any proposed work) proposed completion or recom 1. Tag Top of Fish @ 8507' 2. Set 5 ½" CIBP @ 8457'. 3. Perf & Sqz 50 sx cmt @ 4. Spot 210 sx cmt @ 4029 5. Perf & Sqz 50 sx cmt @ 6. Spot 25 sx cmt @ 200' to 7. Cut off well head, verify LPC Area Below ground materials and the spot 25 starts are spot 25 starts. Spud Date:	SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. Circ hole w/ MLF. Pressure test csg. Spot 25 st 5545-5345'. WOC & Tag (9 5/8" Shoe) -1914'. WOC & Tag (DV Tool, B/Salt) 1914-1714'. WOC & Tag (T/Salt & 13 3/8" Shoe) surface. cmt @ surface, weld on Dry Hole Marker. arker send pics before backfilling hole Rig Release Date:	secut @ 8457-8257'. ***R-111-P POTASH AREA*** De) SEE ATTACHED CONDITIONS OF APPROVAL dige and belief.
of starting any proposed work) proposed completion or recom 1. Tag Top of Fish @ 8507' 2. Set 5 ½" CIBP @ 8457'. 3. Perf & Sqz 50 sx cmt @ 4. Spot 210 sx cmt @ 4029 5. Perf & Sqz 50 sx cmt @ 6. Spot 25 sx cmt @ 200' to 7. Cut off well head, verify LPC Area Below ground materials. Spud Date:	SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. Circ hole w/ MLF. Pressure test csg. Spot 25 ss 5545-5345'. WOC & Tag (9 5/8" Shoe)-1914'. WOC & Tag (DV Tool, B/Salt) 1914-1714'. WOC & Tag (T/Salt & 13 3/8" Shoe) csurface. cmt @ surface, weld on Dry Hole Marker. Arker send pics before backfilling hole Rig Release Date:	secut @ 8457-8257'. ***R-111-P POTASH AREA*** De) SEE ATTACHED CONDITIONS OF APPROVAL dige and belief.
of starting any proposed work) proposed completion or recom 1. Tag Top of Fish @ 8507. 2. Set 5 ½" CIBP @ 8457. 3. Perf & Sqz 50 sx cmt @ 4. Spot 210 sx cmt @ 4029. 5. Perf & Sqz 50 sx cmt @ 6. Spot 25 sx cmt @ 200' to 7. Cut off well head, verify LPC Area Below ground materials. Spud Date: I hereby certify that the information about the start of the	SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. Circ hole w/ MLF. Pressure test csg. Spot 25 st 5545-5345'. WOC & Tag (9 5/8" Shoe) -1914'. WOC & Tag (DV Tool, B/Salt) 1914-1714'. WOC & Tag (T/Salt & 13 3/8" Shoe) surface. cmt @ surface, weld on Dry Hole Marker. arker send pics before backfilling hole Rig Release Date: Ove is true and complete to the best of my knowled.	secut @ 8457-8257'. ***R-111-P POTASH AREA*** De) SEE ATTACHED CONDITIONS OF APPROVAL dige and belief. DATE05/10/2022
of starting any proposed work) proposed completion or recom 1. Tag Top of Fish @ 8507. 2. Set 5 ½" CIBP @ 8457. 3. Perf & Sqz 50 sx cmt @ 4. Spot 210 sx cmt @ 4029 5. Perf & Sqz 50 sx cmt @ 6. Spot 25 sx cmt @ 200' to 7. Cut off well head, verify LPC Area Below ground materials and the start of the st	SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. Circ hole w/ MLF. Pressure test csg. Spot 25 st 5545-5345'. WOC & Tag (9 5/8" Shoe) -1914'. WOC & Tag (DV Tool, B/Salt) 1914-1714'. WOC & Tag (T/Salt & 13 3/8" Shoe) surface. cmt @ surface, weld on Dry Hole Marker. arker send pics before backfilling hole Rig Release Date: Ove is true and complete to the best of my knowled.	completions: Attach wellbore diagram of a cmt @ 8457-8257'. ***R-111-P POTASH AREA*** De) SEE ATTACHED CONDITIONS OF APPROVAL
of starting any proposed work) proposed completion or recom 1. Tag Top of Fish @ 8507. 2. Set 5 ½" CIBP @ 8457. 3. Perf & Sqz 50 sx cmt @ 4. Spot 210 sx cmt @ 4029 5. Perf & Sqz 50 sx cmt @ 6. Spot 25 sx cmt @ 200' to 7. Cut off well head, verify LPC Area Below ground materials and the start of the st	SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. Circ hole w/ MLF. Pressure test csg. Spot 25 st 5545-5345'. WOC & Tag (9 5/8" Shoe) -1914'. WOC & Tag (DV Tool, B/Salt) 1914-1714'. WOC & Tag (T/Salt & 13 3/8" Shoe) surface. cmt @ surface, weld on Dry Hole Marker. arker send pics before backfilling hole Rig Release Date: Ove is true and complete to the best of my knowled.	secut @ 8457-8257'. ***R-111-P POTASH AREA*** De) SEE ATTACHED CONDITIONS OF APPROVAL dige and belief. DATE05/10/2022
of starting any proposed work) proposed completion or recom 1. Tag Top of Fish @ 8507' 2. Set 5 ½" CIBP @ 8457'. 3. Perf & Sqz 50 sx cmt @ 4. Spot 210 sx cmt @ 4029 5. Perf & Sqz 50 sx cmt @ 6. Spot 25 sx cmt @ 200' to 7. Cut off well head, verify LPC Area Below ground materials Spud Date: I hereby certify that the information about SIGNATURE Ruth Shockers.	SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. Circ hole w/ MLF. Pressure test csg. Spot 25 st 5545-5345'. WOC & Tag (9 5/8" Shoe) -1914'. WOC & Tag (DV Tool, B/Salt) 1914-1714'. WOC & Tag (T/Salt & 13 3/8" Shoe) surface. cmt @ surface, weld on Dry Hole Marker. arker send pics before backfilling hole Rig Release Date: Ove is true and complete to the best of my knowled.	See ATTACHED CONDITIONS OF APPROVAL dige and belief. DATE 05/10/2022 Deconocophillips.com PHONE: 5757038321





CONDITIONS OF APPROVAL FOR PLUGGING AND ABANDONMENT OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office I (Hobbs) at (575)-263-6633 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down.

Company representative will be on location during plugging procedures.

- **1.** A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.
- **2.** Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- **3.** Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private- shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- **5.** A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can +be released.
- **6.** If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
- 7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- **8.** Produced water will not be used during any part of the plugging operation.
- 9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- **10.** All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 11. Class 'C' cement will be used above 7500 feet.
- 12. Class 'H' cement will be used below 7500 feet.
- **13.** A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- **14.** All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.
- **16.** When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- **18.** A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).

- 19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
- 20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
- A) Fusselman
- B) Devonian
- C) Morrow
- D) Wolfcamp
- E) Bone Springs
- F) Delaware
- G) Any salt sections
- H) Abo
- I) Glorieta
- J) Yates.
- K) Potash---(In the R-111-P Area (Potash Mine Area),

A solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.

21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing.

DRY HOLE MARKER REQ.UIRMENTS


The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:


- 1. Operator name
- 2. Lease and Well Number
- 3. API Number
- 4. Unit letter
- 5. Quarter Section (feet from the North, South, East or West)
- 6. Section, Township and Range
- 7. Plugging Date
- 8. County

SPECIAL CASES ----AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION





District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

COMMENTS

Action 105706

COMMENTS

Operator:	OGRID:
COG OPERATING LLC	229137
600 W Illinois Ave	Action Number:
Midland, TX 79701	105706
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

COMMENTS

Created B	Comment	Comment Date
plmartir	DATA ENTRY PM	5/26/2022

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 105706

CONDITIONS

Operator:	OGRID:
COG OPERATING LLC	229137
600 W Illinois Ave	Action Number:
Midland, TX 79701	105706
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By	Condition	Condition Date
kfortner	See attached COA	5/25/2022