Received by OCP: 3/7/2022 12:48:29 PM	State of New Mexico	Form C-103 ¹
Office	Energy, Minerals and Natural Resources	Revised July 18, 2013
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Ellergy, withertars and reactar resources	WELL API NO.
District II – (575) 748-1283		30-025-34727
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	
District III – (505) 334-6178	1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410		STATE X FEE
<u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM		
87505		
SUNDRY NOTICES	S AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
DIFFERENT RESERVOIR. USE "APPLICATION OF THE PROPERTY OF THE P	ON FOR PERMIT" (FORM C-101) FOR SUCH	GEM, 8705 JV-P
PROPOSALS.)	W II	8. Well Number 8
	as Well U Other	
2. Name of Operator		9. OGRID Number
BTA OIL PRODUCERS, LLC		260297
3. Address of Operator		10. Pool name or Wildcat
104 S. PECOS; MIDLAND, TX. 79701		GEM;YATES, EAST
		, ,
4. Well Location		
Unit Letter E 2310 feet from	om the NORTH line and 330 feet from the WSE	ST line
Section 2	Township 20S Range 33E NMP	M County LEA
11	. Elevation (Show whether DR, RKB, RT, GR, etc.	
	3581'	
10 (1 1 4	' A D A T I' A NI A CNI A'	D (0.1 D)
12. Check Appr	ropriate Box to Indicate Nature of Notice,	Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:		
PERFORMREMEDIALWORK X□	PLUG AND ABANDON		REMEDIAL WORK ALTERING CAS	ING 🗌
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILLING OPNS. ☐ P AND A	
PULL OR ALTER CASING	MULTIPLE COMPL		CASING/CEMENT JOB	
DOWNHOLE COMMINGLE				
CLOSED-LOOP SYSTEM □				
OTHER:			OTHER:	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Procedure:

- 1. MIRU pulling unit.
- 2. Unseat pump.
- 3. Pump 60 bbl of hot FW to clean up rods and tubing.
- 4. POH and LD pump, rods and sinker bars (send rod string in for inspection).
- 5. ND WH, release TAC, NU 7-1/16" 5M BOP
- 6. POH scanning out and standing back yellow band 2-7/8" production tubing. LD SN, mud joint and TAC (inspect for replacement).
- 7. PU 5.5" CIBP on tubing. RIH and set CIBP @ 6580'. Tag CIBP to confirm setting depth.
- 8. PU 1 jt. Circulate with FW. Pressure test CIBP to 500 psi for 10min against pipe rams. Spot 35' of Class C cement on top of the CIBP, flush w/ 9.5# salt gel.
- 9. POH to 5309', LD tubing, spot 100' of Class C cmt @ 5309' (cmt plug 50' above and below Delaware top @ 5259'). Flush w/ 9.5# salt gel.
- 10. POH to 3745', LD tubing, spot 100' of Class C cmt @ 3745' (cmt plug 50' above and below DVT @ 3695'). Flush with 2% KCL water and circulate to surface.
- 11. POH standing back 3400' of 2-7/8" production tubing, LD remainder of tubing.
- 12. MIRU WL unit. Correlate all depths to Reeves Compensated Neutron/Photo Density Log dated 1/16/2000.
- 13. PU and RIH w/ CCL/CBL tool. Tag TOC @ 3645' to confirm depth. Log from TOC to 1350'. Report results to office.
- 14. PU and RIH w/ 3-1/8" perforating guns w/ gamma ray loaded w/ 4 spf.

Perf Yates (2nd Sand) 3420' – 3430'.

- 15. RDMO WL unit.
- 16. MIRU tubing testers.

- 18. RIH and hydrotest to 7000 psi.
- 19. Set packer 40' above perfs (+/- 3380').
- 20. Pressure test 2-7/8" x 5.5" annulus from pkr to surface to 500 psi.
- 21. MIUL 330 gal tote of full strength HCR from Acquire. Cut acid to 33% on location.
- 22. Acidize Yates (2nd Sand) w/ 990 gal of 33% HCR and displace 2 bbl past top perf.
- 23. Shut in overnight.
- 24. Perform swab test, report test results to office.
- 25. Spot 2 frac tanks and fill each with 400 bbl FW (critical that tanks are clean, check with frac for FW compatibility/chemicals). Install BTA owned tbg frac valve.
- 26. MIRU frac crew.
- 27. Frac Yates (2nd Sand) as per attached frac design. Displace to top perf.
- 28. Flow down well. Swab test and report results to the office.
- 29. POH and LD packer.
- 30. PU production rod pumping BHA and RIH. Place TAC above perfs and pump intake below new perfs. Run 2 joints for mud anchor.
- 31. ND BOP, set TAC, NU WH.
- 32. PU and RIH w/ pump and rods. Load and Test. Hang on well.
- 33. RDMO pulling unit. Put well on production.

I hereby certify that the information above is true and	complete to the best	of my knowledge and belief.
---	----------------------	-----------------------------

SIGNATURE: Katy Reddell TITLE: REGULATORY ANALYST DATE: 3/7/2022

Type or print name: KATY REDDELL E-mail address: kreddell@btaoil.com PHONE: 432-682-3753 ext. 139

For State Use Only

APPROVED BY: Yeary Forther	TITLE_	Compliance Officer A	DATE	11/1/22	
Conditions of Approval (if any):		575-263-6633			

BTA Oil Producers 8705 JV-P Gem #8 Program to Recomplete to Yates (2nd Sand) (3420' – 3430') Lea County, NM

TD: 9700' PBTD: 9604'

KB Elevation: 3598' (17' KB) GL Elevation: 3581' GL

Surface Casing: @ 1385' - 13-3/8" 54.5# J-55 (circ to surf w/ 1100 sx cmt)

Intermediate Casing: @ 3263' - 9-5/8" 40# K-55 (circ to surf w/ 1000 sx cmt)

Production Casing: @ 9,700' - 5-1/2" 17# J-55 & N-80 (circ 2^{nd} stg w/ 2220 sx cmt, DVT @ 3695')

Perforations:

Sqz'd – Delaware (6589' – 6612')

Open – Bone Spring (8213' – 8235'; 8320' – 8331'; 9524' – 9578')

Target - Yates (2nd Sand) (3420' - 3430')

Production Equipment in Hole:

Tubing:	Rods:	Pump:
286 jts of 2-7/8" 6.5# N-80	6' – 1" pony	2.5-1.5-24 w/ 5' plunger
5.5" TAC	79 – 1" D78	
6jts of 2-7/8" 6.5# N-80	99 – 7/8" D78	
SN @ 9262'	179 – 3/4" D78	
6' perf sub	8 – 1" rods	
1 mud jt., EOT @ 9298'		

Capacities:

2-7/8" 6.5# Tubing	0.0058 bbl/ft
5.5" 17# Casing	0.0232 bbl/ft
Between tbg and casing	0.0152 bbl/ft

8705 JV-P Gem #8 Program to Recomplete to Yates (2nd Sand) Lea County, New Mexico

Procedure:

- 1. MIRU pulling unit.
- 2. Unseat pump.
- 3. Pump 60 bbl of hot FW to clean up rods and tubing.
- 4. POH and LD pump, rods and sinker bars (send rod string in for inspection).
- 5. ND WH, release TAC, NU 7-1/16" 5M BOP
- 6. POH scanning out and standing back yellow band 2-7/8" production tubing. LD SN, mud joint and TAC (inspect for replacement).
- 7. PU 5.5" CIBP on tubing. RIH and set CIBP @ 6580'. Tag CIBP to confirm setting depth.
- 8. PU 1 jt. Circulate with FW. Pressure test CIBP to 500 psi for 10min against pipe rams. Spot 35' of Class C cement on top of the CIBP, flush w/ 9.5# salt gel.
- 9. POH to 5309', LD tubing, spot 100' of Class C cmt @ 5309' (cmt plug 50' above and below Delaware top @ 5259'). Flush w/ 9.5# salt gel.
- 10. POH to 3745', LD tubing, spot 100' of Class C cmt @ 3745' (cmt plug 50' above and below DVT @ 3695'). Flush with 2% KCL water and circulate to surface.
- 11. POH standing back 3400' of 2-7/8" production tubing, LD remainder of tubing.
- 12. MIRU WL unit. Correlate all depths to Reeves Compensated Neutron/Photo Density Log dated 1/16/2000.
- 13. PU and RIH w/ CCL/CBL tool. Tag TOC @ 3645' to confirm depth. Log from TOC to 1350'. Report results to office.
- 14. PU and RIH w/ 3-1/8" perforating guns w/ gamma ray loaded w/ 4 spf.


Perf Yates (2nd Sand) 3420' - 3430'.

- 15. RDMO WL unit.
- 16. MIRU tubing testers.
- 17. PU 2.313XN nipple, 6' tbg sub, and AS-1X packer on 2-7/8" N-80 tbg.
- 18. RIH and hydrotest to 7000 psi.
- 19. Set packer 40' above perfs (+/- 3380').
- 20. Pressure test 2-7/8" x 5.5" annulus from pkr to surface to 500 psi.
- 21. MIUL 330 gal tote of full strength HCR from Acquire. Cut acid to 33% on location.
- 22. Acidize Yates (2nd Sand) w/990 gal of 33% HCR and displace 2 bbl past top perf.
- 23. Shut in overnight.
- 24. Perform swab test, report test results to office.
- 25. Spot 2 frac tanks and fill each with 400 bbl FW (critical that tanks are clean, check with frac for FW compatibility/ chemicals). Install BTA owned tbg frac valve.
- 26. MIRU frac crew.
- 27. Frac Yates (2nd Sand) as per attached frac design. Displace to top perf.
- 28. Flow down well. Swab test and report results to the office.
- 29. POH and LD packer.
- 30. PU production rod pumping BHA and RIH. Place TAC above perfs and pump intake below new perfs. Run 2 joints for mud anchor.
- 31. ND BOP, set TAC, NU WH.
- 32. PU and RIH w/ pump and rods. Load and Test. Hang on well.
- 33. RDMO pulling unit. Put well on production.


Estimated Cost: \$305,000

HCD - 11/11/2020

8705 JV-P Gem #8 Program to Recomplete to Yates (2nd Sand) Lea County, New Mexico



Released to Imaging: 11/1/2022 12:18:54 PM



Released to Imaging: 11/1/2022 12:18:54 PM

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 87623

CONDITIONS

Operator:	OGRID:
BTA OIL PRODUCERS, LLC	260297
104 S Pecos	Action Number:
Midland, TX 79701	87623
	Action Type:
	[C-103] NOI Workover (C-103G)

CONDITIONS

Created By		Condition Date
kfortner	None	11/1/2022