eived by OCD: 10/3/2023 8:55:50	AM		Page 1
Submit 1 Copy To Appropriate District	State of New Mex	kico	Form C-103
Office <u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources		Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240	OIL CONSERVATION DIVISION		WELL API NO.
<u>District II</u> - (575) 748-1283			30-045-33103
811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178			5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Franc		STATE 🗌 FEE 🛛
District IV - (505) 476-3460	Santa Fe, NM 87505		6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			
SUNDRY NOT	TCES AND REPORTS ON WELLS DSALS TO DRILL OR TO DEEPEN OR PLU	G BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		Montoya A 34	
PROPOSALS.) 1. Type of Well: Oil Well 🔲 Gas Well 🛛 Other		8. Well Number	
			100S
2. Name of Operator			9. OGRID Number
Dugan Production Corp.			006515
3. Address of Operator			10. Pool name or Wildcat
PO Box 420, Farmington, NM 87	499-0420		Basin Fruitland Coal (71629)
4. Well Location			
	feet from the <u>North</u> line and <u>1</u>	195 feet from th	ne West line
Section 34	Township 32N Range	13W NMPI	
	11. Elevation <i>(Show whether DR,</i>		,
	5889'	,	
Charle Annuantista Davet	Indicate Nature of Notice, Rep		ata
. Check Appropriate Dox to	mulcale mature of motice, Rep	Join of Other Da	aia
	NTENTION TO:	SUB	SEQUENT REPORT OF:
		REMEDIAL WOR	
		COMMENCE DR	
PULL OR ALTER CASING		CASING/CEMEN	
DOWNHOLE COMMINGLE		CASING/CEMEN	
CLOSED-LOOP SYSTEM			
OTHER		OTHER	
	eted operations (Clearly state all per	OTHER: tinent details and	give pertinent dates including estimated date
13. Describe proposed or comp		tinent details, and	
13. Describe proposed or comp of starting any proposed we	rk). SEE RULE 19.15.7.14 NMAC.	tinent details, and	give pertinent dates, including estimated date pletions: Attach wellbore diagram of
13. Describe proposed or comp	rk). SEE RULE 19.15.7.14 NMAC.	tinent details, and	
 Describe proposed or comp of starting any proposed we proposed completion or rec 	rk). SEE RULE 19.15.7.14 NMAC.	tinent details, and	
 Describe proposed or comp of starting any proposed we proposed completion or rec gan Production plans to plug and aban 	rk). SEE RULE 19.15.7.14 NMAC. ompletion. don the well per the following procedure:	tinent details, and For Multiple Com	pletions: Attach wellbore diagram of
 13. Describe proposed or comp of starting any proposed we proposed completion or rec gan Production plans to plug and aban Run 4½" casing scraper to 182 	rk). SEE RULE 19.15.7.14 NMAC. ompletion. don the well per the following procedure:	tinent details, and For Multiple Com	give pertinent dates, including estimated date apletions: Attach wellbore diagram of 1856'-2092'. Load hole. Pressure test casing to 600
 13. Describe proposed or comp of starting any proposed we proposed completion or rec gan Production plans to plug and aban Run 4½" casing scraper to 1820 psi for 30 mins. 	rk). SEE RULE 19.15.7.14 NMAC. ompletion. don the well per the following procedure:)'. RIH & set 41⁄2" CIBP @ 1806'. Fruitland	tinent details, and For Multiple Com Coal perforations @	pletions: Attach wellbore diagram of 1856'-2092'. Load hole. Pressure test casing to 600
 Describe proposed or comp of starting any proposed we proposed completion or rec gan Production plans to plug and aban Run 4½" casing scraper to 182 psi for 30 mins. Spot inside Plug I above CIBP ft/sk). Plug I, inside 4½" casin 	rk). SEE RULE 19.15.7.14 NMAC. ompletion. don the well per the following procedure: D'. RIH & set 4½" CIBP @ 1806'. Fruitland @ 1806' w/28 sks (32.2 cu ft) Class G neat g, 1470'-1806', Fruitland, 28 sks, 32.2 cu	tinent details, and For Multiple Com Coal perforations @ cement to 1470' to c	pletions: Attach wellbore diagram of 1856'-2092'. Load hole. Pressure test casing to 600 cover the Fruitland top (5 gal/sk, 15.8#/gal, 1.15 cu
 Describe proposed or comp of starting any proposed we proposed completion or rec gan Production plans to plug and aban Run 4½" casing scraper to 182 psi for 30 mins. Spot inside Plug I above CIBP ft/sk). Plug I, inside 4½" casin Spot inside Plug II from 330' w/ 	rk). SEE RULE 19.15.7.14 NMAC. ompletion. don the well per the following procedure: D'. RIH & set 4½" CIBP @ 1806'. Fruitland @ 1806' w/28 sks (32.2 cu ft) Class G neat g, 1470'-1806', Fruitland, 28 sks, 32.2 cu	tinent details, and For Multiple Com Coal perforations @ cement to 1470' to c	pletions: Attach wellbore diagram of 1856'-2092'. Load hole. Pressure test casing to 600
 Describe proposed or comp of starting any proposed wc proposed completion or rec gan Production plans to plug and aban Run 4½" casing scraper to 182 psi for 30 mins. Spot inside Plug I above CIBP (ft/sk). Plug I, inside 4½" casin Spot inside Plug II from 330' w/ Surface, 28 sks, 32.2 cu ft. 	rk). SEE RULE 19.15.7.14 NMAC. ompletion. don the well per the following procedure: D'. RIH & set 4½" CIBP @ 1806'. Fruitland @ 1806' w/28 sks (32.2 cu ft) Class G neat g, 1470'-1806', Fruitland, 28 sks, 32.2 cu 28 sks Class G neat cement (32.2 cu ft) to	tinent details, and For Multiple Com Coal perforations @ cement to 1470' to c ift. cover the surface ca	pletions: Attach wellbore diagram of 1856'-2092'. Load hole. Pressure test casing to 600 cover the Fruitland top (5 gal/sk, 15.8#/gal, 1.15 cu
 Describe proposed or comp of starting any proposed wc proposed completion or rec gan Production plans to plug and aban Run 4½" casing scraper to 182 psi for 30 mins. Spot inside Plug I above CIBP ft/sk). Plug I, inside 4½" casin Spot inside Plug I from 330' w/ Surface, 28 sks, 32.2 cu ft. Cut wellhead off. Fill casing w/c 	rk). SEE RULE 19.15.7.14 NMAC. ompletion. don the well per the following procedure: 0'. RIH & set 4½" CIBP @ 1806'. Fruitland @ 1806' w/28 sks (32.2 cu ft) Class G neat g, 1470'-1806', Fruitland, 28 sks, 32.2 cu 28 sks Class G neat cement (32.2 cu ft) to ement in case needed. Install dry hole man	tinent details, and For Multiple Com Coal perforations @ cement to 1470' to c ift. cover the surface ca	pletions: Attach wellbore diagram of 1856'-2092'. Load hole. Pressure test casing to 600 cover the Fruitland top (5 gal/sk, 15.8#/gal, 1.15 cu
 Describe proposed or comp of starting any proposed we proposed completion or rec gan Production plans to plug and aban Run 4½" casing scraper to 182 psi for 30 mins. Spot inside Plug I above CIBP ft/sk). Plug I, inside 4½" casin Spot inside Plug I from 330' w/ Surface, 28 sks, 32.2 cu ft. 	rk). SEE RULE 19.15.7.14 NMAC. ompletion. don the well per the following procedure: 0'. RIH & set 4½" CIBP @ 1806'. Fruitland @ 1806' w/28 sks (32.2 cu ft) Class G neat g, 1470'-1806', Fruitland, 28 sks, 32.2 cu 28 sks Class G neat cement (32.2 cu ft) to ement in case needed. Install dry hole man	tinent details, and For Multiple Com Coal perforations @ cement to 1470' to c ift. cover the surface ca	pletions: Attach wellbore diagram of 1856'-2092'. Load hole. Pressure test casing to 600 cover the Fruitland top (5 gal/sk, 15.8#/gal, 1.15 cu
 Describe proposed or comp of starting any proposed wc proposed completion or rec gan Production plans to plug and aban Run 4½" casing scraper to 182 psi for 30 mins. Spot inside Plug I above CIBP ft/sk). Plug I, inside 4½" casin Spot inside Plug I from 330' w/ Surface, 28 sks, 32.2 cu ft. Cut wellhead off. Fill casing w/c 	rk). SEE RULE 19.15.7.14 NMAC. ompletion. don the well per the following procedure: 0'. RIH & set 4½" CIBP @ 1806'. Fruitland @ 1806' w/28 sks (32.2 cu ft) Class G neat g, 1470'-1806', Fruitland, 28 sks, 32.2 cu 28 sks Class G neat cement (32.2 cu ft) to ement in case needed. Install dry hole man	tinent details, and For Multiple Com Coal perforations @ cement to 1470' to c ift. cover the surface ca	pletions: Attach wellbore diagram of 1856'-2092'. Load hole. Pressure test casing to 600 cover the Fruitland top (5 gal/sk, 15.8#/gal, 1.15 cu
 Describe proposed or comp of starting any proposed wc proposed completion or rec gan Production plans to plug and aban Run 4½" casing scraper to 182 psi for 30 mins. Spot inside Plug I above CIBP ft/sk). Plug I, inside 4½" casin Spot inside Plug I from 330' w/ Surface, 28 sks, 32.2 cu ft. Cut wellhead off. Fill casing w/c 	rk). SEE RULE 19.15.7.14 NMAC. ompletion. don the well per the following procedure: 0'. RIH & set 4½" CIBP @ 1806'. Fruitland @ 1806' w/28 sks (32.2 cu ft) Class G neat g, 1470'-1806', Fruitland, 28 sks, 32.2 cu 28 sks Class G neat cement (32.2 cu ft) to ement in case needed. Install dry hole man	tinent details, and For Multiple Com Coal perforations @ cement to 1470' to c ift. cover the surface ca	pletions: Attach wellbore diagram of 1856'-2092'. Load hole. Pressure test casing to 600 cover the Fruitland top (5 gal/sk, 15.8#/gal, 1.15 cu
 Describe proposed or comp of starting any proposed wc proposed completion or rec gan Production plans to plug and aban Run 4½" casing scraper to 182 psi for 30 mins. Spot inside Plug I above CIBP ft/sk). Plug I, inside 4½" casin Spot inside Plug I from 330' w/ Surface, 28 sks, 32.2 cu ft. Cut wellhead off. Fill casing w/c 	rk). SEE RULE 19.15.7.14 NMAC. ompletion. don the well per the following procedure: 0'. RIH & set 4½" CIBP @ 1806'. Fruitland @ 1806' w/28 sks (32.2 cu ft) Class G neat g, 1470'-1806', Fruitland, 28 sks, 32.2 cu 28 sks Class G neat cement (32.2 cu ft) to ement in case needed. Install dry hole man	tinent details, and For Multiple Com Coal perforations @ cement to 1470' to c ift. cover the surface ca	pletions: Attach wellbore diagram of 1856'-2092'. Load hole. Pressure test casing to 600 cover the Fruitland top (5 gal/sk, 15.8#/gal, 1.15 cu
 Describe proposed or comp of starting any proposed we proposed completion or rec gan Production plans to plug and aban Run 4½" casing scraper to 182 psi for 30 mins. Spot inside Plug I above CIBP ft/sk). Plug I, inside 4½" casin Spot inside Plug I from 330' w/ Surface, 28 sks, 32.2 cu ft. Cut wellhead off. Fill casing w/c Clean location. Rig down and n 	rk). SEE RULE 19.15.7.14 NMAC. ompletion. don the well per the following procedure: D'. RIH & set 41/2" CIBP @ 1806'. Fruitland @ 1806' w/28 sks (32.2 cu ft) Class G neat g, 1470'-1806', Fruitland, 28 sks, 32.2 cu 28 sks Class G neat cement (32.2 cu ft) to ement in case needed. Install dry hole man hove.	tinent details, and For Multiple Com Coal perforations @ cement to 1470' to c ift. cover the surface ca ker.	pletions: Attach wellbore diagram of 1856'-2092'. Load hole. Pressure test casing to 600 cover the Fruitland top (5 gal/sk, 15.8#/gal, 1.15 cu
 Describe proposed or comp of starting any proposed we proposed completion or rec gan Production plans to plug and aban Run 4½" casing scraper to 182 psi for 30 mins. Spot inside Plug I above CIBP ft/sk). Plug I, inside 4½" casin Spot inside Plug I from 330' w/ Surface, 28 sks, 32.2 cu ft. Cut wellhead off. Fill casing w/c Clean location. Rig down and n 	rk). SEE RULE 19.15.7.14 NMAC. ompletion. don the well per the following procedure: 0'. RIH & set 4½" CIBP @ 1806'. Fruitland @ 1806' w/28 sks (32.2 cu ft) Class G neat g, 1470'-1806', Fruitland, 28 sks, 32.2 cu 28 sks Class G neat cement (32.2 cu ft) to ement in case needed. Install dry hole man	tinent details, and For Multiple Com Coal perforations @ cement to 1470' to c ift. cover the surface ca ker.	pletions: Attach wellbore diagram of 1856'-2092'. Load hole. Pressure test casing to 600 cover the Fruitland top (5 gal/sk, 15.8#/gal, 1.15 cu
 Describe proposed or comp of starting any proposed we proposed completion or rec gan Production plans to plug and aban Run 4½" casing scraper to 182 psi for 30 mins. Spot inside Plug I above CIBP ft/sk). Plug I, inside 4½" casin Spot inside Plug I from 330' w/ Surface, 28 sks, 32.2 cu ft. Cut wellhead off. Fill casing w/c Clean location. Rig down and n 	rk). SEE RULE 19.15.7.14 NMAC. ompletion. don the well per the following procedure: D'. RIH & set 41/2" CIBP @ 1806'. Fruitland @ 1806' w/28 sks (32.2 cu ft) Class G neat g, 1470'-1806', Fruitland, 28 sks, 32.2 cu 28 sks Class G neat cement (32.2 cu ft) to ement in case needed. Install dry hole man hove.	tinent details, and For Multiple Com Coal perforations @ cement to 1470' to c ift. cover the surface ca ker.	pletions: Attach wellbore diagram of 1856'-2092'. Load hole. Pressure test casing to 600 cover the Fruitland top (5 gal/sk, 15.8#/gal, 1.15 cu
 13. Describe proposed or comp of starting any proposed we proposed completion or rec gan Production plans to plug and aban Run 4½" casing scraper to 1821 psi for 30 mins. Spot inside Plug I above CIBP of ft/sk). Plug I, inside 4½" casin Spot inside Plug I from 330' w/ Surface, 28 sks, 32.2 cu ft. Cut wellhead off. Fill casing w/c Clean location. Rig down and n 	rk). SEE RULE 19.15.7.14 NMAC. completion. don the well per the following procedure: D'. RIH & set 4½" CIBP @ 1806'. Fruitland @ 1806' w/28 sks (32.2 cu ft) Class G neat g, 1470'-1806', Fruitland, 28 sks, 32.2 cu 28 sks Class G neat cement (32.2 cu ft) to ement in case needed. Install dry hole man hove. Rig Release Date:	tinent details, and For Multiple Com Coal perforations @ cement to 1470' to c ift. cover the surface ca ker.	pletions: Attach wellbore diagram of 1856'-2092'. Load hole. Pressure test casing to 600 cover the Fruitland top (5 gal/sk, 15.8#/gal, 1.15 cu sing shoe. Plug II, inside 4½'' casing, 0-330',
 13. Describe proposed or comp of starting any proposed we proposed completion or rec gan Production plans to plug and aban Run 4½" casing scraper to 1821 psi for 30 mins. Spot inside Plug I above CIBP of ft/sk). Plug I, inside 4½" casin Spot inside Plug I from 330' w/ Surface, 28 sks, 32.2 cu ft. Cut wellhead off. Fill casing w/c Clean location. Rig down and n 	rk). SEE RULE 19.15.7.14 NMAC. ompletion. don the well per the following procedure: D'. RIH & set 41/2" CIBP @ 1806'. Fruitland @ 1806' w/28 sks (32.2 cu ft) Class G neat g, 1470'-1806', Fruitland, 28 sks, 32.2 cu 28 sks Class G neat cement (32.2 cu ft) to ement in case needed. Install dry hole man hove.	tinent details, and For Multiple Com Coal perforations @ cement to 1470' to c ift. cover the surface ca ker.	pletions: Attach wellbore diagram of 1856'-2092'. Load hole. Pressure test casing to 600 cover the Fruitland top (5 gal/sk, 15.8#/gal, 1.15 cu sing shoe. Plug II, inside 4½'' casing, 0-330',
 13. Describe proposed or comp of starting any proposed we proposed completion or rec gan Production plans to plug and aban Run 4½" casing scraper to 1821 psi for 30 mins. Spot inside Plug I above CIBP of fr/sk). Plug I, inside 4½" casin Spot inside Plug I from 330' w/ Surface, 28 sks, 32.2 cu ft. Cut wellhead off. Fill casing w/c Clean location. Rig down and n 	rk). SEE RULE 19.15.7.14 NMAC. completion. don the well per the following procedure: D'. RIH & set 4½" CIBP @ 1806'. Fruitland @ 1806' w/28 sks (32.2 cu ft) Class G neat g, 1470'-1806', Fruitland, 28 sks, 32.2 cu 28 sks Class G neat cement (32.2 cu ft) to ement in case needed. Install dry hole man hove. Rig Release Date: above is true and complete to the best ` \	tinent details, and For Multiple Com Coal perforations @ cement to 1470' to o ift. cover the surface ca ker.	and belief.
 13. Describe proposed or comp of starting any proposed we proposed completion or rec gan Production plans to plug and aban Run 4½" casing scraper to 1821 psi for 30 mins. Spot inside Plug I above CIBP of fr/sk). Plug I, inside 4½" casin Spot inside Plug I from 330' w/ Surface, 28 sks, 32.2 cu ft. Cut wellhead off. Fill casing w/c Clean location. Rig down and n 	rk). SEE RULE 19.15.7.14 NMAC. completion. don the well per the following procedure: D'. RIH & set 4½" CIBP @ 1806'. Fruitland @ 1806' w/28 sks (32.2 cu ft) Class G neat g, 1470'-1806', Fruitland, 28 sks, 32.2 cu 28 sks Class G neat cement (32.2 cu ft) to ement in case needed. Install dry hole man hove. Rig Release Date:	tinent details, and For Multiple Com Coal perforations @ cement to 1470' to o ift. cover the surface ca ker.	pletions: Attach wellbore diagram of 1856'-2092'. Load hole. Pressure test casing to 600 cover the Fruitland top (5 gal/sk, 15.8#/gal, 1.15 cu sing shoe. Plug II, inside 4½'' casing, 0-330',
 13. Describe proposed or compof starting any proposed we proposed completion or reconstruction plans to plug and abantian and the second starting strates and the second start of the second start of	rk). SEE RULE 19.15.7.14 NMAC. completion. don the well per the following procedure: D'. RIH & set 41/2" CIBP @ 1806'. Fruitland @ 1806' w/28 sks (32.2 cu ft) Class G neat g, 1470'-1806', Fruitland, 28 sks, 32.2 cu 28 sks Class G neat cement (32.2 cu ft) to ement in case needed. Install dry hole man hove. Rig Release Date: above is true and complete to the best TITLE Engineer	tinent details, and For Multiple Com Coal perforations @ cement to 1470' to c ift. cover the surface ca ker.	and belief.
 13. Describe proposed or compof starting any proposed we proposed completion or reconstruction plans to plug and abantian and the second starting strates and the second start of the second start of	rk). SEE RULE 19.15.7.14 NMAC. completion. don the well per the following procedure: D'. RIH & set 41/2" CIBP @ 1806'. Fruitland @ 1806' w/28 sks (32.2 cu ft) Class G neat g, 1470'-1806', Fruitland, 28 sks, 32.2 cu 28 sks Class G neat cement (32.2 cu ft) to ement in case needed. Install dry hole man hove. Rig Release Date: above is true and complete to the best TITLE Engineer	tinent details, and For Multiple Com Coal perforations @ cement to 1470' to c ift. cover the surface ca ker.	and belief.
 13. Describe proposed or compof starting any proposed we proposed completion or recompletion of the second start of the s	rk). SEE RULE 19.15.7.14 NMAC. ompletion. don the well per the following procedure: D'. RIH & set 41½" CIBP @ 1806'. Fruitland @ 1806' w/28 sks (32.2 cu ft) Class G neat g, 1470'-1806', Fruitland, 28 sks, 32.2 cu 28 sks Class G neat cement (32.2 cu ft) to ement in case needed. Install dry hole man nove. Rig Release Date: above is true and complete to the best <u>E.</u> TITLE_Engineer <u>E.</u> E-mail address:alip	tinent details, and For Multiple Com Coal perforations @ cement to 1470' to c ift. cover the surface ca ker.	and belief.
 13. Describe proposed or compof starting any proposed were proposed completion or rectar proposed completion or rectar proposed completion or rectar proposed completion or rectar pairs for 30 mins. Run 4½" casing scraper to 1824 psi for 30 mins. Spot inside Plug I above CIBP of ft/sk). Plug I, inside 4½" casin spot inside Plug I from 330" w/ Surface, 28 sks, 32.2 cu ft. Cut wellhead off. Fill casing w/c Clean location. Rig down and n 	rk). SEE RULE 19.15.7.14 NMAC. ompletion. don the well per the following procedure: D'. RIH & set 41/2" CIBP @ 1806'. Fruitland @ 1806' w/28 sks (32.2 cu ft) Class G neat g, 1470'-1806', Fruitland, 28 sks, 32.2 cu 28 sks Class G neat cement (32.2 cu ft) to ement in case needed. Install dry hole man nove. Rig Release Date: above is true and complete to the best L TITLE_Engineer E E-mail address:alip	tinent details, and For Multiple Com Coal perforations @ cement to 1470' to c ift. cover the surface ca ker. of my knowledge ing Supervisor h.reena@duganpr	and belief.
of starting any proposed we proposed completion or rec gan Production plans to plug and aban - Run 4½" casing scraper to 182 psi for 30 mins. - Spot inside Plug I above CIBP ft/sk). Plug I, inside 4½" casin - Spot inside Plug I from 330' w/ Surface, 28 sks, 32.2 cu ft. - Cut wellhead off. Fill casing w/c - Clean location. Rig down and n - Clean location. Rig down and n - Clean location. Rig down and n - GNATURE pe or principame _Aliph Reena. P. - State Use Only PROVED BY:	rk). SEE RULE 19.15.7.14 NMAC. ompletion. don the well per the following procedure: D'. RIH & set 41/2" CIBP @ 1806'. Fruitland @ 1806' w/28 sks (32.2 cu ft) Class G neat g, 1470'-1806', Fruitland, 28 sks, 32.2 cu 28 sks Class G neat cement (32.2 cu ft) to ement in case needed. Install dry hole man nove. Rig Release Date: above is true and complete to the best L TITLE_Engineer E E-mail address:alip	tinent details, and For Multiple Com Coal perforations @ cement to 1470' to c ift. cover the surface ca ker. of my knowledge ing Supervisor h.reena@duganpr	and belief.
 13. Describe proposed or compof starting any proposed were proposed completion or recompletion of the second start of the	rk). SEE RULE 19.15.7.14 NMAC. ompletion. don the well per the following procedure: D'. RIH & set 41/2" CIBP @ 1806'. Fruitland @ 1806' w/28 sks (32.2 cu ft) Class G neat g, 1470'-1806', Fruitland, 28 sks, 32.2 cu 28 sks Class G neat cement (32.2 cu ft) to ement in case needed. Install dry hole man nove. Rig Release Date: above is true and complete to the best L TITLE_Engineer E E-mail address:alip	tinent details, and For Multiple Com Coal perforations @ cement to 1470' to c ift. cover the surface ca ker. of my knowledge ing Supervisor h.reena@duganpr	and belief.

Planned P & A Procedure

Montoya A 34 # 100S 30-045-33103 Basin Fruitland 1150' FNL & 1195' FWL S34 T32N R13W San Juan County, NM Lat:36.9476318 Long:-108.1960144

Dugan Production plans to plug and abandon the well per the following procedure:

- Run 4½" casing scraper to 1820'. RIH & set 4½" CIBP @ 1806'. Fruitland Coal perforations
 @ 1856'-2092'. Load hole. Pressure test casing to 600 psi for 30 mins.
- Spot inside Plug I above CIBP @ 1806' w/28 sks (32.2 cu ft) Class G neat cement to 1470' to cover the Fruitland top (5 gal/sk, 15.8 #/gal, 1.15 cu ft/sk). Plug I, inside 4½" casing, 1470'-1806', Fruitland, 28 sks, 32.2 cu ft.
- Spot inside Plug II from 330' w/28 sks Class G neat cement (32.2 cu ft) to cover the surface casing shoe. Plug II, inside 4½" casing, 0-330', Surface, 28 sks, 32.2 cu ft.
- Cut wellhead off. Fill casing w/cement incase needed. Install dry hole marker.
- Clean location. Rig down and move.

Montoya A 34 # 100S 30-045-33103 Basin Fruitland 1150' FNL & 1195' FWL S34 T32N R13W San Juan County, NM Lat:36.9476318 Long:-108.1960144



Montoya A 34 # 100S 30-045-33103 Basin Fruitland 1150' FNL & 1195' FWL S34 T32N R13W San Juan County, NM Lat:36.9476318 Long:-108.1960144



7" 20# casing @ 230'. Cemented with 99 sks Class B cement. Hole size: 8-3/4". Circulate 8 bbls cement to surface.

Plug II, inside 4 1/2" casing, 0-330', Surface, 28 sks, 32.2 Cu.ft.

4 1⁄2" 10.5# casing @ 2314'. Hole size: 6-1/4"

Cement production casing w/ 252 sks Cement, 486 Cu.ft. Circulated 16 bbls cement to surface.

Set 4 ¹/₂" CIBP @ 1806'. Plug I, Inside 4 ¹/₂" casing, 1470'-1806', Fruitland, 28 sks, 32.2 Cu.ft.

Fruitland Coal Perforated @ 1856' - 2092'

PBTD @ 2269', TD 2314'

Montoya A 34 # 100S 30-045-33103 Basin Fruitland 1150' FNL & 1195' FWL S34 T32N R13W San Juan County, NM Lat:36.9476318 Long:-108.1960144

Formation Tops

- Ojo Alamo None
- Kirtland Surface
- Fruitland 1570
- Pictured Cliff 2153

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
DUGAN PRODUCTION CORP	6515
PO Box 420	Action Number:
Farmington, NM 87499	271725
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By	Condition	Condition Date
mkuehling	Notify NMOCD 24 hours prior to moving on	10/10/2023

CONDITIONS

Page 6 of 6

Action 271725