

Santa Fe Main Office
Phone: (505) 476-3441
General Information
Phone: (505) 629-6116

Online Phone Directory Visit:
<https://www.emnrd.nm.gov/ocd/contact-us/>

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-22678	
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name Sue	
8. Well Number 1	
9. OGRID Number 247692	
10. Pool name or Wildcat Bagley Permo Penn North	
4. Well Location Unit Letter <u>M</u> : <u>660</u> feet from the <u>South</u> line and <u>660</u> feet from the <u>West</u> line Section <u>29</u> Township <u>11S</u> Range <u>33 E</u> NMPM County Lea	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) <u>4331 KB</u>	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK PLUG AND ABANDON
TEMPORARILY ABANDON CHANGE PLANS
PULL OR ALTER CASING MULTIPLE COMPL
DOWNHOLE COMMINGLE
CLOSED-LOOP SYSTEM
OTHER:

SUBSEQUENT REPORT OF:

REMEDIAL WORK ALTERING CASING
COMMENCE DRILLING OPNS. P AND A
CASING/CEMENT JOB
OTHER:

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

See attached

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE



TITLE

Agent

DATE 01/09/2026

Type or print name Quang Truong

E-mail address: qtram@jaymgt.com

PHONE: 713-621-6785

For State Use Only

APPROVED BY:

TITLE

DATE

Conditions of Approval (if any):

RIG 110

SUE #001 – JAY MGMNT – START 1.17.25 FINISH 2.6.25

API# 30-025-22678

1.17.25

MOVE EQUIPMENT FROM WARREN STATE TO SUE # 001 MOVE RIG DOG HOUSE CMT TRUCKS BOP TRAILER POWER SWIVEL LOAD 60 JTS ON W/S TRAILER

LEVEL LOCATION FOR BASE BEAM AND SPOTTED SPOT AND GREASE CROWN ON RIG. TOO WINDY FOR RIG UP SDFN

TRAVEL HOME

1.22.25

DROVE TO LOCATION

HOLD TGSM

START RIG AND RUSU

UNHANG HORSE HEAD

WORKING TO GET PUMP UNSET

PICK UP POLSH ROD SECURE WELL SDFN

TRAVEL HOME

1.23.25

DROVE TO LOCATION

HOLD TGSM

CONTINUE ATTEMP TO GET PUMP UNSET

RIG UP FLOOR TBG TONGS AND BACK OFF TOOL BACK OFF RODS GET 5 K RIG DOWN TBG TONGS RIG UP ROD TONGS

POOH LAY DOWN 127 RODS AT 3200 RIG DOWN RODS EQUIPMENT RIG TBG EQUIPMENT

N/D WELL HEAD

N/U BOP RIG UP FLOOR AND TBG EQUIPMNET

ATTEMPT TO RELEASE TBG ANCHOR GET RELEASE TBG ANCHOR GET STUCK IN SPOT PUMP 15 BBLS OF

9.5 PRESSURE UP TO 700 PSI CONTINUE WORK TO PASS TIGHT SPOT

POOH W/ 50 STANDS GET TO RODS SECURE WELL SDFN

TRAVEL HOME

1.24.25

DROVE TO LOCATION

HOLD TGSM CHK PRESSURE 4.5 800 PSI 2 3/8

BLEED DOWN 4.5 CASING AND LETTED FLOW BACK MAKE 20 BBLS

LAY DOWN ONE JTN WORK ATTEMTED TO UNSEAT PUMP RIG UP BACK OFF TOOL AND BACK OFF RODS

POOH LAY DOWN W/ 109 RODS CHANGE ROD EQUIPMENT BACK TO TBG EQUIPMENT

POOHW/ 4 STANDS GET HUNG UP TURN TBG AND WORK UP AND DOWN PULL 6 STANDS SECURE WELL
SDFN NEED TO MAKE CIRCULATE HOLE TBG FULL OF OIL
TRAVEL HOME

1.27.25

DROVE TO LOCATION

HOLD TGSM CHK PRESSURE TBG 300 PSI CASING 600 PSI

BLEED OFF PRESSURE

MIRU AAA WIRE LINE RIH W/ PERFORATING GUNS SHOT 2 3/8 TBG POOH

POOH W/ 12 STANDS TAC STUCK WORK TO GET TAC RELEASE

CONTINUE POOH SLOW W/ 18 STANDS MORE GET TO RODS AGAIN SECURE WELL SDFN

TRAVEL HOME

1.28.25

DROVE TO LOCATION

HOLD TGSM CHK PRESSURE

BLEED OFF PRESSURE LAY DOWN ONE JTN RIG UP BACK OFF TOOL AND BACK OFF RODS

POOH LAY DOWN W/ 46 RODS

POOH W/ 18 STANDS AND CHANGE BACK EQUIPMENT SEVERAL TIMES TOTAL OF RODS PULL 360 AND 288 JTS AT 9107

SECURE WELL SDFN

TRAVEL HOME

1.29.25

DROVE TO LOCATION

HOLD TGSM CHECK

MIRU AAA WIRE LINE RIG UP 4.5 CIBP RIH TAG TIGHT SPOT AT 5300 ATTEMPT TO WORK CIBP THROUGH TIGHT SPOT POH RIG DOWN AAA WIRE LINE

WAIT ON ORDERS

MIRU 4.5 HM CIBP TBG SET RIH W/ 271 JTS TO EOT AT 8572 WORK TO GET CIBP AT 8572

PUMP 5 BBLs OF FRESH WATER DROP BALL PUMP 32 BLLs OF MLF SET 4.5 CIBP AT 8572

CIRCULATE WELL CLEAN W/ 132 BBLs OF 9.5 MLF

PLUG # 1 MIX& PUMP 25 SXS

POOH 30 STANDS SECURE WELL SDFN

TRAVEL HOME

1.30.25

DROVE TO LOCATION

HOLD TGSM

CONTINUE POOH W/170 JTS AND LAY DOWN 50 JTS
MIRU AAA WIRE LINE RUN CBL FROM 8250 TO SURFACE
RIH W/ 70 STANDS OPEN ENDED FOR PLUG # 2 AT 7298 AND PLUG # 3 AT 6563 AND BECAUSE CBL
RESULTS SHOWS NO CMT BEHIND CASING OCD OF NM DECIDED TO PERFORATE EVERY PLUG
POOH W/ 70 STADS
RIG UP 4.5 PKR RIH W/ 30 STANDS SECURE WELL SDFN
TRAVEL HOME

1.31.25

DROVE TO LOCATION

HOLD TGSM

MIRU 4.5 PKR RIH W/ 221 JT TO EOT AT 6985 AND SET

MIRU AAA WIRE LINE RIH W/ PERFORATING GUNS SHPT 4.5 CASING AT 7298 POOH RIG DOWN WIRE
LINE

GET INJECTION RATE PRESSURE UP TO 1000 BLEED OFF PRESSURE UNSET PKR RIH W/ 12 JTS TO EOT AT
7348

PLUG # 2 MIX AND PUMP 25 SXS

POOH W 15 STANDS LAY DOWN 25 JTS SECURE WELL SDFN

TRAVEL HOME

2.3.25

DROVE TO LOCATION

HOLD TGSM

MIRU AAA WIRE LINE RIH W/ PERFORATING GUNS RIH TAG PLUG # 2 AT 6907 PULL TO 6563 SHOT 4.5
CASING POOH

GET INJECTION RATE PRESSURE UP TO 1000 PSI BLEED OFF PRESSURE UNSET PKR RIH W/ 12 JTS TO
EOT AT 6613

PLUG # 3 MIX & PUMP 25 SXS WOC

WOC

MIRU AAA WIRE LINE RIH W/ PERFORATING GUNS RIH TAG PLUG# 3 AT 6295 PULL TO 5173 SHOT 4.5
CASING POOH RIG DOWN WIRE LINE

GET INJECTION RATE PRESSURE UP TO 1000 PSI BLEED OFF PRESSURE UNSET PKR RIH W/ 12 JTS TO
EOT AT 5223

PLUG # 4 MIX & PUMP 25 SXS

POOH W/ 30 STANDS SECURE WELL SDFN

TRAVEL HOME

2.4.25

DROVE TO LOCATION

HOLD TGSM

RIH W/ 25 STANDS TAG PLUG #4 AT 4895 POOH LAY DOWN 56 JTS PKR DIDN'T SET
POOH W/ 110 JTS IRG DOWN PKR GET NEW RUBBERS ON PKR AND RIH TO EOT AT 3480 AND SET PKR
MIRU AAA WIRE LINE RIH W/ PERFORATING GUNS SHOT 4.5 CASING AT 3780 POOH RIG DOWN WIRE
LINE

GET INJECTION RATE PUMP 1.5 BBLS X MINUTE AT 1200 PSI

PLUG # 5 MIX & PUMP 65 SXS WOC

WOC

UNSET PKR POOH LAY DOWN 44 JTS TO EOT AT 2086

RIG UP AAAWIRE LINE RIH W/ PERFORATING GUNS TAG PLUG # 5 AT 3640 PULL TO 2470 SHOT 4.5
CASING POOH RIG DOWN WIRE LINE

GET INJECTION RATE PUMP 1.5 BBLS X MINUTE AT 1000 Psi

PLUG # 6 MIX & PUMP 65 SXS SECURE WELL SDFN

TRAVEL HOME

2.5.25

DROVE TO LOCATION

HOLD TGSM

RIH W/ 5 JTS TAG PLUG # 6 AT 2255 POOH LAY DOW W/ 22 JTS TO EOT AT 1470

MIRU AAA WIRE LINE RIH W/PERFORATING GUNS SHOT 4.5 CASING AT 1770 POOH RIG DOWN WIRE
LINE

GET INJECTION RATE PUMP 2 BBLS X MINUTE AT 300 PSI

PLUG # 7 MIX & PUMP 65 SXS WOC

WOC

UNSET PKR POOH LAY DOWN W/ 46 JTS

RIG UP AAA WIRE LINE RIH W/ PERFORATING GUNS TAG PLUG # 7 AT 1652 PULL TO 400 SHOT 4.5
CASING POOH RIG DOWN WIRE LINE

GET INJECTION RATE PUMP 2 BBLS X MINUTE AT 100 PSI PLUG # 8 MIX & PUMP 100 SXS

TRAVEL HOME

2.6.25

DROVE TO LOCATION

HOLD TGSM

RIG DOWN TBG EQUIPMENT FLOOR AND N/D BOP

RDSU AND ALL EQUIPMENT

DIG SELLER CUT WELL HEAD INSTALL DRY HOLE MARKER MIX CMT LEVEL LOCATION

DROVE TO LAST LOCATION DIG SELLER START CUT WELL HEAD


TRAVEL HOME

Jay Management Company

Sue 1

Unit Letter M, 660' South, 660' West
 Sect 29, Township 11S, Range 33E NMPM
 Los Co, NM ()
 API No. 30-025-22678

Jay Management Company, LLC
 2401 Fountain View, Suite 420
 Houston, TX 77057



Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 541618

CONDITIONS

Operator: JAY MANAGEMENT COMPANY, LLC 2401 Fountain View Drive Houston, TX 77057	OGRID: 247692
	Action Number: 541618
	Action Type: [C-103] Sub. Plugging (C-103P)

CONDITIONS

Created By	Condition	Condition Date
gcordero	Clean Location in accordance with 19.15.25.10 NMAC.	1/15/2026
gcordero	Submit C-103Q within one year of plugging.	1/15/2026