

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	Matador Production Company	Contact	Mike Ernest
Address	5400 LBJ Freeway, Ste 1500, Dallas TX 75240	Telephone No.	972-371-5200
Facility Name	Cooper 3-6	Facility Type	Producing oil well
Surface Owner	Mr. Jimmie Cooper	Mineral Owner	Mr. Jimmie Cooper
		Lease No.	302395

LOCATION OF RELEASE

30025352040000

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	3	20 S	37 E	458	North	1704	East	Lea

Latitude N 32 36' 30"

Longitude W 103 14' 10"

NATURE OF RELEASE

Type of Release	Crude oil	Volume of Release	6 to 7 bbls	Volume Recovered	5 bbls
Source of Release	Heater treater	Date and Hour of Occurrence	11-19-2007	Date and Hour of Discovery	11-19-2007 10 00 am
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse			


WTR 151

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Cause - Heater treater developed a hole in the fire tube. Oil leaked through the fire tube, through the areiator, backed up in the exhaust stack & overflowed out the top of the exhaust stack.
Remedial action - Emptied heater, replaced fire tube, replaced areiator with blind flange. Left well off production until repairs completed.

Describe Area Affected and Cleanup Action Taken.*
Area affected - Spill was contained in berm around heater, except for wind-blown oil that carried outside berm and contaminated a spot on the location pad approximately 80 ft long by 3 to 4 ft wide.
Cleanup action taken - Picked up as much fluid as possible from inside berm (5 bbls oil), and emptied heater for repairs. Unable to pick up any fluid from outside berm since there were no puddles. Will remove oily caliche and replace with clean material

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Michael G. Ernest	 Approved by District ENVIRONMENTAL ENGINEER	
Title: Chief Engineer	Approval Date: 12-15-07	Expiration Date: 2-15-07
E-mail Address: mgerne@matadorresources.com	Conditions of Approval: Attached <input type="checkbox"/>	
Date: 12-3-2007 Phone: 972-371-5223	SUBMIT FINAL C-141 w/ DOCUMENTATION BY	

* Attach Additional Sheets If Necessary

*NOTE DEPTH TO WATER IS CRITICAL
RPT# 1682