

**Tahoe Energy
Ogrid 22100
Brownlee # 1
30-025-04461
UL P, Section 25, T21S, R36E
Plugging Procedure**

**8 5/8" casing set at 325ft, Cmt Circulated
5 1/2" 14# casing set 3720ft, Cmt with 150sx cmt. TOC calculated 2600ft
Open hole from 3720-3790ft
Perfs 3694-3710ft
Pool – Penrose Skelly Grayburg
Top of Anhy 1200ft
Base of Salt at 2560ft**

- 1. Move in plugging rig**
- 2. NUBOP**
- 3. Pull production equipment**
- 4. Run 5 1/2" gauge ring to 3650ft**
- 5. Run and set CIBP at 3650ft**
- 6. Run tubing and tag CIBP**
- 7. Displace well with gelled brine water**
- 8. Spot 25 sx cmt**
- 9. Pull tbg**
- 10. Perf at 1250ft**
- 11. Run and set packer at 1000ft**
- 12. Squeeze perfs with 25 sx cmt, displace cmt to 1150ft and WOC**
- 13. Release packer and pull tbg**
- 14. Tag cmt plug**
- 15. Perf at 375ft**
- 16. Establish circulation 5 1/2" X 8 5/8" annulus**
- 17. Cement to surf via 5 1/2" casing. Estimated 90 sx cmt**
- 18. Cut off well head and install PA marker**
- 19. Rig down move out SU**
- 20. Clean and level location. Remove SU anchors 1ft BGL**
- 21. Remove any surface production equipment...**