Millard Deck Estate Ogrid 14894 Alexander # 1 30-025-06429 Lot # 2, Section 7, T21S, R37E Plugging Procedure

8 5/8" casing set at 250ft, Cmt Circulated 5 1/2" casing set at 3435ft, Cmt in 2 Stages, DV Tool at 1348ft. 1st stage 200sx, 2nd stage 100sx 4" liner from 4119-3251ft, Cmt circulated Perfs 3799-3931ft CIBP at 3648ft Perfs 3558-3634ft Top of Anhy at 1275ft

- 1. Move in plugging rig
- 2. NUBOP
- 3. Pull any production equipment
- 4. Run 2 3/8" workstring to 3558ft
- 5. Spot 100 sx cmt plug
- 6. Pull tbg and WOC
- 7. Run tbg and tag cement plug
 - A. If cement is at or above 3200ft procede to step 8
 - B. If cement is below 3251ft, Spot additional cement to cover liner top at 3251ft
- 8. Displace well with gelled brine water
- 9. Pull tubing to 1325ft
- 10. Spot 25 sx cmt plug
- 11. Pull tbg
- 12. Perf at 350ft
- 13. Establish circulation 5 ¹/₂" X 8 5/8" casing
- 14. Cement to surface via 5 1/2" casing with estimated 60 sx cmt
- 15. Cut of well head and install PA marker
- 16. Rig down SU and remove SU anchors 1ft BGL
- **17. Remove any surface production equipment**
- 18. Clean and level location

Before the OCD Case 13361 OCD Ex. 7

BEP 5/27/2004

Millard Deck Estate Ogrid 14894 Lea 407 State # 5 30-025-03535 UL D, Section 33, T21S, R35E Plugging Procedure

7 5/8" casing set at 327ft, Cmt circulated

5" casing set at 3949ft, Cmt in 2 stages. DV tool at 1684ft. 1st stage 100sx, 2nd stage 100sx, TOC 890ft – Operator reported Perfs 3848-3890ft Top of Anhy at 1184ft

and the state of the state of the

and the second second second

n an an an an an Arrange. An an an Arrange ann an an an an an Arrange an Arrange an Arrange an Arrange an an a

and part of the second second

Production of the

1. Move in plugging rig

and the Diff.

2. NUBOP

3. Pull any production equipment

4. Run 2 3/8 workstring to 3848ft

5. Spot 50 sx cmt plug

6. Pull tbg and WOC

7. Tag cmt plug

A. If cmt plug at or above 3800ft procede to step 8

B. If cmt plug at or below 3848, spot additional cmt to bring cmt to 3800ft

8. Displace well with gelled brine water

9. Pull tbg to 1240ft

10. Spot 25 sx cmt plug

11. Pull tbg

12. Perf at 350ft

13. Establish circulation 5" X 7 5/8" annulus

14. Circulate cmt to surface via 5" casing, estimated 60 sx cmt

15. Cut off well head and install PA marker

16. Rig down SU. Remove SU anchors 1ft BGL

17. Remove any surface production equipment

18. Clean and level location

BEP 5/27/2004