Tenneco Oil Exploration and Production

A Tenneco Company


6162 South Willow Drive P.O. Box 3249 Englewood, Colorado 80155 (303) 740-4800



Western Rocky Mountain Division

AMENDED COPY

May 30, 1984



New Mexico Oil Conservation Division P.O. Box 2088 Santa Fe, NM 87501

> RE: Hardship Status - Dawson Fed #1 Section 26, T27N, R8W San Juan County, New Mexico

> > Case 8245

Gentlemen:

Tenneco Oil requests that the referenced well be classified as a hardship gas well. Underground waste will occur due to shut-in because of a build up of liquids in the wellbore requiring the well to be swabbed to return it to production. The build up of liquids in the wellbore also causes the water saturation of the pay zones near the wellbore to increase, there by lowering the relative permeability to gas. This low relative permeability, whether permanent or temporary, will restrict the flow of gas.

In order to rectify the water problem this well currently has an intermitter installed that unloads the produced liquids (water) to the low pressure side of the separator. This method has been successful in keeping the wellbore unloaded and flowing freely. The use of other dewatering devices has been considered but rejected. These are:

- (1) Plunger lift due to shut-in bottom hole pressure being very close to the line pressure.
- (2) Undersize tubing the minimum flow rates necessary to unload the produced water, as calculated by the methods proposed by Turner are listed below:

Since the well has a deliverability of approximately 100 MCFD none of the above tubing sizes would enable the well to unload its produced water. It would not be advisable to use smaller tubing than 1" at these depths.

When this well is shut-in for a period of time it has to be swabbed to return it to production. Normal swab time is usually two to three days, at a cost of approximately \$2,500.00, which is more than the gross monthly revenue generated by this well. If Tenneco abandoned this well due to failure to obtain hardship gas well classification, the quantity of gas reserves which would be lost would be 308 MMCF. This well is in a prorated pool which is currently under produced 3029 MCF as of May 1984 production book.

Hardship Status - Dawson #1 Page 2 May 30, 1984

If you have any questions concerning the application for hardship gas well status, please contact Mark Owen, Production Engineer.

Very truly yours,

Scott McKinney

Senior Regulatory Analyst

SMc:gj
Attachment

cc: Mark Owen