AND SHARES

STATE OF NEW MEXICO

ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE

GARREY CARRUTHERS
GOVERNOR

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO 87410 (505) 334-6178

PARAMOUNT PETROLEUM CORP.
Aztec Totah Unit #16 O-18-29N-13W

Downhole Conditions and Equipment

8 5/8" at 200' W/225 sacks
4 1/2" at 5085' W400 sacks. 2 stages
2 3/8" at 4992
Baker Model "B" packer at 4912

	and the state of t
BEFO	RE EXAMPLE CATADACH
CIL	CONTRACTOR OF CASA
10.21-	97 200 80 100 Language
CLSE N	0. 7213
TOMBERS AND AND WARREST	reparted the commentation of which is the measurement when the entire measurement is a second of the commentation of the comme

DIVISION APPROVED PLUGGING PROGRAM

- 1. Release packer and pull same.
- 2. Go back in hole with tubing to plug back TD at 5081' and set a cement plug 5081' to 4931'.
- 3. Pull out of cement with tubing and reverse out with water to make sure tubing is clear. Wait on cement a minimum of 4 hours and tag plug. If plug is at 4980 or above go to step 4. If not, fill to 4931.
- 4. Come out of hole with tubing and pressure up on casing to 500 PSI to insure mechanical integrity. If casing leaks go in hole with packer and locate hole.
- 5. Squeeze with a minimum of 30 sacks of cement leaving 100' of cement inside casing.
- 6 If casing does not have a leak perforate casing at 2500' and set a cement plug 2500' to 2400' in and outside casing to isolate Mesaverde.
- 7. Pull out of hole to 950' and set a cement plug 950' to 750' inside casing.
- 8. Pull out of hole to 250' and set a cement plug 250'-150' inside casing.
- 9. Set a top plug and dry hole marker.
- 10 Fill pits, clean and level location.
 - All plugs will be with neat cement with or without an accelerator.