


MicroBind Case Study – Osage County, OK

Timeline

5/15/12 – Collect initial samples to vertically/horizontally delineate impacted area

Site Map



| 5/15/12 Analytical Results | | |
|----------------------------|-----------------|-----------------------------------|
| Sample ID | Depth (ft. bgs) | Total Soluble Salts Results (ppm) |
| 001 | 0 | 10,300 |
| 001A | 1 | 1,290 |
| 001B | 2 | 3,080 |
| 002 | 0 | 5,690 |
| 002A | 1 | 1,870 |
| 002B | 2 | 1,100 |
| 003 | 0 | 7,840 |
| 003A | 1 | 780 |
| 004 | 0 | 7,170 |
| 004A | 1 | 76.3 |
| 004B | 2 | 717 |

*ft. bgs = feet below ground surface, ppm = parts per million

Results indicated Total Soluble Salts (TSS) levels above the Oklahoma Corporation Commission (OCC's) action level of 2,640 ppm in Sample IDs 001, 001B, 002, 003, and 004.

5/24/12 – Perform remediation services:

- Till the impacted area
- Incorporate gypsum and manure into the surface of the impacted area
- Seed the impacted area
- Treat the impacted area with a MicroBind solution

9/19/13 – Collect confirmation sample from previous sample location

| Comparison of Analytical Results from Pre and Post Remediation | | | | |
|--|-----------------|---|--|---|
| Sample ID | Depth (ft. bgs) | Pre-Remediation Total Soluble Salts Results (ppm) | Post-Remediation Total Soluble Salts Results (ppm) | Δ Total Soluble Salts Results (ppm) |
| 003 | 0 | 7,840 | 2,470 | -5,370 |

Analytical results indicated significant reductions in sample location 003. Full vegetative growth was noted at the time of sampling.




Figure 1: Comparison Graph of Pre and Post Remediation TSS Results

Photographic Documentation of Remediation:



Photograph 1: Pre-Remediation Impacted Area



Photograph 2: Pre-Remediation Impacted Area



Photograph 3: Pre-Remediation Impacted Area



Photograph 4: Pre-Remediation Impacted Area



Photograph 5: Impacted area after incorporation of manure



Photograph 6: Impacted area after incorporation of manure



Photograph 7: Impacted area after incorporation of gypsum



Photograph 8: Treating the impacted area with a MicroBind solution



Photograph 9: Treating the impacted area with a MicroBind solution

Photographic Documentation of Site at September 2013 Confirmation Sampling:



Photograph 10: Site 16 Months Post-Remediation



Photograph 11: Site 16 Months Post-Remediation



Photograph 12: Site 16 Months Post-Remediation



Photograph 13: Site 16 Months Post-Remediation