District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S, First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fc, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	NAB1901739559
District RP	2RP-5185
Facility ID	
Application ID	pAB1901733711

Release Notification

Responsible Party

Responsible Party XTO Energy				OGRID	5380		
Contact Name Tyler Newton				Contact T	Contact Telephone 575-361-1583		
Contact ema	Contact email tyler_newton@xtoenergy.com				# (assigned by OCD) NAB1901739559		
Contact mail	Contact mailing address 522 W. Mermod, Carlsbad, NM 88220						
Location of Release Source							
Latitude 32.248211 Longitude -103.887081							
			(NAD 83 in dec	cimal degrees to 5 deci			
Site Name PL	Site Name PLU CVX JV RB 001H				Pipeline ROW		
Date Release	Discovered	1-5-19		API# (if ap	API# (if applicable) 30-015-40660		
Unit Letter	Section	Township	Danga	Cou			
			Range	Cou			
F	4	T24S	R30E	Edo	dy		
Surface Owner	r: State	🔀 Federal 🗌 Tr	ribal Private (1	Vame:	Y		
	_						
			Nature and	l Volume of	Release		
	Materia	l(s) Released (Select al	l that apply and attach	calculations or specific	ic justification for the volumes provided below)		
☐ Volume Released (bbls) 40.5					Volume Recovered (bbls) 1		
Produced Water		Volume Released (bbls)			Volume Recovered (bbls)		
			ion of total dissolv		☐ Yes ☐ No		
Condensa	te		water $\geq 10,000$ mg	/1?	Volume Recovered (bbls)		
Natural Gas Volume Released (Mcf)					Volume Recovered (Mcf)		
Other (describe) Volume/Weight Released (provide units)			Released (provide	e units)	Volume/Weight Recovered (provide units)		
Cause of Release A release was discovered from a 6" buried oil pipeline at the aforementioned GPS coordinates. The release orginated							
on the pipeline KOW and howed west into the pasture. Freminiary findings point to internal corrosion in the 6 0 clock							
postion on a weld as the cause. A vac truck was dispatched to empty the remaining fluid in line, and was able to							
recover approximately 1 bbl from the surface. The line was clamped until further repairs can be made. Environmental contractor has been retained to assist with remediation.							
	Simue	oven retain	to about with It	modulion.			

State of New Mexico Oil Conservation Division

Incident ID	NAB1901739559	
District RP	2RP-5185	
Facility ID		
Application ID	pAB1901733711	

Was this a major	If YES, for what reason(s) does the respon	nsible party consider this a major release?				
release as defined by	The release was greater than 25 barrels.	party consider and a major receiver				
19.15.29.7(A) NMAC?	and the second that greater than all the second that all the second than all the second that all the second than all the second the second than all the second than all the second than all the second the second than all the second than all the second the second the second than all the second the second than all the second the second the second than all the second the second than all the second the second the second the second the second the se					
⊠ Yes □ No						
IEVEC i li-t-	attended to the company of the compa	0 W/ 11 1 () ()				
	_	nom? When and by what means (phone, email, etc)?				
Yes, on 1-6-19 at 11:20AM Bryan Foust sent a notification email to Mike Bratcher, Robert Hamlet, Jim Amos, Shelly Tucker, and Jim Griswold.						
Initial Response						
The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury						
➤ The source of the rele	ase has been stopped.					
★ The impacted area has	s been secured to protect human health and	the environment.				
■ Released materials ha	we been contained via the use of berms or co	ikes, absorbent pads, or other containment devices.				
★ All free liquids and re	coverable materials have been removed and	d managed appropriately.				
If all the actions described	l above have <u>not</u> been undertaken, explain	why:				
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.						
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.						
Printed Name: Tyler New	rton	Title: SHE Technician				
Signature:	N~~	Date: 1-10-19				
email: tyler_newton@xto	energy.com	Telephone: <u>575-361-1583</u>				
OCD Only Received by:	a Dotamente	Date:1/17/2019				