State of New Mexico Submit 3 Copies to Appropriate Form C-103 Energy, Minerals and Natural Resources District Office Revised March 25, 1999 DISTRICT WELL API NO. 1625 n. French Dr., Hobbs, NM 88240 OIL CONSERVATION DIVISION DISTRICT II 30-015-31173 811 South First, Artesia, NM 88210 Indicate Type of Lease 2040 South Pacheco STATE X DISTRICT III FEE Santa Fe. NM 87505 1000 Rio Brazos Rd., Aztec, NM 87410 State Oil & Gas Lease No. DISTRICT IV 2040 S. Pacheco, Santa Fe, NM 87505 B-2071 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A Lease Name or Unit Agreement Name: DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS) Geronimo "27" State RECEIVED X Oil Well Gas Well Other Name of Operator Well No. MAR 2 5 2005 1 Dominion Oklahoma Texas Exploration & Production, Inc. OCU.ANTERIA Address of Operator Pool name or Wildcat 14000 Quail Springs Parkway - Suite 600 - Oklahoma City, OK 73134 Empire: Penn Well Location :700 Unit letter feet from the South line and 1850' feet from the East line. 27 **17S** Section Township Range **NMPM** Eddy County 10. Elevation (Show whether DR, RKB, RT, Gr, etc.) 3668 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: X PERFORM REMEDIAL WORK **PLUG AND ABANDON** REMEDIAL WORK **ALTERING CASING CHANGE PLANS** COMMENCE DRILLING OPNS. **TEMPORARILY ABANDON PLUG AND ABANDONMENT** MULTIPLE CASING TEST AND CEMENT JOB **PULL OR ALTER CASING** COMPLETION OTHER: OTHER: Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propropsed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. Change to Dominion's previous plans to the P&A of the Geronimo 27 State Com 1. Working interest onwer is requesting to take over the well. Dominion request to plug the well to 4,000', per the attached procedure and schematic. If this work requires an earthen pit, a permit must be approved prior to construction of the pit(s). hereby certify that the information above is true and complete to the best of my knowledge and belief. **3IGNATURE** TITLE Regulatory Specialist DATE 03/21/05 Carla Christian ype or print name 405-749-5263 Telephone No. This space for State use) TITLE Field Supertin DATE 3/29/05 PPROVED BY

onditions of approval, if any


DOMINION EXPLORATION & PRODUCTION

SPUD: 6/18/00 COMPL: 10/23/00 Geronimo 27 State Com 1 Section 27, T-17-S, R-28-E

Empire Field - Eddy County, New Mexico_

ELEV: 3,668' GL 3,689' KB API # 30-015-31173

MKT 3/21/05



Cmt'd wi 925 sx.

Plug & Abandon Procedure GERONIMO "27" STATE COM NO. 1

700' FSL & 1,850' FEL, Sec. 27, T-17-S, R-28-E Eddy County, New Mexico API# 30-015-31173, KB: 3,689' (21' AGL)

- 1. Obtain verbal approval from the New Mexico Oil Conservation Division in Artesia, New Mexico at 505-748-1283 to commence P&A operations. Note details of verbal approval on daily report.
- Blow down tbg. & csg. MIRU WOR. Set tank for displacement and lay lines.
 All displacement fluid to be a salt gel mud consisting of 10# brine w/ 25# of gel per bbl.
 ND wellhead. NU and function test BOP's.
- 3. Unset PLS pkr. @ 7,144' and POOH standing back 2-3/8", 4.7#, P-110 production tbg.
- 4. Run 5-1/2", 17# CIBP on 2-3/8" tbg., set CIBP @ 7,215'. Drop standing valve and pressure test tbg. to 500 psi. Fish standing valve. Rotate out of CIBP, pull EOT 2' off bottom.
- 5. Mix & circulate well w/ 10 ppg mud as noted above. Test CIBP & csg. to 500#.
- 6. RU cementing company. Mix and pump 4 sx. cement (Class C 1.15 ft3/sx.) to spot a 35' cement plug on top of CIBP from 7,109'. Pull setting tool above cement top, reverse circulate to clean tbg. POOH laying down tbg. to 5,050'.
- 7. Mix and pump 15 sx cement to spot a minimum 100' cement plug from 4,950' to 5,050'. Pull setting tool above cement top, reverse circulate to clean tbg. Wait on cement and tag to verify depth. POOH laying down tbg. to 4,100'.
- 8. Mix and pump 15 sx cement to spot a minimum 100' cement plug from 4,000' to 4,100'. Pull setting tool above cement top, reverse circulate to clean tbg. POOH & LD tbg.
- 9. RDMO cementing equip., BOP's and WOR. NU wellhead.
- 10. Clean location. Turn well over to working interest owner.