Submit 1 Copy To Appropriate District State of New Mexico	Form C-103
<u>District 1</u> –(575) 393-6161 Energy, Minerals and Natural Resources	Revised August 1, 2011 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283	30-015-31368
811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III – (505) 334-6178 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410 0	STATE S FEE
<u>District IV</u> $-$ (505) 476-3460 Santa Fe, NM 8/505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	VB-71
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	
PROPOSALS.)	Pawnee State 8. Well Number 2
1. Type of Well: Oil Well Gas Well Other	
2. Name of Operator COG Operating, LLC	9. OGRID Number 229137
3. Address of Operator	10. Pool name or Wildcat
One Concho Center, 600 W. Illinois Ave., Midland, TX 79701	Loco Hills;Glorieta-Yeso (96718)
4. Well Location	
Unit Letter <u>G</u> : <u>1650</u> feet from the <u>North</u> line and <u>2290</u> feet from the <u>East</u> line	
Section 16 Township 17S Range 30E	NMPM County Eddy
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
3648 GR	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A	
	· · ·
OTHER: Deepen OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and	give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of	
proposed completion or recompletion.	
COG Operating LLC respectfully request to deepen the Pawnee State #2 in the Yeso.	
coo operating the respectantly request to deepen the rawnee state #2 in the reso.	
See Attachment for Deepening and Completion procedures.	
r and a second	
· ·	DEC 12 2012
NMC	DCD ARTESIA
Spud Date: Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE 7 - TITLE Regulatory Analyst DATE 12/10/12	
Type or print name <u>Brian Maiorino</u> E-mail address: <u>bmaiorino@concho.com</u>	PHONE: _ <u>432-685-4332</u>
For State Use Only	
APPROVED BY: NOade TITLE Dist BSperson DATE DATE	
Conditions of Approval (if any):	

\$

£

Pawnee State #2 30-015-1368

Deepening Procedure

- 1. MIRU rig.
- 2. LD production equipment
- 3. Sqz upper Yeso w/ +/-400sx of Class C neat.
- 4. Drill out squeeze. Test squeeze to 500 psi for 20 minutes using chart recorder.
- 5. PU 4-3/4" bit and drill 4-3/4" from 4832' to 6050'.
- 6. POOH w/ bit and drillstring.
- 7. RIH w/ logs and log from TD to 4800'.
- 8. RIH w/ 4", 11.3# casing. See next attachment for general centralizer program.
- 9. Cement casing from TD to 4754' w/ 115 sxs Class C cmt. Drop plug and open DV tool. Circ cmt off DV tool. Drop plug to close DV tool.
- 10. PU workstring and RIH and drill out DV tool. POOH and LD workstring.
- 11. RDMO rig.

Completion Procedure

- 1. MIRU rig.
- 2. RIH/ w/ perforating guns and perforate Yeso from 5500'-5700 w/ 1 spf, 28 holes.
- 3. Acidize w/ 2500 gals of 15% HCl. Frac zone w/ 179,800 # of sand. Set plug at 5450'.
- 4. RIH w/ perforating guns and perforate Yeso from 5200-5400.
- 5. Acidize w/ 2500 gals of 15% HCl. Frac zone w/ 179,800 # of sand. Set plug at 5150'.
- 6. RIH w/ perforating guns and perforate Yeso from 4900-5100.
- 7. Acidize w/ 2500 gals of 15% HCl. Frac zone w/ 179,800 # of sand.
- 8. RIH and drill out plug at 5450' and 5150'.
- 9. RIH and cut or back off 4" casing at 4754'. POOH w/ 4" casing. Leave 4" liner from 4754' to 6050' (TD).
- 10. RIH w/ tbg and locate end of tbg at 4700'.
- 11. RIH w/ rods and pump.
- 12. RDMO rig.

