Submit 1 Copy To Appropriate District S	tate of New Mexico	Form C-103
District I Energy, M	inerals and Natural Resources	October 13, 2009 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II	SERVATION DIVISION	30-015-02746
1501 W. Oland Ave., Altesia, Will 00210	Servation Division	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	anta Fe, NM 87505	STATE FEE 6. State Oil & Gas Lease No.
District IV 1220 S. St. Francis Dr., Santa Fe, NM		E-134
87505 SUNDRY NOTICES AND REPC	RTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR DIFFERENT RESERVOIR. USE "APPLICATION FOR PERM	TO DEEPEN OR PLUG BACK TO A	SKELLY ST
PROPOSALS.) 1. Type of Well: Oil Well Gas Well O	ther	8. Well Number 6
2. Name of Operator		9. OGRID Number
Alamo Permian Resources. LLC	1	274841
 Address of Operator 415 W. Wall Street, Suite 500, Midland, TX 7970 	1	10. Pool name or Wildcat HIGH LONESOME;QUEEN
4. Well Location		
Unit Letter \underline{G} : <u>1980</u> feet from the <u>N</u> line	and 1980 feet from the E line	
	wnship 16S Range 29	E NMPM County EDDY
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
PERFORM REMEDIAL WORK PLUG AND AB		
TEMPORARILY ABANDON 🔲 CHANGE PLAI		
PULL OR ALTER CASING MULTIPLE CO		ГЈОВ
OTHER:	OTHER:	
13. Describe proposed or completed operations.	(Clearly state all pertinent details, and	d give pertinent dates, including estimated
date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
proposed completion or recompletion.	the second se	
	Approved for plugging of well bore only. Liability under bond is retained pending rec	
*See Attached File Current C103 P&A	of C-103 (Subsequent Report of Well Pluggi which may be found at OCD Web Page under	(rig) JAN 28 2013
for final inspection.	Forms, www.emnrd.state.nm.us/ocd.	NMOCD ARTESIA
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE Carle Stoker	TITLE <u>Regulatory Affairs Coordinator</u> DATE <u>01/25/2013</u>	
Type or print name <u>CARIE STOKER</u>	E-mail address: <u>cstoker@alamoreso</u>	purces.com PHONE: <u>432.664.7659</u>
For State Use Only		
APPROVED,		
BY: The life. TITLE	ļ	DATE 1/29/2013
Conditions of Approval (if any):		
Conditions of Approval (11 any).	Approved for plugging of well bore only.	
	Diachity under bond is recained must	lipt
	which may be found at OCD Web Page und	
	Forms, www.cmnrd.state.nm.us/ocd.	
		- AW
		4

<u>1/17/13</u>

MIRU Aztec, unhang head. ND pumping T, POOH laying down w/ (71) 5/8 rods, (1) 2' 3/4sub. (1) 12' 1.5 pump w/ 6"gas anchor NU BOP, picked up 1 1/2 joints 2 3/8 tubing tagged bottom. Laid down 1 1/2 joints on ground . POOH w/ 30stands and one single of 2 3/8 tbg into derrick and laid down single strapped pipe @ 1848'. Closed BOP.

<u>1/18/13</u>

Open BOP. Well had 0 psi. RIH w/ 61 joints of 2 3/8 tbg @1878'. Rig up pace setter pumping services, pressured up on lines @ 6000psi, lines held. Bleed lines down. Pumped 35 bbls f/wwell started circulating. Pumped another 10 bbls @ rate of 2.0,= 45bbls.Switched to cement and pumped 12bbls of Class C cement rate @2.0, =50 sx cement, cement plug should have been @1546'. PUH w/14 stands into derrick. Revers with 5.8bbls f/w. Moved in Vortec backhoe dig out celler looking for surface casing. Found casing 4'deep there was no flange. 8 5/8 surface casing was cut and open around 4 1/2 casing. RIH w/ 10 stands, should have tagged cementplug. There was no plug. POOH w/ pipe into derrick. Rigged up wireline, RIH w/ collar locator and 2' gun. Tagged bottom @ 1837'.POOH w/ wireline. Closed bop.

1/21/13

Open BOP. Well had 0 psi. RIH w/ 61 joints @1878'. Pumped 35 bbls f/w. Broke circulation. Swithed to cement, pumped 12 bbl cement =50sx. Also pumped 12 1/2 # cello flake, pumped 2%calcuim=100lb. As soon as we stop pumping the well went on a vacume, it took everything left over that was in the tub. POOH into derrick with tubing, MIRU black worrior wireline. RIH w/ 5 1/2 CIBP set plug @ 1750'. POOH with wire line, RIH w/ 59 joints. Tagged CIBP @1735 (according to pipe tally). POOH laying down 34 joints on ground, leaving 14 stands in derrick. Waited 3 hrs, RIH w/ 2' gun tagged cement plug @1123'. PUH to 873' shot perfs=4 holes. POOH w/ wire line, picked up 2 3/8 x 5 1/2 packer. RIH w/ 14 stands @ 840' tried to set packer but wouldn't . PUH laying down 1 joint, set packer @ 815'. Rigged up cement lines. Pumped @ 1.0 rate w/ 160 psi broke circulation w/ 5bbl pumped 15bbl f/w . Rig down cement lines. Unset packer. POOH laying down tbg and packer. Closed BOP. Rigged up cement lines to back side of 5 1/2 casing. Pumped f/w broke circulation w/ 4 bbl rate @ 2.0 psi @ 160. Switched to cement, pumped @ rate of 2.0. Pressure dropped from 160 psi to 11 psi while pumping. Pumped 70bbls = 295 sx cement but never did see any cement on returns (all water).

<u>1/22/13</u>

RIH w/ 28 joints and 2 3/8 x 5 1/2 packer. Set packer . Broke circulation w/ 3 bbl f/w. Swithched to cement, pumped 28.8bbl=121sx. Got cement to surface through 8 5/8 casing. Switched to water, pumped 3.2bbl. Waited 2 hr then unset packer. POOH w/ tubing laying them down. Rigged up cement hose and topped off cement in 5 1/2 casing w/ 20 bbl = 84 1/2 sx.

1/25/13

PA marker installed.