Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103
District 1 (575) 202 (1(1	Example and Matural Deservation	Revised August 1, 2011
District I – (575) 393-6161	Energy, Minerals and Natural Resources	WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283	OUL CONSERVATION DUVISION	30-015-21486
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE 🛛 FEE 🗌
District IV - (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		B-10715
(DO NOT USE THIS FORM FOR PROPO	ICES AND REPORTS ON WELLS SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A CATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name ARTESIA STATE UNIT
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well 🛛 Other	8. Well Number 602
2. Name of Operator		9. OGRID Number
Alamo Permian Resources. LLC	, <u>, ,</u>	274841
3. Address of Operator		10. Pool name or Wildcat
415 W. Wall Street, Suite 500, M	idland, TX 79701	Artesia; Queen-Grayburg-San Andres
4. Well Location		
Unit Letter L : 1530 f	Teet from the S line and 1310 feet from the W	line
Section 13	Township 18S Range 27E	NMPM County EDDY
	11. Elevation (Show whether DR, RKB, RT, GR, et	c.)
PULL OR ALTER CASING		NT JOB
OTHER:		RETURN TO PRODUCTION
<ol> <li>Describe proposed or complete of starting any proposed wort proposed completion or recompletion</li> </ol>	eted operations. (Clearly state all pertinent details, an rk). SEE RULE 19.15.7.14 NMAC. For Multiple Co	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of
<ol> <li>Describe proposed or complete of starting any proposed wor proposed completion or recompletion</li> </ol>	eted operations. (Clearly state all pertinent details, an rk). SEE RULE 19.15.7.14 NMAC. For Multiple Co	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of
<ol> <li>Describe proposed or complete of starting any proposed wor proposed completion or recompletion</li> </ol>	eted operations. (Clearly state all pertinent details, an rk). SEE RULE 19.15.7.14 NMAC. For Multiple Co	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of
<ol> <li>Describe proposed or complete of starting any proposed wort proposed completion or recompletion</li> </ol>	eted operations. (Clearly state all pertinent details, an rk). SEE RULE 19.15.7.14 NMAC. For Multiple Co	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of
<ol> <li>Describe proposed or complete of starting any proposed wort proposed completion or recompletion</li> </ol>	eted operations. (Clearly state all pertinent details, an rk). SEE RULE 19.15.7.14 NMAC. For Multiple Co	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of The Perform Welk. Testi RECEIVED FEB 06 2014
<ul> <li>13. Describe proposed or completion of starting any proposed wor proposed completion or recorder attached</li> <li>OCA</li> <li>OCA</li> <li>OCA</li> <li>OCA</li> <li>OCA</li> </ul>	Eted operations. (Clearly state all pertinent details, an rk). SEE RULE 19.15.7.14 NMAC. For Multiple Co ompletion. ) NOT NOTIFICO OF INTO NOT NOTIFICO OF MIT NOT NOTIFICO OF MIT NOT WITNESSED BY	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of TT Perform WYK PEST, RECEIVED FEB 06 2014 NMOCD ADTEST
<ul> <li>13. Describe proposed or completion of starting any proposed wor proposed completion or recorder attached</li> <li>OCA</li> <li>OCA</li> <li>OCA</li> <li>OCA</li> <li>OCA</li> </ul>	eted operations. (Clearly state all pertinent details, an rk). SEE RULE 19.15.7.14 NMAC. For Multiple Co	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of TTPREFORM WYK RECEIVED FEB 06 2014 NMOCD APTER
<ul> <li>13. Describe proposed or completion of starting any proposed wor proposed completion or recorder attached</li> <li>OCA</li> <li>OCA</li> <li>OCA</li> <li>OCA</li> <li>OCA</li> </ul>	Eted operations. (Clearly state all pertinent details, an rk). SEE RULE 19.15.7.14 NMAC. For Multiple Co ompletion. ) NOT NOTIFICO OF INTO NOT NOTIFICO OF MIT NOT NOTIFICO OF MIT NOT WITNESSED BY	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of
13. Describe proposed or completion of starting any proposed wor proposed completion or recorder attached         ee attached       OCA         Build of the starting any proposed completion or recorder attached       OCA         hereby certify that the information attached       Test         IGNATURE       CARIE STO	Eted operations. (Clearly state all pertinent details, an rk). SEE RULE 19.15.7.14 NMAC. For Multiple Co ompletion. NOT NOTIFIED OF INTE NOT NOTIFIED OF MUT TO NOT WITHES OF BY bove is true and complete to the best of my knowledg TITLE <u>Regulatory Affairs Con</u> KER_E-mail address: carie@stokeroilfield.com	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of
13. Describe proposed or completion of starting any proposed wor proposed completion or recorder attached         ee attached       OCA         be attached       OCA         icon       OCA         icon<	Eted operations. (Clearly state all pertinent details, an rk). SEE RULE 19.15.7.14 NMAC. For Multiple Co ompletion. NOT NOTIFIED OF INTE NOT NOTIFIED OF MUT TO NOT WITHES OF BY bove is true and complete to the best of my knowledg TITLE <u>Regulatory Affairs Con</u> KER_E-mail address: carie@stokeroilfield.com	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of
13. Describe proposed or completion of starting any proposed wor proposed completion or recorder attached         ee attached       OCA         Build of the starting any proposed completion or recorder attached       OCA         inereby certify that the information attached       OCA         IGNATURE       CARIE STO	Eted operations. (Clearly state all pertinent details, an rk). SEE RULE 19.15.7.14 NMAC. For Multiple Co ompletion. NOT NOTIFIED OF INTE NOT NOTIFIED OF MUT TO NOT WITHES OF BY bove is true and complete to the best of my knowledg TITLE <u>Regulatory Affairs Con</u> KER_E-mail address: carie@stokeroilfield.com	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of TPRECEIVED FEB 06 2014 MOCD ANTESIA e and belief. DATE_01/31/2014
13. Describe proposed or completion of starting any proposed wor proposed completion or record etatached         be attached         000         787         nereby certify that the information a         GNATURE         000         011         020         020         020         021         022         023         024         025         026         026         027         026         027         026         027         026         027         028         029         029         029         029         029         029         029         029         0200         0200         0200         0200         0200         0200         0200         0200         0200         0200         0200         0200         0200         0200         0200	Eted operations. (Clearly state all pertinent details, an rk). SEE RULE 19.15.7.14 NMAC. For Multiple Co ompletion. NOT NOTIFIED OF INTE NOT NOTIFIED OF MUT TO NOT WITHES OF BY bove is true and complete to the best of my knowledg TITLE <u>Regulatory Affairs Con</u> KER_E-mail address: carie@stokeroilfield.com	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of The Perform Welk. RECEIVED FEB 06 2014 MOCD ANTESIA e and belief. DATE_01/31/2014

.

# ARTESIA STATE UNIT #602 WIW (formerly #002)

AFE Est. Gross Cost:	Perfs:
Lease: B-10715	Spud: 03/11/75
1530 FSL & 1310 FWL	P&A: n/a
Pool: 3230 - ARTESIA; Queen-Grayburg-SA	

<u>11/11/13</u>

MIRU PU. No pressure on well. Problems nippling down wellhead (top cap rusted up, trouble removing slips from head & unscrewed wellhead to get slip bowl out). NU BOP. Work stuck pkr loose & POOH w/pkr dragging. POOH w/2-3/8" IPC tbg, cup-type compression pkr & 2-1/2" jts of tailpipe. Left 1-1/2 jts of 2-3/8" tbg & 4-1/2"x10.5"x2-3/8" Watson J-Lock pkr in well. SDFN w/well venting to frac tanks.

# <u>11/12/13</u>

RIH w/overshot w/cut-lip guide & 2-3/8" grapple. Tag parted tbg. Work to catch fish without success. POOH w/overshot. Small chunk of rubber in overshot. Clean out overshot & change grapple to 2-5/16". RIH & tag fish. Worked & rotated to get dwn over fish with no success. POOH with overshot. Wait on drill collars & shoe. PU 3-3/4"x5" notched shoe without cutrite, 3¾" OS with 2-5/6" grapple, XO, (4) 3-1/8" drill collars, XO on 2-3/8" tbg to 1500". SDFN. Well venting to frac tanks.

#### 11/13/13

Finish RIH w/fishing BHA. Tag rubber & rotate 5.00' & tried to catch fish. Indicated fishing tool tried to get over fish. PU 2k over weight & slipped off. Tried to catch fish without success. POOH. LD shoe & changed out 2-3/8" grapple with 2-5/16" grapple. RIH w/overshot. Worked to catch tubing without success. POOH. Broke down fishing tool. Found folded-over piece of tubing wedged in control in overshot. SDFN. Well venting to tanks.

# <u>11/14/13</u>

MIRU reverse unit. PU 5.00' cut-lip guide, flat bottom mill, (4) 3-1/8" DCs, bumper sub & jars. MI, set pipe racks & off-load 68 jts 2-3/8" WS. Tally & RIH w/milling assembly. Tag fish. NU stripperhead & RU swivel. Broke circ, tag fish. Dress off 4.00' of tbg. Full returns while milling & circ clean in 30 mins. RD swivel & ND stripperhead. POOH w/milling assembly & LD. PU 3-3/4" OS with 2-3/8" grapple, (4) 3-1/8" DCs, bumper sub & hydraulic jars on 2-3/8" L80 tbg to 1700'. Vent well to tanks. SDFN.

### <u>11/15/13</u>

Finish RIH w/OS. Latch fish & release pkr. POOH w/tbg & partial fish. Retrieved 1-1/2 jts tbg & partial pkr consisting of top connection, top set of slips, & 4' of pkr mandrel. Rubbers, sleeve, bottom slips & J-slot left in well. Vent well to frac tanks. SDFN.

#### 11/16/13

PU 3-3/4" flat-bottom shoe w/cutrite on bottom (wire & diamonds inside), 7.00'x3-3/4" extension, bumper sub, hydraulic jars, (4) 3-1/8" DCs on 2-3/8" WS. Tag top of fish @ 1854'. NU stripperhead & RU swivel. Mill pkr rubbers & spacers dwn to gauge ring. Had problems milling pkr due to spacers & ring spinning. PU on drill string & could not go back down. LD swivel & top jt w/3000 lbs drag. ND stripperhead & POOH slow. Recovered all pkr parts except btm 1' of mandrel & bottom lugs. LD shoe, jars & bumper sub. Closed BOP & vent well to frac tanks. SDFWE.

#### 11/17/13

RIH w/3-7/8" bit, XO, (4) 3-1/8" DCs, XO on 2-3/8" L80 WS. Tag @ 1865'. Broke circ, wash & rotate to 1869'. Quit making hole due to packer mandrel left in the hole (mandrel should have dropped to bottom but it is embedded in paraffin, iron sulfite & sand plug below it). Circ well clean. POOH w/bit. Inside of bit worn from trying to push mandrel thru dehydrated plug. Well venting to frac tanks. SDFN.

#### 11/18/13

RIH w/3-3/4" conventional notched shoe, hydraulic jars, (4) 3-1/8" DCs on 2-3/8" WS. Tag @ 1869'. RU swivel & NU stripperhead. Wash dwn to 1774'. Plugged shoe. POOH. Plug fell out while POOH. RIH w/same mill. Tag & clean out to tight spot @ 1881'. Could not work past tight spot. Circ clean & POOH. LD shoe, jars & DCs. Note: Bottom of shoe flared out. PU 2-3/8" muleshoe on 2-3/8" WS to 1881'. Circ & try to work tbg below 1881' without success. LD 10 jts of 2-3/8" tbg & SWI. SDFN.

#### 11/19/13

No SIWP. LD WS & prep to RIH w/pkr. Wait on undersize test tools (ID smaller than normal). PU 4-1/2"x10.5#x2-3/8" AD1 plastic-coated pkr. Test tbg in the hole to 3000 psi, ok. Set pkr & try to EIR. Tbg pressured to 1000 psi & leaked off to 200 psi in 10 mins: Bled off pressure. Pumped 75 bbls w/pkr fluid until clean. Set pkr. ND BOP, NU WH. Test pkr & csg to 500 psi for 30 mins w/chart, OK. No pressure decrease. RD kill truck. SWI. SDFN. DC: \$12,800 CTD: \$100,550 *from: S. Cockrum* 

	Description		Length	Depth
50		КВ	3.00'	3.00'
DING	58	jts 23/8" J55 EUE 8rd Tubing	1739.66'	1742.66'
5		AD1 Plastic-cCoated 4-1/2"x10.5#x2-3/8" Packer		
-	1	with 14K Tension	3.00'	1745.66'


11/21/13

ł

Cleaned location. RDMO. Well shut in, waiting on acid job.

## 01/22/14

Hook up acid truck to pressure truck. Hooked 2" steel line to tubing w/valve. Pumped 1 bbl fresh to try & get a rate. Well pressured up to 500 psi. Wait 10 mins, well bled down 150 psi @ 350 psi on tubing. Switched to acid & pumped ¼ bbl through tubing with 550 psi on tbg. Waited 10 mins. Proceeded to pump into well for two hours little by little. Pumped total of 9 bbls and finally started to lose PSI faster while pumping. Waited 30 mins then started pumping with acid w/rate .5 bbl min, PSI @ 500. Acid broke through perfs. PSI dropped from 500 to 100 PSI. Started pumping @ rate of 1.5 bbl min w/1800 psi. 1800 psi, 1.5 bbl min (acid). Pumped all acid down with max rate @ 1.5 w/1800 psi. Switched to fresh water, filled tbg w/9 bbl. Max rate on fresh was 1.5 w/1300 psi. Closed valve on tbg. Rig down acid truck and pump truck. Replaced injection pump with new pump. Note: Max PSI 1800 w/rate 1.5. Pumped a total of 37 bbl of acid w/demulsifier, paraffin solvent, booster, scale inhibitor.



ь.»