Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103		
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources	Revised July 18, 2013 WELL API NO.		
District II - (575) 748-1283	OIL CONSERVATION DIVISION	30-015-22404		
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178	1220 South St. Francis Dr.	5. Indicate Type of Lease		
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	STATE FEE 6. State Oil & Gas Lease No.		
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Saina 1 0, 1111 07303	o. State Off & Gas Lease No.		
87505 SUNDRY NOT	ICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPO	DSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	DONALDSON COM A		
DIFFERENT RESERVOIR. USE "APPL" PROPOSALS.)	ICATION FOR PERMIT" (FORM C-101) FOR SUCH	8. Well Number		
1. Type of Well: Oil Well	Gas Well Other	1		
2. Name of Operator	,	9. OGRID Number		
VANGUARD PERMIAN LLC 3. Address of Operator		258350 10. Pool name or Wildcat		
5847 San Felipe Suite 3000, Hous	ton, Texas 77057	East Loving Brushy Canyon		
4. Well Location				
Unit LetterF:	1930feet from theNorth line and23	03feet from theWestline		
Section 23	Township 23S Range 28E			
	11. Elevation (Show whether DR, RKB, RT, GR, etc.	c.)		
	<u> </u>			
12. Check	Appropriate Box to Indicate Nature of Notice	, Report or Other Data		
		SSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WOI			
TEMPORARILY ABANDON		RILLING OPNS. PANDA		
PULL OR ALTER CASING	MULTIPLE COMPL CASING/CEMEN	NT JOB		
DOWNHOLE COMMINGLE				
CLOSED-LOOP SYSTEM OTHER:	☐ OTHER:			
13. Describe proposed or comp	pleted operations. (Clearly state all pertinent details, a			
of starting any proposed w	ork). SEE RULE 19.15.7.14 NMAC. For Multiple Co	ompletions: Attach wellbore diagram of		
proposed completion of rec	ompietion.			
-				
	SEE ATTACHMENT			
	SEE MI MEINIENI			
		·		
•				
Spud Date:	Rig Release Date:			
Space.	Alg Release Date.			
I hereby certify that the information	above is true and complete to the best of my knowled	ge and belief.		
		•		
SIGNATURE MY HE	ard TITLE AGENT	DATE 3-18-14		
OIGHATORE TO THE	IIIE AGENI			
	ARD E-mail address: _gheard@oilreportsinc.com	n PHONE:575-393-2727		
For State Use Only	1	./ /		
APPROVED BY:	idl TITLE DISTA Spewson	DATE 3/25/2014		
Conditions of Approval (if any):				

VANGUARD PERMIAN LLC

DONALDSON COM A #1

1930/N & 2303/W API #30-015-22404 Sec 23 T23S R28E

Procedure:

31. 32.

33.

34.

MIRU completion rig and test anchors. 1. Kill well with 2% KCL water, if necessary. Unseat pump and POOH w/ rods and 2. pump. ND WH and NU BOP. Release TAC and POOH w/ tubing. Lay out 2-7/8" tubing. 3. PU, strap and TIH with 6-3/4" bit, 7-5/8" casing scraper and 3-1/2" frac 4. string tubing. Clean out hole to 6130' until clean returns, POOH MI wireline w/ packoff. RIH CIBP, GR/CCL & correlate 5. Set the CIBP @ ~6120', dump bail 2 sks cement on top. 6. MU 3-1/8" casing guns set at 4 spf, 120° phasing (0.38" hole, 39.5" 7. penetration). Perforate as follows: 6014' - 6036' (22', 88 shots) a. 9. RD wireline. PU a 7-5/8" Arrowset I packer and RIH to ~6000'. Load tubing/hole with 2 % KCl 10. and set packer. 11. MIRU pump truck and test lines to 4500 psi. 12. Pump 4000 gals 7.5% NEFE acid with rock salt. Pump 500 gal then pump rock salt over next 2000 gals. a. Pump last 1500 gals and flush to 6094'. b. c. Record ISIP, 5 min, 10 min and 30 min. 13. RU swabber and swab well in to test acid job. Recover load and report fluid/gas entry. 14. Release packer and POOH. MI wireline w/ packoff. RIH CBP, GR/CCL & correlate **15.** 16. Set the CBP @ ~5900'. MU 3-1/8" casing guns set at 2 spf, 120° phasing (0.38" hole, 39.5" penetration). 17. 18. Perforate as follows: 5838' - 5850' (12', 24 shots) a. RD wireline. 19. PU a 7-5/8" Arrowset packer and 3-1/2" tubing and RIH with tubing to ~5760' and 20. set packer. MIRU pump truck (with 2000 gals acid) and test lines to 4500 psi. 21. Pump 1000 gals 7.5% NEFE acid with 20 ball sealers. a. b. Pump last 1000 gals and flush to 5850'. Record ISIP, 5 min, 10 min and 30 min. С. Wait at least 1 hr then RU swabber and swab well in to test acid job. Recover load 22. and report fluid/gas entry, if possible. 23. RDMO completion rig. 24. Call out 3-500 bbl tanks & fill with 2% KCl water. Install frac valve in preparation for frac job down 3-1/2" tubing. 25. RU frac Co. and test lines & pump as per frac schedule. 26. Monitor ISIP, 5 min, 10 min, 15 min. Flowback until well dies. Rig down frac valve and release frac tanks. 27. 28. MIRU completion rig. 29. Load hole and release packer, POOH and lay out 3-1/2" frac string tubing. 30. PU a 4-3/4" bit, sand bailer and 2-7/8" tubing and RIH. Clean out the well as needed and knockout the CBP to produce the LBC B, A and AA.

RIH w/ 7-5/8" TAC, SN and 2-7/8" tubing.

RIH w/ rods and pump.


Turn well on to production.

RD & MO.



Donaldson Com A #1 Loving East - 30-015-22404 Eddy County, New Mexico

COMPLETION - 3/2014



District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone: (575) 748-1283 Fax: (575) 748-9720
District III
1000 Rio Brazos Road, Aztec, NM 87410
Phone: (505) 334-6178 Fax: (505) 334-6170
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505
Phone: (505) 476-3460 Fax: (505) 476-3462

⁴ Property Code

312394

7 OGRID No.

258350

¹ API Number

30-015-22404

State of New Mexico Energy, Minerals & Natural Resources Department OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-102 Revised August 1, 2011 Submit one copy to appropriate District Office

☐ AMENDED REPORT

⁶ Well Number

1

Elevation

3020.4

3 Pool Name

East loving Brushy Canyon

***	' Y T	$\Delta \Delta \Lambda$	TIANI	A J II	ACREAGE	DEDICA	TIANI DI	λ T
WPI		ли А	11111	ANI	ALKEALTE	T JP.I JIC.A	LILIN PL	Α 1

⁵ Property Name

Donaldson Com A

⁸ Operator Name

VANGUARD PERMIAN LLC

² Pool Code

40350

,			. ,		¹⁰ Surface	Location			
UL or let no.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/West line	County
F	23	23S	28E	, ,	1930	NORTH	2303	WEST	EDDY
		<u> </u>	" Bc	ttom Ho	le Location If	Different Fron	n Surface	· ·	
UL or lot no.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/West line	County
]									
12 Dedicated Acres	¹³ Joint o	r Infill 14 (i Consolidation	Code 15 Or	l rder No.	<u> </u>	I	<u></u>	
320				,					
L									
No allowable v division.	will be ass	signed to th	is complet	tion until a	Il interests have	been consolidated	or a non-standar	d unit has been ap	proved by the
16			Ī				17 O I	PERATOR CERT	TIFICATION
	ĺ							that the information contained	
							to the best of n	ry knowledge and belief, and th	at this organization either
							11	g interest or unleased mineral i	-
							<u>l</u> 1	ottom hole location or has a ri	
							li li	ant to a contract with an owner	=
			j				li li	n voluntary pooling agreement re entered by the division.	or a compulsory pooling
·			ļ	•			/Xuy	Pearo	3-18-14
			l		•		Signature ()		Date '
							Gaye He		
							Printed Name		
·							gheard@oilre	nortsinc.com	
							E-mail Addre		
									•
							"SURV	EYOR CERTI	FICATION
					!		I hereby ce	rtify that the well loca	tion shown on this
							plat was pi	otted from field notes	of actual surveys
							made by m	e or under my supervis	sion, and that the
							same is tru	e and correct to the be	st of my belief.
									· · · · · · · ·
							Date of Surv	AV.	·
							li .	d Seal of Professional Surv	,
							Signature and	a Sear of Professional Surv	eyor.
,									
									
	İ						Certificate Nu	umber	