	•			
Submit I Copy To Appropriate District	State of New Me	avias	Ĕo	rm <i>C</i> -103
Office [] [District I (575) 393-6161	* * :	State of New Mexico Energy, Minerals and Natural Resources		uly 18, 2013
1625 N. French Dr., Hobbs, NM 88240	whore grant and react	arai resorgioes	WELL API,NO.	
District II - (575) 748-1283 811 S. First St., Artesia, NM 88240	NM 88210 OIL CONSERVATION DIVISION 6178 1220 South St. Francis Dr.		30-015-21639	
District III ~ (505) 334-6178			5. Indicate Type of Lease STATE ⊠ FEE	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV (505) 476-3460	s Rd., Aziec, NM 87410		STATE FEE 6. State Oil & Gas Lease No.	<u> </u>
1220 S. St. Francis Dr., Santa Fe, NM 87505			36037	
SUNDRY NOTIC	ES AND REPORTS ON WELLS	ŝ	7. Lease Name or Unit Agreeme	ont Name
(DO NOT USE THIS FORM FOR PROPOSA DIFFERENT RÉSERVOIR, USE "APPLICA	US TO DRILL OR TO DEEPEN OR PL TION FOR PERMIT" (FORM C-101) FO	UG BACK TO A OR SUCH		
PROPOSALS.)			Overshot State 10 8. Well Number 1	
1. Type of Well: Oil Well: Gas Well: Other 2. Name of Operator Rubicon Oil & Gas, LLC			9. OGRID Number 194266	
3. Address of Operator, 508 W. Wall St. Suite 500 Midland, Texas 79701			10. Pool name or Wildcat	
4. Well Location	xas /9/01		Catclaw Draw	
Unit Letter	2141fcct from the South	line and 65	66 foot from the Fact	line
Section 10	Township 21\$	Range 25E	NMPM County Edd	
	11. Elevation (Show whether DR			1
	3363'RKB			
12. Check An	propriate Box to Indicate N	Jature of Notice	Report or Other Data	
			•	
NOTICE OF INTENTION TO: SUPERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ REMEDIAL WO			BSEQUENT REPORT OF: rk —— [] — ALTERING C	ASING T
	CHANGE PLANS		RILLING OPNS PAND A	73.100
	MULTIPLE COMPL	CASING/CEMEN		لسا
DOWNHOLE COMMINGLE			· 	
CLOSED-LOOP SYSTEM DTHER:	, —	OTHER:		T
13. Describe proposed or complet). SEE RULE 19.15.7.14 NMA	pertinent details, a	nd give pertinent dates, including es ompletions: Attach wellbore diagra	stimated date
Rubicon proposed to plug and abandor	the Overshot State 10 No. 1 - S	see attached pluggi	ng procedure and well bore diagram)
CONDITIONS OF APPROVAL ATTACK	_			
approval Granted providing work	ic			
ompleted by 🗸				
HOS 11, 201	5			
				
9 4				
<u> </u>				
Spud Date:	Rig Release D	ate:		
L				
		·		
hereby certify that the information ab	ove is true and complete to the b	est of my knowled	ge and belief.	
SIGNATURE And of this	TITLE R	agola fory	DATE 4-4- Cogman Lean PHONE: 432	14
Type or print name Ann Rite	hie E-mail address	e and with	- ou mail PHONE 432	68463
For State Use Only	1 1		1	
APPROVED BY (1) (1) (1) (2) (2) (2) (2) (2) (3) (4) (4) (4) (4) (4) (4) (4) (4) (4) (4	M TITLE 1013	5 Depe	WISO DATE 4-	11-14
		10		
	Hacked CO.	45		
TY DEC / W	America, Con			
· C - ;				
	• •	•		

Rubicon Oil & Gas, LLC Overshot State 10 No. 1 Section 10 T215 R25E API # 30-015-21639


- 1. MIRU Plugging Equipment. POOH w/Production equipment (If applicable).
- 2. Set 4 ½" CIBP @ 10,300'. Circulate MLF.
- 3. Cap CIBP w/25 sxs "H" cmt.
- 4. Spot 30 sxs "H" cmt @ 8505'-8250'.
- 5. Spot 25 sxs "C" cmt @ 7500'-7400'.
- 6. Spot 25 sxs "C" cmt @ 5100'-5000'.
- 7. Perf & Sqz 25 sxs "C" cmt @ 3500'. WOC & TAG.
- 8. Perf & Sqz 75 sxs "C" cmt @ 2343'. WOC & TAG. Tag no deeper than 1750'.
- 9. Perf & Sqz 25 sxs "C" cmt @ 858'. WOC & TAG.
- 10. Perf & Sqz approx, 110 sxs "C" cmt @ 423'. Circulate cmt to surface inside and out.
- 11. Cutoff wellhead and verify cmt to surface in all strings. Rig down plugging equipment.
- 12. Cutoff anchors and install marker.

Current

Rubicon Oil & Gas, LLC Overshot State 10 No.1 Overshot Prospect Eddy County, New Mexico Producing Wellbore API No. 30-01521639 KB: 3363' GL: 3350'

Re-Entry: 1/18/2007 P&A'd: 1/8/1976 Spud: 11/13/1975

1980' FSL 660' FEL Section 10' Unit I Township21S Range25E



HAL 5/23/2007

Lat 32:4920781 Long - 104.3765158

Purposed

Rubicon Oil & Gas, LLC Overshot State 10 No.1 Overshot Prospect Eddy County, New Mexico Producing Wellbore API No. 30-01521639 KB: 3363' GL: 3350'

Re-Entry: 1/18/2007 P&A'd: 1/8/1976 Spud: 11/13/1975

1980' FSL 660' FEL Section 10 Unit I Township 21S Range 25E

Bit Size: 17-1/2"

13-3/8" 48.0# @ (373) W/ 450 sx. + 8-1/2 yrds Ready mix. Ome to surface

Bit Size: 11°

8.5/8" 32# @ 2293' w/ 1050 sx. Cmr circ to surface. Tested coring to 1000 psi

Bit Size: 7-7/8"

Casing tie-back summary: 8455'
4-1/2" Bowen Lead seal casing patch
4-1/2" X 5-1/2" X-O w/ 4-00" ID
5-1/2" Weatherford Mechanical Port Collar
48 jts 5-1/2" 17 ppf L55 LTC csg
Cmt via port collar/400 sks: Howco prem lite
+ 100 sks: Prem Tail. Calc TOC ~4500'

8455' see tie-back summary

4-1/2" 11.6 ppf IICP110 LTC Set @ 10672' Cmt w/ 400 sx. Cl H w/ additive ______ Cmt top 9000' based on caliper from CNDL, GR, Calp ran 12/1975.

Set 4-1/2" CIBP @10,515' and Cap w/ 35' cnit PBTD 10,480'

PBTD: ~10591' TD: ~10,705' PERF & SQZ 110 SX5 CMT@ 423'

PERF & SOZ 25 SXS CMT@ 858

PERFE SOZ 75 SXS CMT@ 2343" PERFE SOZ 25 SXS CMT@ 3500"

- SPOT 255X5 CMT@ 5100'

SPOT 25 5X5 CMT @ 7500'

SPOT 30 SXS CMT@ 8505.

4/2 CIBP W/ 25 SXS CMT. @ 10,300' PERFS 10362-10428

NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT

Operator: Rubicon Oil & Ges	
Well Name & Number: 25hot 5tate 10 7	t /
API#: 30-015-21639	

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- **6.** If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
- 8. Cement Retainers may not be used.

- 9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.
- 10. Plugs may be combined after consulting with and getting approval from NMOCD.
- 11. Minimum WOC time for tag plugs will be 4 Hrs.

DATE: 4 - 1/- 14

APPROVED BY:

GUIDELINES FOR PLUGGING AND ABANDONMENT

DISTRICT II / ARTESIA

- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sacks of gel per 100 bbls of water.
- A cement plug is required to be set 50' below and 50' above all casing shoes and casing stub plugs. These plugs must be tagged.
- A CIBP with 35' of cement on top may be set in lieu of 100' cement plug.
- A plug as indicated above must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set below and above salt zones must be tagged.
- No more than 2000' is to be allowed between cement plugs in open hole and no more than 3000' in cased hole.
- DV tools are required to have a 100' cement plug set 50' above and below the tool and must be tagged.
- Formations to be isolated with plugs placed at the top of each formation are:
 - o Fusselman
 - o Devonian
 - o Morrow
 - o Wolfcamp
 - o Bone Spring
 - o Delaware
 - o Any Salt Section (Plug at top and bottom)
 - o Abo
 - o Glorieta
 - Yates (this plus is usually at base of salt section)
- If cement does not exist behind casing strings at recommended formation depths, the casing must be cut and pulled with plugs set at these depths or casing must be perforated and cement squeezed behind casing at the formation depths.
- In the R-111-P area (Potash Mine area) a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts common to the section penetrated and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible (50' below and 50' above).