

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505
RECEIVED
MAY 08 2014
NMOCD ARTESIA

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nHMP1413429654

Name of Company Devon Energy		Contact Tracy Kidd
Address PO Box 250 Artesia, NM 88211		Telephone No. 575.513.0628
Facility Name Cotton Draw Unit 65 SWD		Facility Type Salt Water Disposal
Surface Owner Federal	Mineral Owner State	API No. 30-015-10843

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	2	25S	31E	1980	N	1980	E	Eddy

Latitude: 32.161085918

Longitude: -103.746039442

NATURE OF RELEASE

Type of Release Spill Produced Water	Volume of Release 255 BBLS	Volume Recovered 250 BBLS
Source of Release Produced water line	Date and Hour of Occurrence May 5, 2014 7:00AM	Date and Hour of Discovery May 5, 2014 7:00AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Joah Weidemann; Devon Energy Assistant Production Foreman	
By Whom? David Medlock with RW Trucking	Date and Hour 7:00 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		


Describe Cause of Problem and Remedial Action Taken.*

The leak was in the produced water line coming from the Cotton Draw Unit 76 location to the Cotton Draw Unit 65 SWD. The check valve on the produced water header was bad. The line was isolated to determine the exact cause of the problem and the well was shut in. Once it was determined what the issue was the leaking area was dug up and repairs were made. The line had a hole in it as a result of corrosion.

Describe Area Affected and Cleanup Action Taken.*

The produced water leak was contained within the earthen berm surrounding the location. On May 5 a vacuum truck recovered 250 BBLS of the 255 BBLS spilled. The area where the spill occurred was back dragged. Soil samples will be taken to determine if remediation is needed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Sandra Farley	OIL CONSERVATION DIVISION	
Printed Name: Sandra Farley	Approved by Environmental Specialist: 	
Title: Field Admin Support	Approval Date: 5/14/14	Expiration Date: NA
E-mail Address: Sandy.Farley@dmv.com	Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 6/14/14	Attached <input type="checkbox"/>
Date: May 6, 2014	Phone: 575.746.5587	

* Attach Additional Sheets If Necessary

2PP-2300