

				м	
Submit 1 Copy To Appropriate I		State of New Me			Form C-103
Office - District I - (575) 393-6 M OIL CONSERVATION Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM& 274& IA DISTRICT District II - (575) 748-1283 811 S. First St., Artesia, NM 882 MAY 0 1 2019 IL CONSERVATION DIVISION District III - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 District IV - (505) 476-3460 District IV - (505) 476-3460				Revised July 18, 2013 WELL API NO.	
				30-015-26671	
				5. Indicate Type of Lease STATE STATE	
				6. State Oil & Gas Lease	e No.
87305				K-6385	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				7. Lease Name or Unit A Dee 36 SE State	Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				8. Well Number	
1. Type of Well: Oil Well Gas Well Other				5 9. OGRID Number	
2. Name of Operator Yates Petroleum Corporation				025575	
 Address of Operator South Fourth Street, Artesia, NM 88210 				10. Pool name or Wildc Canyon; Wolfcamp	at
4. Well Location					
Unit Letter <u>P</u> : <u>990</u> feet from the <u>South</u> line and <u>990</u> feet from the <u>East</u> line					
Section 36 Township 19S Range 24E NMPM Eddy County					
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3592'GR					
				•	
12.	Check Appropriate E	Box to Indicate N	ature of Notice,	Report or Other Data	
	OF INTENTION T			SEQUENT REPOR	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK					
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB					
DOWNHOLE COMMINGL					
CLOSED-LOOP SYSTEM OTHER:			OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date					
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.					
Yates Petroleum Corporation plans to plug and abandon this well as follows:					
1. MIRU all safety equipment as needed. NU BOP. RIH with GR/JB to 7040'. Set a 7" CIBP at 7030' then dump 35' Class "H" cement					
on top.					
 Spot a 45 sx Class "C" cement plug from 5320'-5170'. This will cover top of Wolfcamp. Spot a 40 sx Class "C" cement plug from 4161'-4021'. This will cover DV tool. 					
4. Spot a 35 sx Class "C" cement plug from 2170'-2050'. This will cover top of Glorieta.					
 Spot a 30 sx Class "C" cement plug from 1255'-1145'. This will cover 9-5/8" casing shoe. WOC and tag. Spot a 45 sx Class "C" cement plug from 150' up to surface. 					
7. Cut off wellhead, install				Approved for plugging of a	vell bore only.
Wellbore schematics attach	ed			Liability under bond is reta of C-103 (Subsequent Rep	ort of Wall Diversion
				which may be found an OC Forms, www.cmnrd.state.nr	D Web Page under
Spud Date:		Rig Release Da	ite:		
well MUST BE		8/2016			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
SIGNATURE Charter TITLE Regulatory Reporting Supervisor DATE April 29, 2015					
	<u>Tina Huerta</u> I	E-mail address: <u>tir</u>	nah@yatespetroleun	n.com PHONE:	575-748-4168
For State Use Only					
APPROVED BY: MOUL TITLE 15 TO Spewish DATE 5/7/15- Conditions of Approval (if any):					
★ Sec	Attached	COAS	• •		





NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT Operator <u>Jates Petholeum</u> Well Name & Number: <u>Dee</u> 36 SE State #5-API #: <u>30-015 - 26671</u>

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- 6. If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
- 8. Cement Retainers may not be used.
- 9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.

10. Plugs may be combined after consulting with and getting approval from NMOCD. 11. Minimum WOC time for tag plugs will be 4 Hrs.

DATE: 5/7/15-

APPROVED BY:

GUIDELINES FOR PLUGGING AND ABANDONMENT

DISTRICT II / ARTESIA

- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sacks of gel per 100 bbls of water.
- A cement plug is required to be set 50' below and 50' above all casing shoes and casing stub plugs. These plugs must be tagged.
- A CIBP with 35' of cement on top may be set in lieu of 100' cement plug.
- A plug as indicated above must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set below and above salt zones must be tagged.
- No more than 2000' is to be allowed between cement plugs in open hole and no more than 3000' in cased hole.
- DV tools are required to have a 100' cement plug set 50' above and below the tool and must be tagged.
- Formations to be isolated with plugs placed at the top of each formation are:
 - o Fusselman
 - o Devonian
 - o Morrow
 - o Wolfcamp
 - o Bone Spring
 - o Delaware
 - o Any Salt Section (Plug at top and bottom)
 - o Abo
 - o Glorieta
 - Yates (this plus is usually at base of salt section)
- If cement does not exist behind casing strings at recommended formation depths, the casing
 must be cut and pulled with plugs set at these depths or casing must be perforated and cement
 squeezed behind casing at the formation depths.
- In the R-111-P area (Potash Mine area) a solid cement plug must be set across the salt section.
 Fluid used to mix the cement shall be saturated with the salts common to the section penetrated and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible (50' below and 50' above).