Submit 1 Copy To Appropriate District State of New Mexico	Form C-103
Submit 1 Copy To Appropriate District Office District 1 – (575) 393-6161 OIL CONSERVA State of New Mexico District 1 – (575) 393-6161 OIL CONSERVA State of New Mexico New	Revised July 18, 2013
Office District I = (575) 748-1283 OGNSERVA: State of New Mexico New Mexico Office District I = (575) 748-1283	WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 1 2017 <u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210 JAN 0 3 OIL CONSERVATION DIVISION	30-015-21071
<u>District III</u> – (505) 334-61781220 South St. Francis Dr.	5. Indicate Type of Lease STATE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460 Santa Fe, NM 87505	STATE FEE 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	
87505	V-4655
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Bandit State SWD
PROPOSALS.)	8. Well Number 1
1. Type of Well: Oil Well Gas Well Other SWD #SWD-930	•
2. Name of Operator Read & Stevens, Inc.	9. OGRID Number 018917
3. Address of Operator	10. Pool name or Wildcat
P. O. Box 1518, Roswell, NM 88202	SWD Delaware
4. Well Location	
Unit Letter F: 1980 feet from the North line and 20	
Section 10 Township 23S Range 26E	NMPM County Eddy
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
3313.8' GL	Saffering and Company of the Company
12. Check Appropriate Poy to Indicate Nature of Natice 1	Damant on Othan Data
12. Check Appropriate Box to Indicate Nature of Notice, I	Report or Other Data
NOTICE OF INTENTION TO: SUBS	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK D PLUG AND ABANDON REMEDIAL WORK	·
TEMPORARILY ABANDON	LING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT	JOB
DOWNHOLE COMMINGLE	
CLOSED-LOOP SYSTEM	ala and and the same at a Table
	chanical Integrity Test 🔽
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
12/19/2016 to 12/26/2016	
MIRUSU. Suspect hole in csg close to surface. Open well to tank. Pump 65 bbls 15# kill mud via tbg. Pump at	
3.5 BPM w/200# pump pressure. Pressure dropped to 0#. SD pump. Tbg on slight vacuum. TOH w/2 3/8" steel	
tbg. TIH w/on-off tool, 2 3/8" x 4' perfd sub, 96 jnts 2 3/8" tbg. Pkr at 3050'. TOH w/tbg, pkr. TIH w/RBP & 96 jnts	
2 3/8" tbg. Set RBP @ 3055'. Release on-off tool. LD 2 jnts tbg. Dig dwn 3' around WH. Found quarter size hole and	
several pin holes in 5 1/2" csg. TOH w/workstring. RIH w/tension pkr and set at 68 FFS. Load tbg w/5 bbls kill mud	
Pressure up to 600# and hold for 10 min. Held ok. Release pressure. Move	
TIH w/workstring open ended. TOH w/worksting. NDBOP. NUWH. Dig be	II hole around WH. Weld plate around
5 1/2" csg. Weld 5 1/2" bell nipple to 5 1/2" csg. Screw on extension. NUV	/ H.
Continued page 2	
Spud Date: 01/10/1007 Rig Release Date:	
Spud Date: 01/10/1997 Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
·	
SIGNATURE Barages TITLE Production/Regulator	y DATE 12/29/2016
III E 1 TOUGHT TOURS INTROGULATION	J DAIE IEIEOIEOIO
Type or print name Kelly Barajas E-mail address: kbarajas@read-s	stevens.com PHONE: 575-624-3760
For State Use Only	
APPROVED BY: PULLED INGE TITLE COMPLIANCE C	FILER DATE 1/4/17
Conditions of Approval (if any):	Trugo DAIE 1/7/19

Bandit State SWD #1 30-015-21071 Page 2 of C-103 dated 12/29/2016

Load and pressure test csg to 650#. Hold for 20 min. Held ok. Release pressure. RD pump truck. Fill in cellar. NUBOP. TIH w/on-off tool, 96 jnts 2/3" tbg. Latch onto RBP at 3055'. Release RBP. Well flowing up csg side. SWI. RU pump truck. Bullhead 13 bbls 15# kill mud dwn csg and 3 bbls dwn tbg. Well on vacuum. RD pump truck. TOH w/97 jnts 2 3/8" tbg. TIH w/5 ½" x 2 3/8" ASI-X pkr and 97 jnts 2 3/8" tbg. Set pkr at 3084'. Reverse circ 15# mud 110 bbls pkr fluid. Pressure up on csg to 520# and hold for 30 min. Held ok. Release pressure. TOH w/97 jnts 2 3/8" workstring. TIH w/on-off tool, and 95 jnts 2 3/8" tbg. Tag pkr at 3084'. Space well out. LD 1 jnt of tbg. TIH w/2 3/8" x 8' x 8' x 8' x 6' PC tbg subs and 1 jnt 2 3/8" tbg. Latch onto pkr. NDBOP. NUWH. Left pkr w/10,000# tension. Pressure csg to 500# and hold for 30 min. Ran chart recorder for OCD. Held okay. Release pressure. Pressure up to 4400#. Pump out plug. Pump 28 BFW via tbg at 600# injection pressure. Well ready for disposal.

Attachment: Copy of Chart



BARIDI + St #15WD