SHOULD I COPY TO APPROPRIATE DISTRICT Form C-103 State of New Mexico Office Revised July 18, 2013 Energy, Minerals and Natural Resources District I - (575) 393-6161 WELL API NO. 1625 N. French Dr., Hobbs, NM 88240 30-015-29728 <u>District II</u> - (575) 748-1283 OIL CONSERVATION DIVISION 811 S. First St., Artesia, NM 88210 5. Indicate Type of Lease District III - (505) 334-6178 1220 South St. Francis Dr. STATE 🛛 FEE 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 6. State Oil & Gas Lease No. District IV - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 891005247E SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A Cotton Draw Unit DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH 8. Well Number Gas Well Other SWD 1. Type of Well: Oil Well 84 2. Name of Operator 9. OGRID Number Devon Energy Production Company, LP 405-552-6558 6137 3. Address of Operator 10. Pool name or Wildcat 333 West. Sheridan Avenue Oklahoma City, OK 73102-5015 SWD; Devonian 4. Well Location Unit Letter I: 2615 feet from the SOUTH line and 1160 feet from the EAST line Township 25S Range 31E **NMPM Eddy County** 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3455' GL 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK □ PLUG AND ABANDON REMEDIAL WORK \boxtimes ALTERING CASING TEMPORARILY ABANDON **CHANGE PLANS** \Box COMMENCE DRILLING OPNS.☐ P AND A **PULL OR ALTER CASING MULTIPLE COMPL** \Box **CASING/CEMENT JOB** DOWNHOLE COMMINGLE **CLOSED-LOOP SYSTEM** OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. Performed and passed an unofficial MIT test. Casing and tubing held pressure. Essentially confirming the issue was not disposal interval RIH with WL to set a plug in the packer isolating our injection interval. Set plug after 2 attempts. Pressure tested and passed. Pulled injection tubing. Tubing did show some corrosion and WL marks in plastic coating. Currently reviewing this for further analysis and/or modification. Set RBP in 5-1/2" casing at as pressure control and to keep any trash off injection packer. Run in hole with packer and tested casing to isolate problem area. Believe overshot seal assembly to be leaking. Ran in with mills to clean casing and confirm ID. Ran caliper log to document ID changes. Ran Enventure casing patch from 741' - 1220'. Drilled out float shoe from patch. Retrieve RBP. RIH with workstring and pull plug from packer. RIH with same injection string of tubing. Circulate packer fluid. Latch onto packer. Land tubing and RDMOL WO rig. Perform MIT 6/20/2017 and received verbal by Richard Inge with the NMOCD. Attached. I hereby certify that the information above is true and complete to the best of my knowledge and belief. **SIGNATURE** TITLE: Regulatory Specialist DATE 6/21/2017 Type or print name: <u>Linda Good</u> E-mail address: <u>linda.good@dvn.com</u> PHONE: 405-552-6558 For State Use Only NGE TITLE COMPLIANCE OFFICER DATE 6/22/17

APPROVED BY: LUMB Conditions of Approval (if any):

