

Submit 1 Copy To Appropriate District Office	State of New Mexico				C-103
<u>District 1</u> – (575) 393-6161				Revised July 18, 2013 WELL API NO.	
District II ~ (575) 748-1283         811 S. First St., Artesia, NM 88210       OIL CONSERVATION DIVISION         District III ~ (505) 334-6178       1220 South St. Francis Dr.			30-015-22887		
			5. Indicate Type of Lease STATE ☑ FEE ☐		
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505			6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fc, NM 87505				L-2764	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL, OR TO DEEPEN OR PLUG BACK TO A				7. Lease Name or Unit Agreement Irish Hills KW State	Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				8. Well Number	(,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
1. Type of Well: Oil Well Gas Well Other				1-Y	
2. Name of Operator EOG Y Resources, Inc.				9. OGRID Number 025575	
3. Address of Operator				10. Pool name or Wildcat	
104 South Fourth Street, Artesia, NM 88210				Penasco Draw; SA-Yeso	
4. Well Location Unit Letter P: 330 feet from the South line and 345 feet from the East line					
Section 2 Township 19S Range 24E NMPM Eddy County					
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3652'GR					
3032 GR					
12. Check Ap	propriate Box to Inc	dicate N	ature of Notice, I	Report or Other Data	
NOTICE OF INTENTION TO: SUBS				SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK  PLUG AND ABANDON  REMEDIAL WORL					
TEMPORARILY ABANDON					Ц
DOWNHOLE COMMINGLE					
CLOSED-LOOP SYSTEM  OTHER:		П	OTHER:		П
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date					
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Con proposed completion or recompletion.				•	Ē
DECEDIED					
EOG Y Resources, Inc. plans to plug and abandon this well as follows:  1. MIRU all safety equipment as needed. TOH with production equipment.  2107 I 0 101					
<ol> <li>MIRU all safety equipment as needed. TOH with production equipment.</li> <li>RIH with GR/JB to 2120'.</li> </ol>			ent.		
3. Run a gyro survey. 4. Set a 4-1/2" CIBP at 2100'. NOIT CONSERVATION					
5. Load hole with plugging mud and spot a 25 sx Class "C" cement plug from 2100'-1740'. This will place a plug over the open					
perforations and Glorieta top. WOC and tag. Reset plug if necessary.					
6. Perforate at 1010'. Pressure test and check for circulation up backside of casing. Spot a 25 sx Class "C" cement plug from 1010'-650'. WOC and tag. Reset plug if necessary.					
7. Perforate at 290'. Pressure test and check for circulation up backside of casing. Spot a 35 sx Class "C" cement plug from 500' up to					
surface. This will place a plug over the San Andres top and casing shoe to surface.  8. Cut off wellhead, install dry hole marker and clean location.					
Wellbore schematics attached Well Mast be Plassel ay 11-1-18					
Spud Date:	ì	elease Da	4 /		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
SIGNATURE TITLE Regulatory Specialist DATE November 1, 2017					
Type or print name Tina Huerta E-mail address: tina_huerta@eogresources.com PHONE: 575-748-4168 For State Use Only					
APPROVED BY: DATE 1/-1-17 Conditions of Approval (if any):					





## **CONDITIONS FOR PLUGGING AND ABANDONMENT**

## District II / Artesia N.M.

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office II at (575)-748-1283 at least 24 hours before beginning work.

- 1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs.
- 2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- 3. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- 5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
- 6. If the well is not plugged within 1
- 7. If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
- 8. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- 9. Produced water will not be used during any part of the plugging operation.
- 10. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- 11. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 12. Class 'C' cement will be used above 7500 feet.
- 13. Class 'H' cement will be used below 7500 feet.
- 14. A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- 15. All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing

- 16. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- 18. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).
- 19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
- 20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
  - A) Fusselman
  - B) Devonian
  - C) Morrow
  - D) Wolfcamp
  - E) Bone Springs
  - F) Delaware
  - G) Any salt sections
  - H) Abo
  - I) Glorieta
  - J) Yates.
  - K) Potash--- (In the R-111-P Area (Potash Mine Area), a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.
- 21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing

## DRY HOLE MARKER REQUIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least '%'' welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

1. Operator name 2. Lease and Well Number 3.API Number 4. Unit Letter 5. Quarter Section (feet from the North, South, East or West) 6. Section, Township and Range 7. Plugging Date 8. County (SPECIAL CASES)------AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)