Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD-A	RTESIA
-------	--------

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

Expires:	January	31.
Lease Serial No.		
	-	

SUNDRY N	OTICES AND REPORTS ON WELLS	
Do not use this	form for proposals to drill or to re-enter	an
abandoned well.	Use form 3160-3 (APD) for such propos	sals.

	NOTICES AND REPO				NMNM81616 ~		
Do not use thi abandoned wel	s form for proposals to I. Use form 3160-3 (API	drill or to re- D) for such p	enter an roposals.		6. If Indian, Allottee of	or Tribe Name	
SUBMIT IN 1	RIPLICATE - Other inst	tructions on	page 2		7. If Unit or CA/Agre	ement, Name and/or No.	
Type of Well ☐ Gas Well ☐ Oth	er				8. Well Name and No. H B 10 FEDERAL		
2: Name of Operator DEVON ENERGY PRODUCT	Contact: ION COMPAN: Erin.workm	ERIN WORK nan@dvn.com	MAN		9. API Well No. 30-015-33836	,	
3a. Address 333 WEST SHERIDAN AVE OKC, OK 73102 3b. Phone No. (include area code) Ph: 405-552-7970					10. Field and Pool or Exploratory Area CEDAR CANYON; BONE SPRING Defaware,		
4. Location of Well (Footage, Sec., T.	, R., M., or Survey Description)			11. County or Parish,		
∕Sec 10 T24S R29E Mer NMP	NWNE 810FNL 1780FEL	-			EDDY COUNT		
12. CHECK THE AF	PROPRIATE BOX(ES)	TO INDICA	TE NATURE OI	F NOTICE,	REPORT, OR OTH	HER DATA	
TYPE OF SUBMISSION			TYPE OF	ACTION		NO. 100 1500	
Notice of Intent ■ Notice of Intent Notice of Inten	☐ Acidize	☐ Dee	pen	☐ Product	ion (Start/Resume)	■ Water Shut-Off	
	☐ Alter Casing	☐ Hyd	raulic Fracturing	☐ Reclam	ation	■ Well Integrity	
☐ Subsequent Report	□ Casing Repair	□ New	Construction	Recomp	lete	□ Other	
☐ Final Abandonment Notice	☐ Change Plans	Plug	and Abandon	☐ Tempor	arily Abandon		
	☐ Convert to Injection	Plug	Back	☐ Water I	Disposal		
If the proposal is to deepen directions Attach the Bond under which the wor following completion of the involved testing has been completed. Final At determined that the site is ready for fi Devon Energy Production Cor Spring and recomplete to the	k will be performed or provide operations. If the operation re- landonment Notices must be fil nal inspection. npany, LP respectfully re-	the Bond No. or sults in a multipled only after all	ifile with BLM/BIA e completion or reco requirements, included back the Cedar	Required sul impletion in a r ing reclamation Canyon; Bo	osequent reports must be new interval, a Form 316 n, have been completed a	filed within 30 days 0-4 must be filed once	
Attachment: Procedures Current Wellbore Proposed Wellbore	SUBJECT APPROVA	TO LIKE L BY ST	7		APPRO		
Thank you,			OCT 20	²⁰¹⁷ C		OF APPROVAL	
	WITNES	\$	RECEIV	ED			
14. I hereby certify that the foregoing is	true and correct. Electronic Submission # For DEVON ENERGY Committed to AFMSS fo	Y PRODUCTIO	N ĆOMPAN, sent	t to the Carls	bad		
Name (Printed/Typed) ERIN WO	RKMAN		Title REGUL	ATORY CO	MPLIANCE PROF.		
Signature (Electronic S	Submission)		Date 08/28/20	017			
\cap	THIS SPACE FO	OR FEDERA	L OR STATE	OFFICE U	SE		
Approved By Aul 4 Conditions of approval, if any, are attache certify that the applicant holds legal or equ	nitable title to those rights in the		Title TP	BUI	REAU OF LAND MA Carlsbad Field		
which would entitle the applicant to condu Title 18 U.S.C. Section 1001 and Title 43		crime for any pe	Office rson knowingly and	willfully to ma			

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **

Ruf 10-27-17

DVN: H B 10 Federal #5

API #30-015-33836

Sec 10-T24S-R29E Eddy County, NM 8/25/2017

Purpose: Recomplete Brushy Sandstone

T.D. -8,100' PBTD - 8,100'; CIBP to be SET @ ~6,800' w/35' cmt on top (PBTD 6,765')

Wellbore fluid: Formation oil, natural gas and formation water.

Casing and Tubing Data:

Size	Wt. lb/ft	Grade	Interval	(.80 S. F.) Collapse	(.80 S. F.) Burst	Drift	Capacity (bbls/ft)
13-3/8"	48	H-40	0 - 419'	600	1,375	12.559"	
8-5/8"	32	J-55	0-3,043	2,000	3,100	7.796"	
5-1/2"	17	J-55	0 - 8,100'	3,930	4,250	4.767"	0.0232
2-7/8"	6.5	L-80	0 – 7,984'	8,925	8,450	2.347"	0.00579

2-7/8" by 5-1/2" -0.0152 bbls/ft.

5-1/2" -0.1305 ft3/ft

Top of Cement: To be validated via Cement Bond Log during procedure

Current Perfs:


2nd Bone Spring Sandstone

7,927'-7,940' (13')

HB 10 Federal #5 Procedure:

- 1. Remove PR and Stuffing Box. Install Rod rams. Unseat pump and T.O.H. with rods and pump.
- 2. ND wellhead. NU 5,000 psi BOPE, w/1 set of blind rams on bottom plus 1 set of 2-7/8" tbg rams on top. Test BOPE to Devon specifications. Have 10,000 psi tubing valve(s) for frac.
- 3. Unset TAC @ ~7,794'. T.O.H.
- 4. TIH and set CIBP at 6,800'. Cap CIBP with 35' cement for a PBTD of 6,765'. Wait on cement.
- 5. MIT the 5-1/2" csg to 500 psi at surface for 30 min with a 1000 psi chart recorder and submit results to BLM.

- 6. Run casing integrity log and CBL. Submit results to BLM and verify top of cement above proposed perforated interval. Do not proceed until casing integrity and cement bond accepted by BLM.
- 7. RU frac crew, iron, and tubing isolation valves rated for > 5,000 psig service. TIH frac string and packer. Set packer at 4,000'. Test CIBP and cement plug to max treating pressure. Test annulus to 1,000 psig to verify packer integrity.
- 8. R.U. Wireline Service Company and full lubricator. Test lubricator to Devon specifications. RIH with slick guns. Perforate the Brushy Sandstone between approximately 6,500' and 5,200' MD.
- 9. RD Wireline. RU frac crew. Test iron and stimulate perforated interval in the Brushy Sandstone.
- 10. RD frac. Flow well back immediately.
- 11. Once well dies. Unset treating packer, drop down and reverse circ. out fluid to PBTD of 6,765'. TOOH frac string. RDMO frac stack and additional equipment.
- 12. T.I.H. with production tubing detail as before but place T.A.C. @ \sim 6,600' (below bottom perf).
- 13. N.D. BOPE and N.U. wellhead. Install rod rams.
- 14. T.I.H. with pump and rod design.
- 15. R.D.M.O. DDCU and release all rentals. Return well to production.



	PRODUCTION COMPANY LP
/ell Name: HB 10 FEDERAL #5	Field: CEDAR CANYON
ocation: 810' FNL & 1780' FEL; SEC 10-T245-R29E	County: EDDY State: NM
levation: 3058' KB; 3045' GL; 13' KB to GL	Spud Date: 3/6/05 Compl Date: 4/2/05
Pl#: 30-015-33836 Prepared by: Joe Koessler	Date: 8/25/17 Rev:
PROPOSED BRUSHY SANDSTON RECOMPLETION	A PARA PARA PARA PARA PARA PARA PARA PA
17-1/2" hole 13-3/8", 48#, H40, 8RD , STC, @ 419'	A SOUTH AND THE STATE OF THE ST
11" Hole 8-5/8", 32#, J55, 8RD, STC, @ 3,043'	HOUSE STATES CONTRACTOR IN STATES STA
Proposed: BRUSHY SANDSTONE 6,500'-5,200' (Exact interval and perforated density TBD)	Proposed: 2. Cap CIBP w/35' cmt. 6,765' PBD. 1. Set CIBP @ 6,800'
Bone Spring (4/05) 7,927'-7,940'	TO THE COLOR OF TH

Conditions of Approval

Devon Energy Production company HB - 05, API 3001533836 T24S-R29E, Sec 10, 810FNL & 1780FEL October 2, 2017

- 1. Begin wellbore operations within 90 days of these dated conditions of approval for the processed Electronic Submission #386364 notice of intent.
- 2. Operator is required to have the BLM approved NOI procedure with applicable conditions of approval on location for this workover operation.
- 3. Well is located within the designated Medium Cave Karst Area, which requires cement circulation on both the surface and intermediate casing.
- 4. Subject to like approval by the New Mexico Oil Conservation Division.
- 5. Before adding, replacing, or repairing casing or a liner, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 6. A closed loop system is required. The operator shall properly dispose of drilling/circulating contents at an authorized disposal site. Tanks are required for all operations, no excavated pits.
- 7. Surface disturbance beyond the existing pad shall have prior BLM approval.
- 8. Functional H₂S monitoring equipment shall be on location.
- 9. Blow Out Prevention Equipment 3000 (3M) to be used. All BOPE and workover procedures shall establish fail safe well control. Ram(s) for the work string(s) used is required equipment. Manual BOP closure system including a blind ram and pipe ram(s) designed to close on all (hand wheels or automatic locking devices) equipment installed regardless of BOP design. Function test the installed BOPE to 500psig when well conditions allow. Related equipment, (choke manifolds, kill trucks, gas vent or flare lines, etc.) employed when needed for reasonable well control requirements.
- 10. All waste (i.e. trash, salts, chemicals, sewage, gray water, etc.) created during work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Portojohns and trash containers will be on-location during fracturing operations or any other crewintensive operations.
- 11. Notify BLM 575-361-2822 Eddy Co. as work begins. Some procedures witnessed. If there is no response, leave a voice mail with the API#, workover purpose, and a call back phone number.
- 12. The BLM PET witness is to run tbg tally and agree to cement volumes and placement.

 Sample each plug for cement curing time and tag and/or pressure test as requested by BLM PET witness.

- 13. After setting the CIBP within 100' of the top perf 7927', perform a charted casing integrity test of 500psig minimum. Document the pressure test on a one hour full rotation calibrated (within 6 months) recorder chart registering within 35 to 85 per cent of its full range. Verify all annular casing vents plumbed to the surface and open during this pressure test. Call BLM 575-361-2822 Eddy Co. and arrange for a BLM witness of that pressure test. Include a copy of the chart with the subsequent sundry for this workover.
- 14. Provide BLM with an electronic copy (Adobe Acrobat Document) of the Step 6. proposed cement bond log. Start the CBL at the regulatory (within 100' of the top perforation of 7927) CIBP depth. Take the CBL with 0psig casing pressure from the CIBP to TOC. Attach the CBL to a pswartz@blm.gov email.
- 15. This procedure is subject to the next three numbered paragraphs.
- 16. Set cement plugs to cover a minimum of 100ft plus 10ft for every 1,000ft from the bottom of the plug, rounding the number of necessary sacks up to the nearest 5 sacks. Never use less than 25sx. Examples: A cement plug set at 8000 in 7" casing would require a min of 35sx. A 25sx plug in 5 ½" casing should cover 250ft, which may exceed 100ft plus 10ft per 1000ft.
- 17. Class H > 7500ft & C < 7500ft) cement plugs(s) will be necessary. For any plug that requires a tag or pressure test a minimum WOC time of 4 hours(C) & 8 hours(H) is recommended. Formation isolation plugs of Class "C" to be mixed 14.8#/gal, 1.32 ft³/sx, 6.3gal/sx water and "H" to be mixed 16.4#/gal, 1.06ft³/sx, 4.3gal/sx water.
- 18. Minimum requirement for mud placed between plugs is 25 sacks of salt water gel per 100 barrels in 9 lb/gal brine.
- 19. Set a 25sx balanced Class "H" plug on the CIBP set within 100' of the top perf 7927'. WOC, and tag the plug with tbg at 7690' or above.
- 20. Set a 25sx balanced Class "C" plug across the Bone Spring formation top from 7230' or below. WOC, and tag the plug with tbg at 6990' or above.
- 21. Set a 25sx balanced Class "C" plug across the 5 ½" DV Tool from about 6820. DV Tool depth approximated, the new CBL should show a better depth definition. Set the plug from about 60' below the Tool. WOC, and tag the plug with tbg 250' above the setting depth.
- 22. The subsequent report is to include stimulation injection pressures. Report maximum/minimum injection rate (BPM) and max/min stimulation injection pressures.
- 23. Submit a (BLM Form 3160-5 subsequent report describing (dated daily) all wellbore activity and the Mechanical Integrity Test. File intermediate Form 3160-5 within 30 days of any interrupted workover procedures and a complete workover subsequent sundry.
- 24. A BLM Well Recompletion Form 3160-4 and a NMOCD Form C-102 "Well Location and Acreage Dedication Plat" with updated information is necessary with the subsequent package when recompletion changes a well's Pool designation.
- 25. File intermediate **subsequent sundry** Form 3160-**5** within 30 days of any interrupted workover procedures and a complete workover subsequent sundry.

An inactive/shut-in well bore is a non-producing completion that is capable of "beneficial use" i.e. production in **paying quantities** or of service use.

- 26. Submit evidence to support your determination that the well is in active "beneficial use" for BLM approval on the Sundry Notice Form 3160-5 within 90 days of this sundry's approval date.
- 27. Should "beneficial use" not be achieved submit for BLM approval a plan for plug and abandonment.

