District I

• 1625 N. French Dr., Hobbs, NM 88240 Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720 District III

1000 Rio Brazos Road, Aztec, NM 87410 Phone: (505) 334-6178 Fax: (505) 334-6170 District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3460 Fax: (505) 476-3462

State of New Mexico

Form C-101 Revised July 18, 2013

Energy Minerals and Natural Resources

Oil Conservation Division CONSERVATION AMENDED REPORT

1220 South St. Francis Dr. ARTESIA DISTRICT

Santa Fe, NM 87505

DEC 06 2017

	CATION I	FOR PE	ERMIT TO) DRILL, RF	E- <u>EN</u> TEI	R, DEEPEN,	RECEIVEI PLUGBAC	K, OR A	DD A ZONE	
		1. O	perator Name and	d Address		OGRID Number 025575				
EOG Y Resources, Inc. 104 South Fourth Street Artesia, NM 88210								³ API Num		
						30-015-26118				
	rty Code 625			Prop Paris	erty Name h IV Com				Well No. 2	
<u> </u>				7. Surfac	ce Location	n				
UL - Lot F		wnship 19S	Range 24E	Lot Idn	Feet from 1980	N/S Line North	Feet From 1980	E/W Line West	County Eddy	
<u> </u>	20	193	24E	358. Proposed B			1700	VY CSt	Eugy	
UL - Lot	Section Tov	wnship	Range		Feet from	N/S Line	Feet From	E/W Line	County	
				· Pool Iı	nformation	1				
				Pool Name					Pool Code	
				N. Seven Rivers; Glor	rieta-Yeso				97565	
11. Worl	T	1:	2. Well Type	Additional W			Lease Type	15.	Ground Level Elevation	
··· Worl			O O		13. Cable/Rotary N/A		P P	,	3450'	
^{16.} Mu		17. P	Proposed Depth		^{18.} Formation Chester		^{19.} Contractor N/A		^{20.} Spud Date N/A	
Depth to Groun	Seener .			e from nearest fresh		J/A	Distance to nearest surface water N/A			
Nwiii i	•1			1 1	o	, 44 (894.4 197.4				
~ We WIII De	using a closed	d-loop syst	em in lieu of li	ined pits roposed Casing	and Ceme	ent Program				
Туре	Hole Size	Ca	sing Size	Casing Weight/f			Depth Sacks of Ce		Estimated TOC	
Surface	14-3/4"		9-5/8"	36#		1290'	1375 sx (I		0	
Production			7"	23#, 26#	23#, 26#		2100 sx (In		0	
										
			Casing/	Cement Progra	ım: Additi	onal Comments		•		
Refer to page 2	? for details									
				roposed Blowou	_ ıt Preventi	on Program				
	Туре			Working Pressure		Test Press	ure	· · · · · · · · · · · · · · · · · · ·	Manufacturer	
1	Manual BOP		3000 psi		<u> </u>	3000 psi		Whichever company is available		
best of my kno	wledge and beli	ief.		e and complete to the		OIL (CONSERVA	TION DIV	ISION	
	ify that I have to NMAC □, if		ith 19.15.14.9 (A	A) NMAC 🗌 and/	or Appr	aymi	and gris	danz		
Printed name: Tina Huerta					Title:	Title: Legeologist				
Title: Regulatory Specialist					Appre	Approved Date: 12-8-17 Expiration Date: 12-8-19				
E-mail Addres	s: tina_huerta@	@eogresour	ces.com			•				
Date: December 6, 2017 Phone: (575) 748-4168					Cond	Conditions of Approval Attached				

Parish IV Com #2 Section 26-T19S-R24E Eddy County, New Mexico Page 2

Form C-101 continued:

EOG Y Resources, Inc. plans to plug back and recomplete this well as follows:

- 1. MIRU all safety equipment as needed. POOH with the packer. Load hole as necessary with fresh water.
- 2. TIH with retrieving tool to recover the RBP at 8460'. Loading hole as necessary with cut brine. Tag the packer at 8699' and cap it with 50 sx of class "H" cement. WOC and tag the plug, re-set if necessary. This will put a plug over open Morrow perfs and junked tool over the Morrow and cover open Atoka perforations.
- 3. Set a CIBP at 8075' and cap it with 25 sx class "H" cement. This will place a plug over open Strawn perforations.
- 4. Set a CIBP at 7579' and cap it with 25 sx class "H" cement. This will place a plug over squeezed Canyon perforations.
- 5. Spot a 160' class "C" cement plug across Wolfcamp top.
- 6. Load hole with treated water and pull a GR/CBL/CCL log to determine the TOC. Perforate 50' above the TOC and squeeze if necessary. Test the casing to 2000 psi.
- 7. Perforate Yeso 2400'-2900' with deep penetrating charges using 1 jspf with 90 degree phasing.
- **8.** TIH with packer, 2.25" profile nipple and tubing. Set packer at 30' above the top perf.
- 9. Breakdown the formation with treated water. Limit STP to 5000 psi. Monitor pressure decline until the surface pressure is 0 psi. Swab, test and evaluate. Send samples to lab for analysis.
- 10. Acidize with 5000g of 20% NEFE acid. Drop 200 1.3 SG RCN ball sealers spaced out evenly throughout the acid flush to the bottom perf with treated water. Limit STP to 5000 psi. Swab, flow test and evaluate. Consider turning well over to production, or if the decision to frac is made. POOH with packer and tubing. TIH with packer, O/O tool, 2.25" profile nipple and 3.5" 9.3#/ft P-110 frac string. Loading hole as necessary with treated water.
- 11. MI RU frac valve and WSC to pump a fracturing treatment down the 3.5" tubing at 38-40 BPM while limiting the surface treating pressure to less than 8,600 psi. Put 2,000 psi on the 3.5 X 5.5" annulus and monitor pressure during the treatment. A pop off valve should be installed on the annulus and set at 2,500 psi.

Treating	Schedule

					lb Proppant		
Stage	Stage	gal	Fluid	Prop Conc			-
Numbe:	r			lb/gal	Stage	Cumulative	Proppant
1	Injectio	n 1500.	Slickwater	0.00	0.	0.	
2	Acid	2000.	20% HCL	0.00	0.	0.	:
3	Pad	2000.	Slickwater	0.00	0.	0.	
4	ISIP	0.	Slickwater	0.00	0.	0.	
5	Pad	14000.	Slickwater	0.00	0.	0.	
6	SLF	33000.	Slickwater	0.50	16500.	16500.	100 Mesh
7	SLF	25000.	Slickwater	1.00	25000.	41500.	100 Mesh
8	SLF	22000.	Slickwater	1.50	33000.	74500.	100 Mesh
9	SLF	17000.	Slickwater	2.00	34000.	108500.	100 Mesh
10	SLF	6600.	Slickwater	2.50	16500.	125000.	100 Mesh
11	Flush	1500.	Slickwater	0.00	0.	0.	

Estimated Surface Treating Pressure = 5,100 psig. Maximum Surface Treating Pressure = 8,600 psig.

Fluid Specifications: Fresh water with 0.8 to 1.2 Gal/M FR, biocide and scale inhibitor.

EOG will provide:

7 clean frac tanks with 480 bbls of fresh water for the treatment and flush.

12. Flow test and evaluate and let the well clean up, if the well is dead or the pressure is low bullhead 10# brine with biocide and POOH with tubing and packer. If the well head pressure is staying above 200 psi set a blanking plug in the O/O tool jay off the packer and POOH laying down the 3.5" frac string. TIH with tubing and jay back onto the packer and pull the blanking plug.

13. Swab the well in and turn it over to Production.

Wellbore schematics attached

Regulatory Specialist December 6, 2017



