Submit 1 Copy To Appropriate District Office State of New Mexico	Form C-10
District I Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240 Energy, Minerals and Natural Resources	October 13, 200 WELL API NO,
District II	30-005-62781
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 1220 South St. Francis Dr.	STATE S FEE
District IV Santa Fe, NM 87505 Santa Fe, NM 87505	6. State Oil & Gas Lease No.
	VA-1952
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name Sunfish State
PROPOSALS.)	8. Well Number
1. Type of Well: Oil Well 🗌 Gas Well 🛛 Other	1
2. Name of Operator	9. OGRID Number
Armstrong Energy Corporation	001092
3. Address of Operator	10. Pool name or Wildcat
P.O. Box 1973, Roswell, NM 88202-1973	Foor Ranch; San Andres (Gas)
4. Well Location	
Unit Letter J: 1980 feet from the South line and 198	
Section 32 Township 9S Range 27E	NMPM Chaves County
11. Elevation (Show whether DR, RKB, RT, GR, etc.	.)
3925' KB	
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK D PLUG AND ABANDON REMEDIAL WORK	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI	LLING OPNS. 🔲 PAND A 🛛 🛛 🛛
PULL OR ALTER CASING 🔲 MULTIPLE COMPL 🔲 CASING/CEMENT	г ЈОВ 🗍
	_
DOWNHOLE COMMINGLE Image: Common comm Common common comm	
DOWNHOLE COMMINGLE Image: Complete com	nent dates, including estimated date of starting any
DOWNHOLE COMMINGLE Image: Common comm Common common comm	nent dates, including estimated date of starting any
DOWNHOLE COMMINGLE OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent operations). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore	nent dates, including estimated date of starting any e diagram of proposed completion or recompletion
DOWNHOLE COMMINGLE OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbord 1. Set CIBP @ 1950', load hole and test to 500 psi, held OK.	nent dates, including estimated date of starting any e diagram of proposed completion or recompletion
DOWNHOLE COMMINGLE OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertiner proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbord 1. Set CIBP @ 1950', load hole and test to 500 psi, held OK. 2. Circ hole with mud.	nent dates, including estimated date of starting any
DOWNHOLE COMMINGLE OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinproposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbord 1. Set CIBP @ 1950', load hole and test to 500 psi, held OK. 2. Circ hole with mud. 3. Spot 25 sx on CIBP, WOC, tag @ 1758'.	nent dates, including estimated date of starting any e diagram of proposed completion or recompletion NM OIL CONSERVATION ARTESIA DISTRICT
DOWNHOLE COMMINGLE OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertiner proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbord 1. Set CIBP @ 1950', load hole and test to 500 psi, held OK. 2. Circ hole with mud. 3. Spot 25 sx on CIBP, WOC, tag @ 1758'. 4. Perf 1560', could not pump into perfs.	nent dates, including estimated date of starting any e diagram of proposed completion or recompletion
DOWNHOLE COMMINGLE OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertin proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbord 1. Set CIBP @ 1950', load hole and test to 500 psi, held OK. 2. Circ hole with mud. 3. Spot 25 sx on CIBP, WOC, tag @ 1758'. 4. Perf 1560', could not pump into perfs. 5. Spot 25 sx @ 1610' WOC, tag @ 1374'.	nent dates, including estimated date of starting any e diagram of proposed completion or recompletion NM OIL CONSERVATION ARTESIA DISTRICT JAN 0 4 2018
 DOWNHOLE COMMINGLE	nent dates, including estimated date of starting any e diagram of proposed completion or recompletion NM OIL CONSERVATION ARTESIA DISTRICT
DOWNHOLE COMMINGLE OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinproposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbord 1. Set CIBP @ 1950', load hole and test to 500 psi, held OK. 2. Circ hole with mud. 3. Spot 25 sx on CIBP, WOC, tag @ 1758'. 4. Perf 1560', could not pump into perfs. 5. Spot 25 sx @ 1610' WOC, tag @ 1374'. 6. Perf 400', establish circulation up 8-5/8" annulus to Surface. 7. Cement w/ 110 sx and circulate, WOC and tag.	nent dates, including estimated date of starting any e diagram of proposed completion or recompletion NM OIL CONSERVATION ARTESIA DISTRICT JAN 0 4 2018
DOWNHOLE COMMINGLE OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinproposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbord 1. Set CIBP @ 1950', load hole and test to 500 psi, held OK. 2. Circ hole with mud. 3. Spot 25 sx on CIBP, WOC, tag @ 1758'. 4. Perf 1560', could not pump into perfs. 5. Spot 25 sx @ 1610' WOC, tag @ 1374'. 6. Perf 400', establish circulation up 8-5/8" annulus to Surface. 7. Cement w/ 110 sx and circulate, WOC and tag. 8. Cut off wellhead 3' below ground.	nent dates, including estimated date of starting any e diagram of proposed completion or recompletion NM OIL CONSERVATION ARTESIA DISTRICT JAN 0 4 2018
DOWNHOLE COMMINGLE OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinproposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbord 1. Set CIBP @ 1950', load hole and test to 500 psi, held OK. 2. Circ hole with mud. 3. Spot 25 sx on CIBP, WOC, tag @ 1758'. 4. Perf 1560', could not pump into perfs. 5. Spot 25 sx @ 1610' WOC, tag @ 1374'. 6. Perf 400', establish circulation up 8-5/8" annulus to Surface. 7. Cement w/ 110 sx and circulate, WOC and tag.	nent dates, including estimated date of starting any e diagram of proposed completion or recompletion NM OIL CONSERVATION ARTESIA DISTRICT JAN 0 4 2018
DOWNHOLE COMMINGLE OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinproposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbord 1. Set CIBP @ 1950', load hole and test to 500 psi, held OK. 2. Circ hole with mud. 3. Spot 25 sx on CIBP, WOC, tag @ 1758'. 4. Perf 1560', could not pump into perfs. 5. Spot 25 sx @ 1610' WOC, tag @ 1374'. 6. Perf 400', establish circulation up 8-5/8" annulus to Surface. 7. Cement w/ 110 sx and circulate, WOC and tag. 8. Cut off wellhead 3' below ground.	nent dates, including estimated date of starting any e diagram of proposed completion or recompletion NM OIL CONSERVATION ARTESIA DISTRICT JAN 0 4 2018
DOWNHOLE COMMINGLE OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinproposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbord 1. Set CIBP @ 1950', load hole and test to 500 psi, held OK. 2. Circ hole with mud. 3. Spot 25 sx on CIBP, WOC, tag @ 1758'. 4. Perf 1560', could not pump into perfs. 5. Spot 25 sx @ 1610' WOC, tag @ 1374'. 6. Perf 400', establish circulation up 8-5/8" annulus to Surface. 7. Cement w/ 110 sx and circulate, WOC and tag. 8. Cut off wellhead 3' below ground.	nent dates, including estimated date of starting any e diagram of proposed completion or recompletion NM OIL CONSERVATION ARTESIA DISTRICT JAN 0 4 2018
 DOWNHOLE COMMINGLE OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertine proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbord 1. Set CIBP @ 1950', load hole and test to 500 psi, held OK. 2. Circ hole with mud. 3. Spot 25 sx on CIBP, WOC, tag @ 1758'. 4. Perf 1560', could not pump into perfs. 5. Spot 25 sx @ 1610' WOC, tag @ 1374'. 6. Perf 400', establish circulation up 8-5/8" annulus to Surface. 7. Cement w/ 110 sx and circulate, WOC and tag. 8. Cut off wellhead 3' below ground. 9. Install Dry Hole Marker, cut off anchors and clean location. 	nent dates, including estimated date of starting any e diagram of proposed completion or recompletion NM OIL CONSERVATION ARTESIA DISTRICT JAN 0 4 2018
 DOWNHOLE COMMINGLE OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertine proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbord 1. Set CIBP @ 1950', load hole and test to 500 psi, held OK. 2. Circ hole with mud. 3. Spot 25 sx on CIBP, WOC, tag @ 1758'. 4. Perf 1560', could not pump into perfs. 5. Spot 25 sx @ 1610' WOC, tag @ 1374'. 6. Perf 400', establish circulation up 8-5/8" annulus to Surface. 7. Cement w/ 110 sx and circulate, WOC and tag. 8. Cut off wellhead 3' below ground. 9. Install Dry Hole Marker, cut off anchors and clean location. 	nent dates, including estimated date of starting any e diagram of proposed completion or recompletion NM OIL CONSERVATION ARTESIA DISTRICT JAN 0 4 2018
 DOWNHOLE COMMINGLE OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertine proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbord 1. Set CIBP @ 1950', load hole and test to 500 psi, held OK. 2. Circ hole with mud. 3. Spot 25 sx on CIBP, WOC, tag @ 1758'. 4. Perf 1560', could not pump into perfs. 5. Spot 25 sx @ 1610' WOC, tag @ 1374'. 6. Perf 400', establish circulation up 8-5/8" annulus to Surface. 7. Cement w/ 110 sx and circulate, WOC and tag. 8. Cut off wellhead 3' below ground. 9. Install Dry Hole Marker, cut off anchors and clean location. 	nent dates, including estimated date of starting any e diagram of proposed completion or recompletion NM OIL CONSERVATION ARTESIA DISTRICT JAN 0 4 2018
DOWNHOLE COMMINGLE OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertin proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbook 1. Set CIBP @ 1950', load hole and test to 500 psi, held OK. 2. Circ hole with mud. 3. Spot 25 sx on CIBP, WOC, tag @ 1758'. 4. Perf 1560', could not pump into perfs. 5. Spot 25 sx @ 1610' WOC, tag @ 1374'. 6. Perf 400', establish circulation up 8-5/8" annulus to Surface. 7. Cement w/ 110 sx and circulate, WOC and tag. 8. Cut off wellhead 3' below ground. 9. Install Dry Hole Marker, cut off anchors and clean location. Spud Date: Rig Release Date:	Internet dates, including estimated date of starting any e diagram of proposed completion or recompletion MM OIL CONSERVATION ARTESIA DISTRICT JAN 0 4 2018 RECEIVED
DOWNHOLE COMMINGLE OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertine proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbord 1. Set CIBP @ 1950', load hole and test to 500 psi, held OK. 2. Circ hole with mud. 3. Spot 25 sx on CIBP, WOC, tag @ 1758'. 4. Perf 1560', could not pump into perfs. 5. Spot 25 sx @ 1610' WOC, tag @ 1374'. 6. Perf 400', establish circulation up 8-5/8" annulus to Surface. 7. Cement w/ 110 sx and circulate, WOC and tag. 8. Cut off wellhead 3' below ground. 9. Install Dry Hole Marker, cut off anchors and clean location. Spud Date: Rig Release Date: Rig Release Date: product	Internet dates, including estimated date of starting any e diagram of proposed completion or recompletion ARTESLA DISTRICT JAN 0 4 2018 RECEIVED ge and belief.
DOWNHOLE COMMINGLE OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinproposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbord 1. Set CIBP @ 1950', load hole and test to 500 psi, held OK. 2. Circ hole with mud. 3. Spot 25 sx on CIBP, WOC, tag @ 1758'. 4. Perf 1560', could not pump into perfs. 5. Spot 25 sx @ 1610' WOC, tag @ 1374'. 6. Perf 400', establish circulation up 8-5/8" annulus to Surface. 7. Cement w/ 110 sx and circulate, WOC and tag. 8. Cut off wellhead 3' below ground. 9. Install Dry Hole Marker, cut off anchors and clean location. Spud Date: Rig Release Date: install Dry Hole Marker, cut off anchors and clean location. Spud Date: Rig Release Date: Spud Date: TITLE	ment dates, including estimated date of starting any e diagram of proposed completion or recompletion ARTESIA DISTRICT JAN 0 4 2018 RECEIVED ge and belief. DATE3/10/2017
 DOWNHOLE COMMINGLE OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertine proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbord 1. Set CIBP @ 1950', load hole and test to 500 psi, held OK. 2. Circ hole with mud. 3. Spot 25 sx on CIBP, WOC, tag @ 1758'. 4. Perf 1560', could not pump into perfs. 5. Spot 25 sx @ 1610' WOC, tag @ 1374'. 6. Perf 400', establish circulation up 8-5/8" annulus to Surface. 7. Cement w/ 110 sx and circulate, WOC and tag. 8. Cut off wellhead 3' below ground. 9. Install Dry Hole Marker, cut off anchors and clean location. 	ment dates, including estimated date of starting any e diagram of proposed completion or recompletion ARTESIA DISTRICT JAN 0 4 2018 RECEIVED ge and belief. DATE3/10/2017
DOWNHOLE COMMINGLE OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertin proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbord 1. Set CIBP @ 1950', load hole and test to 500 psi, held OK. 2. Circ hole with mud. 3. Spot 25 sx on CIBP, WOC, tag @ 1758'. 4. Perf 1560', could not pump into perfs. 5. Spot 25 sx @ 1610' WOC, tag @ 1374'. 6. Perf 400', establish circulation up 8-5/8" annulus to Surface. 7. Cement w/ 110 sx and circulate, WOC and tag. 8. Cut off wellhead 3' below ground. 9. Install Dry Hole Marker, cut off anchors and clean location. Spud Date: Rig Release Date: install Dry Hole Marker, cut off anchors and clean location. Spud Date: Rig Release Date: install Dry Hole Marker, cut off anchors and clean location. Spud Date: Rig Release Date: install Dry Hole Marker, cut off anchors and complete to the best of my knowled SIGNATURE	ment dates, including estimated date of starting any e diagram of proposed completion or recompletion ARTESIA DISTRICT JAN 0 4 2018 RECEIVED ge and belief. DATE3/10/2017
DOWNHOLE COMMINGLE OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinproposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbord 1. Set CIBP @ 1950', load hole and test to 500 psi, held OK. 2. Circ hole with mud. 3. Spot 25 sx on CIBP, WOC, tag @ 1758'. 4. Perf 1560', could not pump into perfs. 5. Spot 25 sx @ 1610' WOC, tag @ 1374'. 6. Perf 400', establish circulation up 8-5/8" annulus to Surface. 7. Cement w/ 110 sx and circulate, WOC and tag. 8. Cut off wellhead 3' below ground. 9. Install Dry Hole Marker, cut off anchors and clean location. Spud Date: Rig Release Date: install Dry Hole Marker, cut off anchors and clean location. Spud Date: Rig Release Date: SignATURE	ment dates, including estimated date of starting any e diagram of proposed completion or recompletion ARTESIA DISTRICT JAN 0 4 2018 RECEIVED ge and belief. DATE3/10/2017