Submit 1 Copy To Appropriate District	State of New Maria	Former C 102					
Office	State of New Mexico ergy, Minerals and Natural Resources	Form C-103 Revised July 18, 2013					
<u>District I</u> – (575) 393-6161 End 1625 N. French Dr., Hobbs, NM 88240	rigy, minerals and realural resources	WELL API NO.					
<u>District II'-</u> (575) 748-1283 <u>811 S. First St., Artesia, NM 88210</u> OI	L CONSERVATION DIVISION	30-015-10413					
<u>District III</u> – (505) 334-6178	1220 South St. Francis Dr.	5. Indicate Type of Lease STATE X FEE					
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	Santa Fe, NM 87505	STATE FEE 6. State Oil & Gas Lease No.					
1220 S. St. Francis Dr., Santa Fe, NM 87505							
SUNDRY NOTICES AN	D REPORTS ON WELLS	7. Lease Name or Unit Agreement Name					
(DO NOT USE THIS FORM FOR PROPOSALS TO D DIFFERENT RESERVOIR. USE "APPLICATION FO							
PROPOSALS.)	TYLER AVC STATE 8. Well Number 1						
1. Type of Well: Oil Well Gas Well	8. Well Number 1 9. OGRID Number						
EOG Y RESO	2. Name of Operator EOG Y RESOURCES INC						
3. Address of Operator		10. Pool name or Wildcat					
PO BOX 2267	MIDLAND, TX 79702	DARK CANYON II; PENN (G)					
4. Well Location							
Unit Letter J : 1700	_feet from the SOUTH line and 2						
Section 30	Township 23S Range 25E vation (Show whether DR, RKB, RT, GR, etc	NMPM County LEA					
	3908' GR						
Enderstein sie einen Stean Bernin Gemmung als freiden Steile Bernung gehet met ein der Bereinstein "	······································						
12. Check Appropri	ate Box to Indicate Nature of Notice.	Report or Other Data					
		•					
		BSEQUENT REPORT OF:					
	—						
		IT JOB					
DOWNHOLE COMMINGLE							
_OTHER:							
		nd give pertinent dates, including estimated date					
	RULE 19.15.7.14 NMAC. For Multiple Co	ompletions: Attach wellbore diagram of					
proposed completion or recompletion							
EOG Y proposes to P&A this well	using the attached procedure.						
Added Perf @ 5095	~						
Part @ 5093		NM OIL CONSERVATION ARTESIA DISTRICT					
		JAN 1 1 2018					
		RECEIVED					
Spud Date:	Rig Release Date:						
C ALE LOO							
Dee Attached CE	11 1005	Be Plassed By 1-12-19					
I hereby certify that the information above is true and complete to the best of my knowledge and belief.							
V And in a							
SIGNATURE MULLIN TITLE Regulatory Analyst DATE 01/09/2018							
Type or print name Kay Maddox E-mail address: kay_maddox@eogresources.com PHONE: 432-686-3658							
	E-mail address: kay_maddox@ed	ogresources.com PHONE: 432-686-3658					
For State Use Only							
	E-mail address: kay_maddox@ed	ogresources.com PHONE: 432-686-3658 DATE /-/2 -18					



Tyler AVC State #1 1700' FSL & 2230' FEL Sec. 30-235-25E Eddy County, New Mexico API # 30-015-10413

> P&A Procedure AFE # 109214

Executive Summary:

Pull production equipment, P&A well, cut off wellhead, install dry hole marker and clean location.

TD:	11,640'	PBTD: 10,570'	GL:	3,908'	KB:	3,922'
Surface Casing:13 ¾" 48# & 54# at 1,059'. Cemented with 850 sx. Cement circulateIntermediate Casing:9 ¾" 36# & 40# at 5,045'. Cemented with 500 sx. Cut and pulled fro 9 ¾" 36# & 40# w/ slip jt at 2,728'. Cemented with 600 sx. Cement						nd pulled from 2,720'.
Production Casing: 5 ½" 15.5# & 17# at 10,923'. Cemented with 750 sx. To and pulled from 7,988'. 5 ½" 15.5# & 17# w/ slip jt at 7,994'. Cemented with 6 CBL.				,		

P&A Procedure:

- 1. Notify NMOCD 24 hours prior to commencing work. MIRU well service unit and all necessary safety equipment.
- 2. ND WH, NU BOP, release Uni V packer at 9,199' and TOH with 2%" production string.
- 3. RU WL and RIH with GR and JB to 9,215'. POOH. RIH with 5½" CIBP and set CIBP at 9,205'. POOH.
- 4. TIH and tag top of CIBP. Circulate plugging mud then spot 25 sx class "H" cement on top of CIBP.
- 5. Pick up to 8,125' and spot a 180' (≈25 sx) class "H" cement plug from 8,125'-7,945' (this will cover top of Wolfcamp).
- 6. Pick up to 5,095' and spot a 150' (≈25 sx) class "C" cement plug from 5,095'-4,945' (this will cover 9%" csg shoe). Pick up, reverse tubing clean, and POOH to WOC.
- RU WL to RIH and tag TOC, then perf 5½" csg at 4,763'. POOH. TIH with packer and set packer at 4,623'. Spot a 140' (≈45 sx) class "C" cement plug from 4,763'-4,623' inside and outside 5½" casing (this will cover top of Bone Spring). Release packer, pick up, reverse tubing clean and POOH. ~
- 8. RU WL to RIH and perf 5½" csg at 2,229'. POOH. TIH with packer and set packer at 2,109'. Spot a 120' (≈40 sx) class "C" cement plug from 2,229'-2,109' inside and outside 5½" casing (this will covertop of Delaware). Release packer, pick up, reverse tubing clean and POOH.

- 9. RU WL to RIH and perf 5½" csg at 1,110'. POOH. TIH with packer and set packer at 1,000'. Spot a 110' (≈35 sx) class "C" cement plug from 1,110'-1,000' inside and outside 5½" casing (this will cover ~ 13¾" csg shoe). Release packer, pick up, reverse tubing clean and POOH to WOC.
- **10.** RU WL to RIH and tag TOC, then pick up and perf 5½" csg at 50'. Circulate a 15 sx class "C" cement plug from 50'-surface.
- 11. RDMO well service unit, cut off wellhead, install dry hole marker and clean location.


Production Engineer:

x

1

Bin A Solate Date: 1/8/2018

Brice A. Letcher, P.E.





Formation	n Tops
Delaware	2,179
Bone Spring	4,713
Wolfcamp	8,075
Penn.	9,065
Chester	10,872
Miss.	11,232
Silurian	11,588

