				in										
Form 3160-5 June 2015)		OCD Artes			APPROVED									
UNITED STATES (June 2015) DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on page 2					OMB NO. 1004-0137 Expires: January 31, 2018 5. Lease Serial No. NMNM98122 6. If Indian, Allottee or Tribe Name 7. If Unit or CA/Agreement, Name and/or No. 8920002760									
								1. Type of Well Gas Well 🛱 Other: INJECTION				8. We		
								<ul> <li>Oil Well Gas Well 2.</li> <li>Name of Operator</li> </ul>	DEBI GORDON			9. API Well No.		
									N@LINNENERGY.C					
3a. Address 600 TRAVIS STREET SUIT HOUSTON, TX 77002	3b. Phone No. (include area code) Ph: 281-840-4010 Fx: 832-209-4340			10. Field and Pool or Exploratory Area GRAYBURG										
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				11. County or Parish, State										
Sec 21 T17S R31E SENE 1			EDDY COUNTY, NM											
12. CHECK THE	APPROPRIATE BOX(ES)	TO INDICATE 1	NATURE O	F NOTICE,	REPORT, OR OTH	IER DATA								
TYPE OF SUBMISSION		TYPE OF ACTION												
Notice of Intent	C Acidize	🗖 Deepen		Producti	on (Start/Resume)	□ Water Shut-Off								
□ Notice of Intent	□ Alter Casing	🗖 Hydrauli	Iydraulic Fracturing   Image: Reclam     Iew Construction   Image: Recommendation		tion	U Well Integrity								
🛛 Subsequent Report	Casing Repair	New Cor			lete	□ Other								
Final Abandonment Notice	Change Plans	🛛 Plug and	Abandon	Tempor	nporarily Abandon									
	Convert to Injection	Plug Bac	k	U Water D	isposal									
13. Describe Proposed or Completed If the proposal is to deepen directi Attach the Bond under which the following completion of the invol testing has been completed. Final determined that the site is ready for	onally or recomplete horizontally, work will be performed or provide ved operations. If the operation re Abandonment Notices must be fi	, give subsurface locat the Bond No. on file sults in a multiple cor	ons and measu with BLM/BIA	ared and true ve A. Required sub completion in a r	rtical depths of all pertin sequent reports must be ew interval, a Form 316	ent markers and zones. filed within 30 days 0-4 must be filed once								
LINN OPERATING, LLC IS REFERENCED WELL LOC ACTION NEEDED TO BE (	ATED IN EDDY COUNTY,	NM. THIS WELL	UG AND AE WAS IN AN	BANDONME EXPIRED T	NT REPORT FOR <sup>*</sup> A STATUS, CORRE	THE ECTIVE								
THE OPERATIONAL SUM	MARY AND FINAL WELLB	ORE DIAGRAMS	ARE ATTAC	CHED.										
FINAL PLUG AND ABAND														
		313	CONSED	11入すれ										
Accepted for record - NMOCD			DI CONSERVATIO			IATION								
Accepted for record - NMOCD						20-18								
				iu										
14. I hereby certify that the foregoin	Electronic Submission #	404484 verified by	ECEIVED the BLM We	) Il Information	System									
C	For LINN OPERA ommitted to AFMSS for proc	TING INCORPORA	TED. sent to	o the Carlsba										
Name (Printed/Typed) DEBI GORDON			Title REGULATORY MANAGER											
Signature (Electron	ic Submission)	Da	e 02/14/2	018										
Amentel For D.	THIS SPACE FO	OR FEDERAL C	R STATE	OFFICE U	SE									
Approved By	res a. Com	,	ie Su	ou.	БТ	<b>2-27-18</b> Date								
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office Carlsbad											

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions	on	page	2)	,
---------------	----	------	----	---

`

\*\* BLM REVISED \*\*

## SKELLY UNIT #10 API#: 30-015-05325 Plug and Abandonment Operations

11/30/2017 MI & Spot Equipment. Dugout cellar. SISD

7

- 12/01/2017 Tried to RU but rig mat kept sinking in sand (had backhoe bring in caliche). Spot rig mat & RUPU
- 12/04/2017 Crew to location. Held 5 min safety meeting and go over JSA. Bled well down to frac pit. NDWH, tubing slips were stuck in WH. Pulled 35 K on tubing, had to beat on wellhead bowl repeatedly to free up slips. Slips out. Made several attempts to unset packer, finally got to unset but unable to come up, were able to go down but couldn't come up. Was going to NUBOP but rig didn't have right flange. WH bowl measured 9" Model of WH is a 7" DNT. Unable to find flange. NUWH, left well going down temp. F.L. SDFN. Ordered out new 7" WH for tomorrow.
- 12/05/2017 Crew to location. Held daily safety meeting, go over JSA. Decision was made not to replace WH. Took old WH cap, cut out the center and welded to extra BOP flange. Decision was also made to shoot off tubing and leave packer in the hole. Called BLM and got verbal approval from Jim Amos to proceed. RU wireline, RIH and found top of packer @ 2070'. Pull up to 2055' and shot tubing off. PU 2 jnts, <u>RIH tag and</u> stack out @ 2135'. LD 2 jnts. S/I, SDFN.
- 12/06/2017 Crew to location. Held daily safety meeting, go over JSA. Bled well down, POOH, laid down 66 jnts 2-3/8" IPC. RU wireline, RIH W/7" gauge ring, tagged and @ 2055'. Called BLM Jim Amos got verbal to set CIBP @ 2055'. RIH w/CIBP on wireline and set @ 2055'. POOH w/wireline, PU 62 jnts, RIH to 2055', circulate hole with 74 bbls MLF. Spot 25 sxs on top of CIBP. Calc TOC 1892'. POOH w/24 stands, lay rest down. RU wireline, RIH to 1550' and perf. RIH w/7" packer to 1235', load hole, set packer. Tried to establish injection rate but unable to. Pressured up to 700 psi and held for 10 min. Bled off press. Called BLM and got verbal approval to spot 30 sxs. POOH W/packer, RIH open ended to 1550 '. Will spot 30 sxs tomorrow. S/I well. SDFN
- 12/07/2017 Crew to location. Held daily safety meeting, go over JSA. Yesterday perf'd @ 1550' and unable to establish an injection rate. EOT already at 1550', we pumped 30 sxs Class C @ 14.8 ppg and displaced with 6 bbls. POOH with tubing, WOC 4 hrs. Calc'd TOC 1402'. RIH w/tubing, tag cement @ 1462'. POOH w/12 stands, lay rest down. Called BLM, verbal ok. RIH w/tubing and packer to 357' RU wireline, RIH to 660' and perf. POOH w/wireline. Load hole, set packer, establish injection rate of 1.5 bpm @ 700'psi. Squeeze 40 sxs Class C @ 148 ppg. Displace with 8.5 bbls to 560. ISIP was 0 psi. S/I well. Will tag tomorrow AM SDFN
- 12/08/2017 Crew to location, held daily safety meeting, go over JSA. Bled well down. 9 psi. Release packer, POOH, remove packer. RIH tag cement @ 525'. POOH RIH W/wireline, perf @ 100'. POOH w/wireline. RIH w/1 jnt and packer, load hole, set packer, establish injection rate 2 bpm @ 400 psi. Squeeze 50 sxs Class C @ 14.8 ppg from 100' to surface. Called and notified BLM. RDPU equipment.
- 12/20/2017 Cut wellhead and weld on below ground level dry hole marker as required.

## FINAL PLUG AND ABANDONMENT OPERATIONS WERE COMPLETED 12/20/2017

