

District I - (575) 393-6161

RECEIVED

Energy, Minerals and Natural Resources

Revised July 18, 2013

1625 N. French Dr., Hobbs, NM 88240

District II - (575) 748-1283

811 S. First St., Artesia, NM 88210

District III - (505) 334-6178

1000 Rio Brazos Rd., Aztec, NM 87410

District IV - (505) 476-3460

1220 S. St. Francis Dr., Santa Fe, NM 87505

FEB 25 2019

OH CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

DISTRICT II-ARTESIA

WELL API NO.

30-015-37551

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Bebop BPE State

8. Well Number 1H

9. OGRID Number 14744

10. Pool name or Wildcat

Jennings; BS; West 97860

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

Mewbourne Oil Company

3. Address of Operator

PO Box 5270, Hobbs NM 88241

4. Well Location

Unit Letter D : 660 feet from the North line and 330 feet from the West line

Section 36 Township 25S Range 31E NMPM Eddy County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

3313' GL

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

DOWNHOLE COMMINGLE ☐

CLOSED-LOOP SYSTEM ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ P AND A ☐

CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

See attached plugging procedure.

Please call Jake Nave with any questions.

Notify OCD 24 hrs. prior to any work done.

ENTERED
2/26/19

Spud Date:

Rig Release Date:

* See Attached COA's must be plugged by 2/26/20

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jackie Lathan TITLE Regulatory DATE 02/22/19

Type or print name Jackie Lathan E-mail address: jlathan@mewbourne.com PHONE: 575-393-5905

For State Use Only

APPROVED BY: [Signature] TITLE Staff mg. DATE 2/26/19

Conditions of Approval (if any):

emailed Jackie

PLUG & ABANDON PROCEDURE

Submitted By: J. Nave

Wellname: Bebop BPE St #1H

Location: 660' FNL & 330' FWL
Unit Letter D, Sec 36, T25S, R31E
Eddy, NM

API #: 30-015-37551

Procedure:

1. MIRU BCM.
2. RIH w/wireline & perform CBL from 6100' to surface.
3. RIH & set 5 1/2" CIBP @ 9154'. (Top perf @ 9204')
4. Test csg to 500# for 30 min.
5. RIH w/tbg & circ hole w/9.0# mud.
6. Spot 25 sks Class H cmt on top of CIBP. WOC & tag @ or above 9054'.
7. POOH w/tbg to 8357' (Top of Bone Springs). Spot 25 sks Class H cmt. WOC & tag @ or above 8257'.
8. POOH w/tbg to 6037' (DV tool @ 5987'). Spot 25 sks Class "C" cmt. WOC & tag @ or above 5937'.
9. POOH w/tbg to 4360' (9 5/8" csg shoe @ 4310'). Spot 25 sks Class "C" cmt. WOC & tag cmt @ or above 4260'.
10. POOH w/tbg to 3850' (TOC on 5 1/2" csg @ 3800'). Spot 25 sks Class "C" cmt. WOC & tag cmt @ or above 3750'. POOH w/tbg. (Will confirm TOC w/bondlog & adjust accordingly.)
11. RIH w/wireline & perf 5 1/2" & 9 5/8" csg @ 1870' (Top Salt @ 1820'). Establish circulation on 9 5/8" x 5 1/2" annulus. Circ mud to surface.
12. TIH w/packer to 1500'. Squeeze 60 sks Class "C" into 8 5/8" x 5 1/2" annulus & 5 1/2" csg. WOC. TIH & tag plug @ or above 1770'. TOOH.
13. RIH w/wireline & perf 5 1/2" & 9 5/8" csg @ 1126' (13 3/8" csg shoe @ 1076'). Establish circulation.
14. TIH w/packer to 850'. Squeeze 60 sks Class "C" into 8 5/8" x 5 1/2" annulus & 5 1/2" csg. WOC & tag plug @ or above 1026'. TOOH w/tbg.
15. RIH w/wireline & peft 5 1/2" csg @ 200'. Circ approx. 60 sks Class "C" cmt to surface.
16. Cut off WH & install dry hole marker.
17. Clear location.
18. RDMO BCM.

Mewbourne Oil Company

Well Name: **Bebop BPE State #1H (Current Schematic)**

Updated by: J. Bryand

Spud Date: 5/27/2011

Date Updated: 2/1/2016

Surface

17 1/2" x 13 1/2" 48# H40

Set @ 1076'

Circ. 200 sks to pit

Intermediate

12 1/2" x 9 1/2" 36# & 40# K55

Set @ 4310'

Circ. 250 sks to pit

DV Tool @ 5987'

Production

8 1/2" hole to 9150'

8 1/2" from 9150' to 12760'

Set 5 1/2" 17# & 20# HCP110 & L80 @ 12750'

1st stage 1160 sk, circ 100 sk off DV tool @ 5987'

2nd stage 380 sk

Est TOC @ 3800'

Est TOC 3800'

KOP 8280'

CIBP Set @ 9625'

TVD @ 8796'

TD 8 1/2" hole @ 12760'

Float Collar @ 12675'

Tops:

Rustler	990
Top of Salt	1820
Base of Salt	4060
Delaware	4337
Bone Spring	8357

Perfs:


Stage 7	Stage 6	Stage 5	Stage 4	Stage 3	Stage 2	Stage 1
9204-206	9716-718	10228-230	10740-742	11252-254	11764-655	12276-278
9332-334	9844-846	10356-358	10868-870	11380-382	11892-894	12404-406
9460-462	9972-974	10484-486	10996-998	11508-510	12020-022	12532-534
9588-590	10100-102	10612-614	11124-125	11636-638	12146-150	12660-662

Mewbourne Oil Company

Well Name: **Bebop BPE State #1H (After Schematic)**

Updated by: J. Nave

Date Updated: 2/19/19



Tops:

Rustler	990
Top of Salt	1820
Base of Salt	4060
Delaware	4337
Bone Spring	8357

CONDITIONS FOR PLUGGING AND ABANDONMENT

District II / Artesia N.M.

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, **Notify NMOCD District Office II at (575)-748-1283 at least 24 hours before beginning work.**

1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs.
2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
3. Trucking companies being used to haul oilfield waste fluids to a disposal – commercial or private – shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
6. If the well is not plugged within 1
7. If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
8. **Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.**
9. Produced water will not be used during any part of the plugging operation.
10. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
11. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
12. **Class 'C' cement will be used above 7500 feet.**
13. **Class 'H' cement will be used below 7500 feet.**
14. **A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged**
15. **All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing**

16. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
17. **A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.**
18. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, **(WOC 4 hrs and tag).**
19. **No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.**
20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
 - A) Fusselman
 - B) Devonian
 - C) Morrow
 - D) Wolfcamp
 - E) Bone Springs
 - F) Delaware
 - G) Any salt sections
 - H) Abo
 - I) Glorieta
 - J) Yates.
 - K) **Potash---** (In the R-111-P Area (Potash Mine Area), a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, **WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.**
21. **If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing**

DRY HOLE MARKER REQUIREMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

1. Operator name 2. Lease and Well Number 3.API Number 4. Unit Letter 5. Quarter Section (feet from the North, South, East or West) 6. Section, Township and Range 7. Plugging Date 8. County (SPECIAL CASES)-----AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)